

# Vehicle Damage Insurance Claim

## Driver Information

Name:	Kimberly Hernandez
License No:	S94597643
DOB:	01/07/1970
Address:	08345 Torres Fork Suite 403, Port Amanda, MA 88072
Class:	M
Endorsements:	Four Wheeler

## Vehicle Damage Assessment

Car Make	Chevrolet
Car Model	Rivero
Car Color	White
Damage Details	The front bumper has a noticeable dent and green paint transfer, indicating a collision. The bumper's paint is chipped, and there are scratches on the surrounding area.
Damage Level	Medium
Repair Recommendation	Consider professional repair for the bumper dent and paint chipping. Use touch-up paint for minor scratches and ensure a thorough inspection for any structural damage.
Claim Value (\$)	\$3,169

## Claim Summary

This claim report details the damages assessed for the insured vehicle. Based on the inspection, the vehicle requires: Consider professional repair for the bumper dent and paint chipping. Use touch-up paint for minor scratches and ensure a thorough inspection for any structural damage.. The estimated severity level is categorized as 'Medium', with an estimated claim value of \$3,169. Please review and approve for claim processing.