

# Vehicle Damage Insurance Claim

## Driver Information

Name:	Sandra Trevino
License No:	S93530309
DOB:	02/27/2063
Address:	6282 Gregory Point Apt. 948, Scottborough, NH 06029
Class:	M
Endorsements:	Four Wheeler

## Vehicle Damage Assessment

Car Make	Renault
Car Model	Megane
Car Color	Blue
Damage Details	The rear bumper is severely damaged, with visible dents and scratches. The rear lights and license plate are intact but the bumper is detached from the car.
Damage Level	high
Repair Recommendation	Replace the rear bumper and repair any structural damage to the car's frame.
Claim Value (\$)	\$4,041

## Claim Summary

This claim report details the damages assessed for the insured vehicle. Based on the inspection, the vehicle requires: Replace the rear bumper and repair any structural damage to the car's frame.. The estimated severity level is categorized as 'high', with an estimated claim value of \$4,041. Please review and approve for claim processing.