

Vehicle Damage Insurance Claim

Driver Information

Name:	Derek Arellano
License No:	S38581353
DOB:	06/21/1989
Address:	68346 White Wall Apt. 804, East Angela, TN 05515
Class:	CDL
Endorsements:	Four Wheeler

Vehicle Damage Assessment

Car Make	Saturn
Car Model	Ion
Car Color	Green
Damage Details	The front bumper is detached, the hood is open, and there is a noticeable dent on the front left side of the car.
Damage Level	high
Repair Recommendation	Consider a full front-end inspection and repair, including bumper, hood, and dent repair. Check for any underlying damage to the frame or suspension.
Claim Value (\$)	\$8,478

Claim Summary

This claim report details the damages assessed for the insured vehicle. Based on the inspection, the vehicle requires: Consider a full front-end inspection and repair, including bumper, hood, and dent repair. Check for any underlying damage to the frame or suspension.. The estimated severity level is categorized as 'high', with an estimated claim value of \$8,478. Please review and approve for claim processing.