

Vehicle Damage Insurance Claim

Driver Information

Name:	Jacqueline Phillips
License No:	S15902118
DOB:	05/29/1995
Address:	Unit 0980 Box 0271, DPO AP 30617
Class:	D
Endorsements:	Four Wheeler

Vehicle Damage Assessment

Car Make	Honda
Car Model	Civic
Car Color	Silver
Damage Details	The front bumper is severely damaged, with visible dents and scratches. The front fender is also damaged, with a noticeable dent. The front headlight is shattered, and the hood is slightly bent. The side mirror is detached, and there are scratches on the side of the car.
Damage Level	high
Repair Recommendation	Consider replacing the front bumper, fender, and headlight. The hood and side mirror should be repaired or replaced. Address any scratches and dents on the side of the car.
Claim Value (\$)	\$3,411

Claim Summary

This claim report details the damages assessed for the insured vehicle. Based on the inspection, the vehicle requires: Consider replacing the front bumper, fender, and headlight. The hood and side mirror should be repaired or replaced. Address any scratches and dents on the side of the car.. The estimated severity level is categorized as 'high', with an estimated claim value of \$3,411. Please review and approve for claim processing.