

Vehicle Damage Insurance Claim

Driver Information

Name:	Joyce Jones
License No:	S18039282
DOB:	10/15/2003
Address:	56048 Fischer Bypass, East Kathleenville, NJ 37339
Class:	D
Endorsements:	Four Wheeler

Vehicle Damage Assessment

Car Make	Peugeot
Car Model	308
Car Color	Gray
Damage Details	The rear bumper has visible scratches and dents, particularly on the left side. The rear light area also shows some scratches.
Damage Level	medium
Repair Recommendation	Consider repairing the scratches and dents with touch-up paint or a bumper repair kit. If the dents are significant, professional bodywork may be necessary.
Claim Value (\$)	\$4,010

Claim Summary

This claim report details the damages assessed for the insured vehicle. Based on the inspection, the vehicle requires: Consider repairing the scratches and dents with touch-up paint or a bumper repair kit. If the dents are significant, professional bodywork may be necessary.. The estimated severity level is categorized as 'medium', with an estimated claim value of \$4,010. Please review and approve for claim processing.