

Vehicle Damage Insurance Claim

Driver Information

Name:	Philip Schneider
License No:	S58882270
DOB:	09/28/1986
Address:	1681 Ramirez Heights, South Monica, LA 58147
Class:	M
Endorsements:	Four Wheeler

Vehicle Damage Assessment

Car Make	Opel
Car Model	Astra
Car Color	Blue
Damage Details	The front bumper is severely damaged with visible cracks and dents. The headlights and grille are also affected, with parts of the grille missing. The hood shows signs of impact with dents and possible internal damage.
Damage Level	high
Repair Recommendation	Replace the front bumper, repair or replace the headlights and grille, and inspect the hood for internal damage. Consider a full body shop assessment.
Claim Value (\$)	\$2,139

Claim Summary

This claim report details the damages assessed for the insured vehicle. Based on the inspection, the vehicle requires: Replace the front bumper, repair or replace the headlights and grille, and inspect the hood for internal damage. Consider a full body shop assessment.. The estimated severity level is categorized as 'high', with an estimated claim value of \$2,139. Please review and approve for claim processing.