

Vehicle Damage Insurance Claim

Driver Information

Name:	Jeanne Farrell
License No:	S36572347
DOB:	09/24/2052
Address:	33588 Martin Viaduct, Port Eric, IL 16019
Class:	M
Endorsements:	Four Wheeler

Vehicle Damage Assessment

Car Make	Citroen
Car Model	C3 Aircross
Car Color	White
Damage Details	The car has visible damage to the front bumper, hood, and left side of the body. The bumper is detached, the hood is dented, and there are scratches and dents on the left side.
Damage Level	medium
Repair Recommendation	Replace the detached bumper, repair the dented hood, and address the scratches and dents on the left side. Consider a full inspection for any underlying damage.
Claim Value (\$)	\$5,560

Claim Summary

This claim report details the damages assessed for the insured vehicle. Based on the inspection, the vehicle requires: Replace the detached bumper, repair the dented hood, and address the scratches and dents on the left side. Consider a full inspection for any underlying damage.. The estimated severity level is categorized as 'medium', with an estimated claim value of \$5,560. Please review and approve for claim processing.