



DRILLHOLE RECORD

HOLE No.

BH1

CONTRACT No. GE/99/05

SHEET 1 of 3

PROJECT 11SW-A/CR595 Upper G/F Joyful Building 16-18 Belcher's Street, Kennedy Town, H.K.

METHOD Rotary

CO-ORDINATES

WORKS ORDER No. GE/99/05.255

MACHINE & No. D116

E 831653.05
N 816084.29

DATE from 31/03/2001 to 09/04/2001

FLUSHING MEDIUM Water

ORIENTATION

Vertical

GROUND LEVEL + 57.00 mPD

Drilling Progress	Casing depth/size	Water Depth (m)	Water Recovery %	Total core Recovery %	Solid core Recovery %	R.Q.D.	Fracture Index	Tests	Samples			Reduced Level	Depth (m)	Legend	Grade	Description
									No.	Type	Depth					
31/03/2001	PX	08:00							A	•	0.50	56.50	0.50			Loose, grey (N5), silty fine to coarse SAND with some subangular fine to coarse gravel sized rock fragments. (TOPSOIL)
									B	•	1.00					Very loose, yellowish brown (10YR5/8), silty fine to coarse SAND with some subangular fine to coarse gravel and occasional cobble of rock fragments. (COLLUVIUM)
									C	•	1.50	55.50	1.50			
31/03/2001 06/04/2001		Dry at 18:00 Dry at 08:00		98				2,3 3,4,4,5 N=16	D	•	2.00				V	Extremely weak, light yellowish brown (10YR6/4), completely decomposed meta fine ash TUFF. (Stiff to very stiff, sandy SILT with occasional subangular fine gravel sized rock and quartz fragments)
									1	•	2.00					
									2	•	3.00					
									3	•	3.10					
									4	•	3.55					
				98					5	•	4.00					
									6	•	5.00					
								2,3 3,3,3,4 N=13	7	•	5.10					
									8	•	5.55					
				98					9	•	6.00					
									10	•	7.00					
								4,5 5,7,7,10 N=29	11	•	7.10					
									12	•	7.55					
				98					13	•	8.00	49.00	8.00		V	Extremely weak, dark yellowish brown (10YR3/6), completely decomposed meta fine ash TUFF. (Very silty fine SAND with some subangular fine to coarse gravel and occasional cobble of rock fragments)
									14	•	9.00					
								50/40mm 100/20mm 100cls/20mm	15	•	9.10	47.90	9.10			9.10-10.00m: With much subangular fine to coarse gravel.
	PX	10.00										47.00	10.00			

- Small disturbed sample
- Large disturbed sample
- SPT liner sample
- ▨ U76 undisturbed sample
- U100 undisturbed sample
- ▤ Mazier sample
- ▦ Piston sample

- ▲ Water sample
- ▲ Piezometer / standpipe tip
- ↓ Standard penetration test
- ⊥ Pressuremeter test
- ⊥ Permeability test
- ⊥ Impression packer test
- ∇ In-situ vane shear test

LOGGED SOC *soch*
DATE 10/04/2001
CHECKED BCT *BCT*
DATE 11/04/2001

REMARKS

- Standpipe was installed at 22.00m.
- Piezometer buckets were installed in this drillhole:
 - Standpipe (BH1-5) 16.00-20.00m (9 nos.).



DRILLHOLE RECORD

HOLE No.
BH1

CONTRACT No. GE/99/05

SHEET 2 of 3

PROJECT 11SW-A/CR595 Upper G/F Joyful Building 16-18 Belcher's Street, Kennedy Town, H.K.

METHOD Rotary

CO-ORDINATES

WORKS ORDER No. GE/99/05.255

MACHINE & No. D116

E 831653.05
N 816084.29

DATE from 31/03/2001 to 09/04/2001

FLUSHING MEDIUM Water

ORIENTATION Vertical

GROUND LEVEL + 57.00 mPD

Drilling Progress	Casing depth/size	Water Depth (m)	Water Recovery %	Total core Recovery %	Solid core Recovery %	R.Q.D.	Fracture Index	Tests	Samples	Reduced Level	Depth (m)	Legend	Grade	Description		
	HX								No. Type Depth					As sheet 1 of 3.		
									16 10.00							
									17 11.00							
									18 11.10							
									19 12.10	44.80	12.20					
									20 12.20							
									21 12.65				V	Extremely weak, yellowish brown (10YR5/8), completely decomposed meta fine ash TUFF. (Very stiff, sandy SILT)		
									22 13.10							
									23 14.10							
									24 14.20							
									25 14.65							
									26 15.10	41.80	15.10		V/IV	Very weak, dark yellowish brown (10YR3/6), completely to highly decomposed meta fine ash TUFF. (Recovered as angular, fine to coarse GRAVEL and COBBLE of rock fragments)		
									27 16.10							
									28 16.20							
									28 16.25							
									16.80	40.20	16.80		IV	16.80-17.07m: Highly decomposed zone.		
									17.07	39.83	17.07		III	Moderately strong, yellowish brown (10YR5/8), moderately decomposed meta fine ash TUFF. Joints are widely to very widely spaced, very narrow, rough planar, iron stained and kaolin infilled, dipping 20°-30° and 60°-70°.		
									18.00							
									19.51							
									37.00		20.00					
• Small disturbed sample — Large disturbed sample - SPT liner sample - U76 undisturbed sample - U100 undisturbed sample - Mazier sample - Piston sample ▲ Water sample ○ Piezometer / standpipe tip ↓ Standard penetration test - I Pressuremeter test - I Permeability test - I Impression packer test - V In-situ vane shear test									LOGGED SOC <i>Soc</i>						REMARKS	
									DATE 10/04/2001							
									CHECKED BCT <i>BCT</i>							
									DATE 11/04/2001							

