

Date:

ЛНВ: 010-222-0525

CAPE TOWN: 0795383281 Email: admin@bbplumbing.co.za finance@bbplumbing.co.za

Goneral & Specialising Plumbing * Leak Detection * Drain jetting & Cleaning * Drain Inspections

We have inspected the geyser installation of the water heating system and pipework and noted the below non compliances.

		All items ticked below are non compliant.
1	-	Cold vacuum breaker breaker (Must be 300mm above geyser)
2	-	Hot vacuum breaker (Must be 300mm above geyser and 400mm away)
3		Vacuum breaker not over drip tray
4		Safety valve
5		Not copper
6	-	Need brackets
7	+	Has a 90 degree short radius bend
8		Exceeds 4m, Must be upsized to 28mm
9	-	Must have 1m copper from hot water outlet
10		Must have 1m copper from cold water inlet
11		Pipes in roof not secured properly
12		PRV overflow pipe not adequately secured.
13		PRV not over drip tray
14	-	System unbalanced
15	-	No shut off to the geyser
16	-	No electrical isolator switch
17		Pipes not electrically bonded or not correctly bonded
18	-	Non return valve installed on unbalanced system (warranty can be voided if not installed)
19		Tray overflow item not compliant
20	-	Not PVC
21	-	No brackets every 1m
22	-	Has a 90 degree short radius bend
23	-	No fall on the outlet pipe
24	-	Geyser support
25	9	Lagging
26	-	No lagging
27		Lagging is split
28	-	Incorrect type of lagging
29	-	Geyser access
30	-	Roof sheets/tiles need to be removed to replace the geyser
31	-	Trap door is in bathroom
32		Trap door to be enlarged or roof access
33	_	Type of pipe in the ceiling or exposed.
	P	Iumbers indemnity Electric geyser / Solar geyser / Heat pump / Pipe Repairs / Assesment The plumbing work on this contract was completed under the direct instruction of the owner who hereby accepts legal responsibility for non compliance (if any as stated above) in the therms of the regulations. Sans10254/1306/1352
		Seyser make: Serial: Code:
	P	lease advise if a quotation can be supplied to meet these critical compliance requirements: YES / NO
	Abbus	nsurance name:
	C	laim number:
		lient Name and Surname:
	8 1	nstallers Name: