

26. Ramalingeshwara temple

Place - Chandkavathe

District : Vijayapura
Taluk : Sindagi
Locality : Chandkavathe

Geo - Coordinates:
Lat : 16.962131°N
Long : 76.144154°E




History

The temple consists of a garbhagraha antarala and sabhamandapa. This temple is in most dilapidated condition. In the garbhagraha is a Sivalinga. The sabhamandapa has fallen. The exterior walls of the temple are decorated with richly carved sculptures. The Kadambanagara or phamsana Sikhara has fallen.



3D Point Cloud



Plan