

SERVICE INFORMATION

Customer: Wabash @ Wabash Cadiz KY

Contact: Eric Joiner

Location: 489 International Dr - Cadiz, KY, 42211

Phone: 270-206-8185

Job #: 0267286

Email: eric.joiner@onewabash.com

SERVICE REQUESTED

D532229-Bay# 6 Middle R&M Hoist Serial# HHW11917 Replace Wire Rope Assembly D532230- Bay# 6 Middle R&M Hoist Serial# HGW07090 Replace Wire Rope Assembly

DATE: 12/19/2025

LEAD: Emmanuel Maddox

JOB SAFETY ANALYSIS (JSA)

HAZARD RECOGNITION

PPE & SAFEGUARDS

☒ FALLING DEBRIS	☒ FALL HAZARD	☒ SAFETY GLASSES	☒ HARD HATS
☐ FIRE / EXPLOSION	☐ ARCING	☒ STEEL TOED SHOES	☒ FALL PROTECTION
☐ ELECTROCUTION	☐ OVERHEAD HAZARDS	☐ HEARING PROTECTION	☐ FACE SHIELD
☐ HEAT / COLD	☐ AIRBORNE PARTICLES	☒ GLOVES	☐ RESPIRATORS
☐ CHEMICALS	☐ UTILITIES	☐ LONG SLEEVES	☐ FIRE RETARDANT
☒ MOBILE EQUIPMENT	☐ MOVING HAZARDS	☐ BARRICADES	☐ TAPE / WARNING SIGNS
☐ ENVIRONMENTAL	☐ PINCHING / CRUSHING	☐ FIRE EXTINGUISHER	☐ LOCKOUT/TAGOUT
☐ PRESSURIZED SYSTEMS	☐ RIGGED LOADS	☐ TAG LINES	☐ HOUSE KEEPING
☐ SLIPPING / TRIPPING	☐ FLYING DEBRIS	☐ VENT OR FAN	☐ HOLE COVERS
☐ FLOOR OPENINGS	☐ SUBFLOORS	☐ MSDS/CHEM PROTECTION	☐ FIRE BLANKETS

DESCRIBE ANY OTHER HAZARDS PRESENT FOR THIS WORK: --

DESCRIBE SAFEGUARDS TO ADDRESS THESE ADDITIONAL HAZARDS: --

HAVE ALL EQUIPMENT, PRE-SHIFT INSPECTIONS AND SAFETY CHECKS BEEN COMPLETED?: YES

HAVE ALL TECHNICIANS REVIEWED THE JSA AND VERIFIED THE PROPER PPE AND SAFEGUARDS?: YES

GENERAL SERVICE WORK

Service Performed

Got parts needed to Jeff

By Emmanuel Maddox

Materials

No information to show

Attachments

No attachments

CRANES SERVICED



D532230

Location: **Bay 6 Middle**

Crane MFG: **Bohnert equip. company**

Capacity: **5 Ton**

Crane Serial: **LE6062204 Lucette Cranes**

Crane Hoists

Hoist 1 MFG: **R&M**

Capacity: **5 Ton**

Model: **SX40400050P35BL0F**

Service Performed

New wire rope assembly on 62B

10:32 AM

By Emmanuel Maddox

No material required to supply

No material to be ordered

Attachments



D532229

Location: **Bay 6 Middle**

Crane MFG: **Bohnert equip. company**

Capacity: **5 Ton**

Crane Serial: **LE7080901F Lucette Cranes**

Crane Hoists

Hoist 1 MFG: **R&M**

Capacity: **5.0 Ton**

Model: **SX40410050P35BL0F**

Service Performed

Cut old rope clips out and removed Allen bolts. Completed rope change and installed new rope clips and bolts

08:47 AM

By Emmanuel Maddox

Rope clip Allen heads are stripped. Moore will have to be ordered prior to being able to change rope. The existing ones will need to be extracted.

08:08 AM

By Emmanuel Maddox

No material required to supply

No material to be ordered

Attachments



TECHNICIAN(S)	START TIME	END TIME	TOTAL
Emmanuel Maddox	4:00 AM	11:00 AM	7
TOTALS			7

DATE: 12/22/2025

LEAD: Emmanuel Maddox

JOB SAFETY ANALYSIS (JSA)

HAZARD RECOGNITION

PPE & SAFEGUARDS

FALLING DEBRIS	✓ FALL HAZARD	✓ SAFETY GLASSES	✓ HARD HATS
FIRE / EXPLOSION	ARCING	✓ STEEL TOED SHOES	✓ FALL PROTECTION
ELECTROCUTION	OVERHEAD HAZARDS	HEARING PROTECTION	FACE SHIELD
HEAT / COLD	AIRBORNE PARTICLES	✓ GLOVES	RESPIRATORS
CHEMICALS	UTILITIES	LONG SLEEVES	FIRE RETARDANT
MOBILE EQUIPMENT	MOVING HAZARDS	BARRICADES	TAPE / WARNING SIGNS
ENVIRONMENTAL	PINCHING / CRUSHING	FIRE EXTINGUISHER	LOCKOUT/TAGOUT
PRESSURIZED SYSTEMS	RIGGED LOADS	TAG LINES	HOUSE KEEPING
SLIPPING / TRIPPING	FLYING DEBRIS	VENT OR FAN	HOLE COVERS
FLOOR OPENINGS	SUBFLOORS	MSDS/CHEM PROTECTION	FIRE BLANKETS

DESCRIBE ANY OTHER HAZARDS PRESENT FOR THIS WORK: --

DESCRIBE SAFEGUARDS TO ADDRESS THESE ADDITIONAL HAZARDS: --

HAVE ALL EQUIPMENT, PRE-SHIFT INSPECTIONS AND SAFETY CHECKS BEEN COMPLETED?: YES

HAVE ALL TECHNICIANS REVIEWED THE JSA AND VERIFIED THE PROPER PPE AND SAFEGUARDS?: YES

GENERAL SERVICE WORK

Service Performed

No information to show

Materials

No information to show

Attachments

No attachments

CRANES SERVICED



D532229

Location: Bay 6 Middle

Crane MFG: Bohnert equip. company

Capacity: 5 Ton

Crane Serial: LE7080901F Lucette Cranes

Crane Hoists

Hoist 1 MFG: R&M

Capacity: 5.0 Ton

Model: SX40410050P35BL0F

Service Performed

Cut old rope clips out, removed bolts. Completed rope change and installed new rope clips and bolts.
Verified limits.

08:48 AM

By Emmanuel Maddox

No material required to supply

No material to be ordered

Attachments



TECHNICIAN(S)	START TIME	END TIME	TOTAL
- No work time recorded -			

DATE: 12/29/2025

LEAD: Emmanuel Maddox

JOB SAFETY ANALYSIS (JSA)

HAZARD RECOGNITION

PPE & SAFEGUARDS

FALLING DEBRIS	✓ FALL HAZARD	✓ SAFETY GLASSES	✓ HARD HATS
FIRE / EXPLOSION	ARCING	✓ STEEL TOED SHOES	✓ FALL PROTECTION
ELECTROCUTION	OVERHEAD HAZARDS	HEARING PROTECTION	FACE SHIELD
HEAT / COLD	AIRBORNE PARTICLES	✓ GLOVES	RESPIRATORS
CHEMICALS	UTILITIES	LONG SLEEVES	FIRE RETARDANT
MOBILE EQUIPMENT	MOVING HAZARDS	BARRICADES	TAPE / WARNING SIGNS
ENVIRONMENTAL	PINCHING / CRUSHING	FIRE EXTINGUISHER	LOCKOUT/TAGOUT
PRESSURIZED SYSTEMS	RIGGED LOADS	TAG LINES	HOUSE KEEPING
SLIPPING / TRIPPING	FLYING DEBRIS	VENT OR FAN	HOLE COVERS
FLOOR OPENINGS	SUBFLOORS	MSDS/CHEM PROTECTION	FIRE BLANKETS

DESCRIBE ANY OTHER HAZARDS PRESENT FOR THIS WORK: --

DESCRIBE SAFEGUARDS TO ADDRESS THESE ADDITIONAL HAZARDS: --

HAVE ALL EQUIPMENT, PRE-SHIFT INSPECTIONS AND SAFETY CHECKS BEEN COMPLETED?: NO

HAVE ALL TECHNICIANS REVIEWED THE JSA AND VERIFIED THE PROPER PPE AND SAFEGUARDS?: NO

GENERAL SERVICE WORK

Service Performed

No information to show

Materials

No information to show

Attachments

No attachments

TECHNICIAN(S)	START TIME	END TIME	TOTAL
Emmanuel Maddox	4:00 AM	10:45 AM	6.75
		TOTALS	6.75

WORK ORDER CLOSE OUT

Was all requested work completed?	Yes
Operational and limit checks performed?	Yes
Additional work, repairs requested?	No
Was Equipment used on this job?	No



Albert Newberry

12/29/2025

CUSTOMER SIGNATURE:

CUSTOMER PRINTED NAME:

SIGNATURE DATE: