



**TECHNICKÝ SKÚŠOBNÝ
ÚSTAV PIEŠŤANY, š.p.**

Krajinská cesta 2929/9, 921 01 Piešťany, Slovenská republika



SNAS

Reg. No. 009/S-047

Skúšobňa TSÚ - Skúšobňa strojov a výrobných zariadení

Tel.: +421-33-79 57 222

Fax: +421-33-77 23 716

e-mail: svz@tsu.sk

www.tsu.sk

POS č.: 220500317/M

Pages: 1 / 12

No of Annexes: -

Test report

No.: 220500317/M

Test name: SAFETY OF MACHINERY

Test subject – name: Hydraulický systém – integrovaný

Type – marking: HYDROFOGG

Manufacturer: DETECTAIR, s.r.o.
Trojičné nám. 5-9
821 06 Bratislava, Slovak Republic

Customer – Applicant: COCV TSÚ Piešťany
Krajinská cesta 2929/9
921 01 Piešťany
Slovak Republic

Order – application number: 220500317

Place of test: TSÚ Piešťany
Krajinská cesta 2929/9
921 01 Piešťany, Slovak Republic

Test – procedure method: See article 2 on page 2

Date of test performance: 15.12.2022 – 27.01.2023

Distribution: 1 x – customer
1 x – TSU (SSZV)

Date of issue: 30. 01. 2023

Tested and
elaborated by:

Patrik Vavrínek
Testing technician

Checked and
approved by:

**TECHNICKÝ SKÚŠOBNÝ
ÚSTAV PIEŠŤANY, š.p.**
Skúšobňa TSÚ
Krajinská cesta 2929/9
921 01 PIEŠŤANY

Ing. Mário Zemko
Head of machinery and production
devices Testing Body

Test results introduced in this test report are related to the test subject only and do not substitute other documents required by state supervisory authorities and according to other specific regulations. Test report can be reproduced or published as a whole, in parts only with written approval of TSÚ test body.

COPYRIGHT © TSÚ Piešťany, š.p.