



Note that C2, C3, C5, C6, C17, and C20 were left off the PCB due to being redundant bypass capacitors (very close to other filter capacitors from the previous stage) for the particular layout.

