



Stopped Bus Safe Passage



Daniel Correia 90480 Joaquim Ramos 88812




Objectives

- Detection of persons and vehicles through a camera mounted on a dashboard of a bus
- Warn surrounding cars about vehicles coming the other way and persons on the road in front of the bus




System Architecture






Demonstration timeline (example)





Demonstration



```
carobu_1 | CPM JSON: {"fields":{"cpm":{"cpmParameters":{"managementContainer":{"referencePosition":{"altitude":{"altitudeConfidence":14,"altitudeValue":15.97},"latitude":40.6041932,"longitude":-8.6632732,"positionConfidenceEllipse":{"semiMajorConfidence":4095,"semiMajorOrientation":0.0,"semiMinorConfidence":4095}},"stationType":6},"numberOfPerceivedObjects":4,"perceivedObjectContainer":[{"classification":[{"class":{"vehicle":{"confidence":98,"type":3}},"confidence":98}],{"objectConfidence":98,"objectID":0,"objectRefPoint":0,"timeOfMeasurement":0,"xAcceleration":{"longitudinalAccelerationConfidence":0.0,"longitudinalAccelerationValue":0.0},"xDistance":{"confidence":1.0,"value":1216.28},"xSpeed":{"confidence":1.0,"value":11.27},"yAcceleration":{"lateralAccelerationConfidence":0.0,"lateralAccelerationValue":0.0},"yDistance":{"confidence":1.0,"value":1216.28},"ySpeed":{"confidence":1.0,"value":7.95}},"classification":[{"class":{"person":{"confidence":97,"type":1}},"confidence":97}],{"objectConfidence":97,"objectID":1,"objectRefPoint":0,"timeOfMeasurement":0,"xAcceleration":{"longitudinalAccelerationConfidence":0.0,"longitudinalAccelerationValue":0.0},"xDistance":{"confidence":1.0,"value":1216.28},"xSpeed":{"confidence":1.0,"value":11.27},"yAcceleration":{"lateralAccelerationConfidence":0.0,"lateralAccelerationValue":0.0},"yDistance":{"confidence":1.0,"value":1216.28},"ySpeed":{"confidence":1.0,"value":7.95}},"classification":[{"class":{"person":{"confidence":97,"type":1}},"confidence":97}],{"objectConfidence":97,"objectID":2,"objectRefPoint":0,"timeOfMeasurement":0,"xAcceleration":{"longitudinalAccelerationConfidence":0.0,"longitudinalAccelerationValue":0.0},"xDistance":{"confidence":1.0,"value":1216.28},"xSpeed":{"confidence":1.0,"value":11.27},"yAcceleration":{"lateralAccelerationConfidence":0.0,"lateralAccelerationValue":0.0},"yDistance":{"confidence":1.0,"value":1216.28},"ySpeed":{"confidence":1.0,"value":7.95}},"classification":[{"class":{"vehicle":{"confidence":95,"type":3}},"confidence":95}],{"objectConfidence":95,"objectID":3,"objectRefPoint":0,"timeOfMeasurement":0,"xAcceleration":{"longitudinalAccelerationConfidence":0.0,"longitudinalAccelerationValue":0.0},"xDistance":{"confidence":1.0,"value":1216.28},"xSpeed":{"confidence":1.0,"value":11.27},"yAcceleration":{"lateralAccelerationConfidence":0.0,"lateralAccelerationValue":0.0},"yDistance":{"confidence":1.0,"value":1216.28},"ySpeed":{"confidence":1.0,"value":7.95}},"sensorInformationContainer":[{"detectionArea":{"stationarySensorRectangle":{"semiMajorRangeLength":750.0,"semiMajorRangeOrientation":3601.0,"semiMinorRangeLength":20.0}},{"sensorID":1,"type":1},{"detectionArea":{"stationarySensorRadial":{"range":100,"stationaryHorizontalOpeningAngleEnd":3601.0,"stationaryHorizontalOpeningAngleStart":3601.0}},{"sensorID":2,"type":12},{"detectionArea":{"stationarySensorRadial":{"range":100,"stationaryHorizontalOpeningAngleEnd":3601.0,"stationaryHorizontalOpeningAngleStart":3601.0}},{"sensorID":3,"type":10},{"detectionArea":{"stationarySensorRadial":{"range":100,"stationaryHorizontalOpeningAngleEnd":3601.0,"stationaryHorizontalOpeningAngleStart":3601.0}},{"sensorID":4,"type":11}],{"stationDataContainer":{"originatingVehicleContainer":{"driveDirection":0,"heading":{"headingConfidence":127.0,"headingValue":144.0},"speed":{"speedConfidence":127.0,"speedValue":0.0}},{"generationDeltaTime":44258,"header":{"messageID":14,"protocolVersion":1,"stationID":1}},{"newInfo":true,"receiverID":2,"receiverType":5,"rssi":-255,"stationID":1,"test":{"json_timestamp":1655935613.526352,"timestamp":1655935613.525269}}
carobu_1 | DENM JSON: {"fields":{"denm":{"management":{"actionID":{"originatingStationID":1,"sequenceNumber":0},"detectionTime":1626453837,"eventPosition":{"altitude":{"altitudeConfidence":1,"altitudeValue":15.97},"latitude":40.6041932,"longitude":-8.6632732,"positionConfidenceEllipse":{"semiMajorConfidence":0,"semiMajorOrientation":0.0,"semiMinorConfidence":0}},"referenceTime":1626453837,"stationType":6,"validityDuration":1,"situation":{"eventType":{"causeCode":12,"subCauseCode":12},"informationQuality":7}},{"header":{"messageID":1,"protocolVersion":2,"stationID":1}},{"newInfo":true,"receiverID":2,"receiverType":5,"rssi":-255,"stationID":1,"test":{"json_timestamp":1655935613.527315,"timestamp":1655935613.527111}}
carobu_1 | DENM JSON: {"fields":{"denm":{"management":{"actionID":{"originatingStationID":1,"sequenceNumber":0},"detectionTime":1626453837,"eventPosition":{"altitude":{"altitudeConfidence":1,"altitudeValue":15.97},"latitude":40.6041932,"longitude":-8.6632732,"positionConfidenceEllipse":{"semiMajorConfidence":0,"semiMajorOrientation":0.0,"semiMinorConfidence":0}},"referenceTime":1626453837,"stationType":6,"validityDuration":1,"situation":{"eventType":{"causeCode":40,"subCauseCode":40},"informationQuality":7}},{"header":{"messageID":1,"protocolVersion":2,"stationID":1}},{"newInfo":true,"receiverID":2,"receiverType":5,"rssi":-255,"stationID":1,"test":{"json_timestamp":1655935613.527641,"timestamp":1655935613.527482}}
```



Questions?