

Harbor Mutual Insurance

CLAIM INSPECTION REPORT

Claim and Adjuster Information

Claim Number	CLM-893919
Policy Number	HO-2026-40891
Named Insured	Denise R. Varga
Loss Location	904 Coral Drive, Marigold Beach, FL 34231
Date of Loss	04/10/2026
Date of Inspection	03/15/2026
Peril	Wind/hail
Assigned Adjuster	Monica J. Sato · License OH-CLM-31104
Adjuster Phone	(330) 555-0378

Summary

Inspection confirmed hail damage consistent with a storm event reported in the area on the date of loss. Impact marks are present on the roof surface (22 squares), gutters, north and west siding elevations, and two window panes. Hail size is estimated at 1.5-2.0 inches based on impressed diameter measurements on the aluminum components. Loss is covered under the policy subject to the windstorm deductible.

Site Inspection Findings

A physical inspection of the loss site was conducted on the date noted above. Photographs and measurements were taken and are retained in the claim file. All findings are consistent with the reported cause of loss.

Cause of Loss Determination

Cause of loss determined to be: **Wind/hail**. The loss is covered under the terms of the policy subject to applicable deductibles and any sublimits noted in the declarations or attached endorsements.

Damage Assessment and Estimate

Line Item	Estimated Cost
Asphalt shingle roof replacement (22 squares)	\$9,900.00
Gutter and downspout replacement (160 linear ft)	\$2,240.00
Aluminum siding repair — north and west elevations	\$1,760.00
Window pane replacement (2 units)	\$640.00
General contractor overhead and profit (15%)	\$2,162.00
	Amount
TOTAL ESTIMATED REPLACEMENT COST VALUE	\$16,702.00
Less: Policy Deductible	(to be applied at payment)
Applicable Depreciation (if ACV basis)	(to be calculated)
RECOMMENDED INITIAL RESERVE	\$17,537.10

Recommended Reserve

Based on the field inspection and line-item estimate, an initial reserve of \$17,537.10 is recommended (replacement cost value plus 5% contingency). The reserve may be revised pending contractor bids, supplemental documentation, or

identification of additional covered damages.

Report prepared by: Monica J. Sato, Licensed Property Adjuster (OH-CLM-31104). This report is for internal claims use only and does not constitute an admission of liability or a final coverage determination.