

HYDRANT DISPENSER / REFUELLER CHECK LIST

Location : DPPU MINANGKABAU



Equipment ID	Date	Group	Shift
NO	CHECKS	S/C	REMARKS
I	Cleanliness	S	
II	Truck conditions		
1	Fuel	S	
2	Radiator Condition / Water	S	
3	Lubricant	S	
4	Battery Condition	S	
5	Brake	S	
6	General Condition of Engine	S	
7	Horn	S	
8	Wiper	S	
9	Head & Tail Lamps Condition	S	
10	Sign Lamps	S	
11	Beacon Light	S	
12	Fueling Lamps	S	
13	PTO / Hydraulic Pump	S	
14	Compressor	S	
15	Mirrors	S	
16	Tires	S	
17	General Condition of Transmission	S	
18	Hydraulic Ladder / Platform	S	
19	Rearward Gear Warning	S	
III	Tank Condition		
1	Step Condition	S	
2	Jet Level Sensor Condition	S	
3	Pressure Vacuum Valve / Free Vent	S	
4	Water Drain Line Tank (roof area water drain)	S	
IV	Safety Equipments		
1	Flame trap condition	S	
2	Grounding and/or Bonding Cable Condition	S	
3	Interlock System	S	
4	Seal Override Interlock System	S	
5	Seal Override Deadman	S	
6	Fire Extinguishers (seal, number & date of last check) (pressure indicator)	S/C	1 02-07-22.1
7	"Product"-No Smoking-Safety Signs & Decals	S	
8	Safety Cone ; 4-Direction Flag ; Landyard	S	
V	Refueling Equipments		
	Before Refueling		
1	Underwing Hoses Condition	N/A	
	: Rear Hose & Reel conditions	S	
	: Front Hose & Reel conditions	N/A	
2	Platform Hoses Condition : Left	S	
	: Right	S	
3	Condition of Flowmeter : Sealing	S	
	: Calibration exp. Date	S	02-07-2023
4	Deadman Control Condition	S	
5	Input Coupler Condition	S	
6	Date of Last Filter Change	S	02-07-22.1
7	PCV & Regulator	S	
8	Nitrogen Pressure Indicator	N/A	PSI (40 - 70 PSI)
	During Refueling		
1	Inlet Pressure Indicator	S	40 Kg/Cm ² or PSI
2	PCV Monitor Indicator	S	40 Kg/Cm ² or PSI
3	PCV Air Reference Indicator	S	0.4 Kg/Cm ² or PSI
4	PDG Indicator	S	2 PSI, Flowrate 120 LPM
VI	Others		
1	Operating Hours Record	S	
2	Rubber Block	S	
3	Oil Absorbent / Spill Kit	S	
4	Sight Glass / Visijar Condition	S	
5	Ladder Wellness	S	
6	Fuel Leaks	S	
7	Dust Cap Input Coupler and/or Underwing Coupling	S	
8	Bucket with Bonding Wire	S	
9	Filter Sumps and/or Tank Sumps Drain	S	
Performed by	Result : 2 3 1 (Name & Sign)		
General Condition Summary by Supervisor	01 / 02 / 03 (Select One)		
Refueling Supervisor	Boy - P. (Name & Sign)		

NOTES : S : Satisfactory 01 : Can be Operated
C : Comment 02 : Can be Operated with Repairs
N/A : Not Available 03 : Can not be Operated

- This record shall be maintained and retained at least 1 year

SF-119/2020-AVS