



Traffic Accident Report

General Vehicle Information


Make:	Subaru	Body Type:	Sedan	Fuel:	Petrol
Model:	G4	Cylinders:	4	Transaxle:	2WD
Reg. year:	2012	Seating Cap.:	5	Steering Pos.:	Right hand
Model #:	GP-203913	Odometer:	6500km	Transmission:	Automatic
Engine Number:	567FGH56	Rating CC:	1987cc	Colour:	GREY
Reg. No.:	TBA	Import Type:	Japanese	Body Grade:	1.6l

Brief Report of the Accident

On Thursday, August 23, 2021 a Subaru (Car1) motor car was traveling along East avenue in a southerly direction heading towards a main road (West Road) whilst Car 2 was heading easterly on Trafalgar road.

As both cars approach the intersection East Avenue and West Road, both drivers refused to stop before reaching the centre of the intersection and they then collided in each other causing damages.

Road Diagram



Record of Damages

Bonnet:	No Damage	Left Headlight:	No Damage
Right Fender:	No Damage	Radiator:	No Damage
Left Fender:	Minor damages (repairable)	Engine Bay:	No Damage
Front Bumper:	No Damage	Fog lights:	No Damage
Crash Bar:	No Damage	Air bags:	Left front and Rear Door-Deployed Left Curtain -Deployed
Grill:	No Damage	Left Rear door:	Major Damages (Needs replacement)
Right Headlight:	No Damage	Left Front Door:	Major Damages (Needs replacement)

Pictures of Damages

