



## Traffic Accident Report

### General Vehicle Information


|                       |           |                      |          |                       |            |
|-----------------------|-----------|----------------------|----------|-----------------------|------------|
| <b>Make:</b>          | Mazda     | <b>Body Type:</b>    | SUV      | <b>Fuel:</b>          | Petrol     |
| <b>Model:</b>         | Axela     | <b>Cylinders:</b>    | 4        | <b>Transaxle:</b>     | 2WD        |
| <b>Reg. year:</b>     | 2016      | <b>Seating Cap.:</b> | 5        | <b>Steering Pos.:</b> | Right hand |
| <b>Model #:</b>       | AX45      | <b>Odometer:</b>     | 28390 km | <b>Transmission:</b>  | Automatic  |
| <b>Engine Number:</b> | AX45-5689 | <b>Rating CC:</b>    | 2000cc   | <b>Colour:</b>        | RED        |
| <b>Reg. No.:</b>      | TBA       | <b>Import Type:</b>  | Japanese | <b>Body Grade:</b>    | 2.0l       |

### Brief Report of the Accident

On Wednesday, January 2, 2022 the Mazda (car1) motor car was traveling along Holborn avenue in a southerly direction heading towards a main road (Trafalgar Road) whilst a Car 2 was heading easterly on Trafalgar road.

At the intersection Trafalgar Road and Holborn Road, both cars moved towards the centre of the intersection where they collided in each other causing damages.

### Road Diagram



## Record of Damages

|                         |                                   |                          |                            |
|-------------------------|-----------------------------------|--------------------------|----------------------------|
| <b>Bonnet:</b>          | Major damages (repairable)        | <b>Left Headlight:</b>   | Completely destroyed       |
| <b>Right Fender:</b>    | No damage                         | <b>Radiator:</b>         | Minor Damages (repairable) |
| <b>Left Fender:</b>     | Major damages (repairable)        | <b>Engine Bay:</b>       | Bent at the Front          |
| <b>Front Bumper:</b>    | Completely destroyed              | <b>Fog lights:</b>       | Completed Destroyed        |
| <b>Crash Bar:</b>       | Major Damages (needs replacement) | <b>Air bags:</b>         | None Deployed              |
| <b>Grill:</b>           | Completed destroyed               | <b>Right Front door:</b> | No Damage                  |
| <b>Right Headlight:</b> | Minor damages                     | <b>Left Front Door:</b>  | Slight Damages             |

## Pictures of Damages

