



Traffic Accident Report

General Vehicle Information


Make:	Toyota	Body Type:	Sedan	Fuel:	Petrol
Model:	Corolla	Cylinders:	4	Transaxle:	2WD
Reg. year:	2016	Seating Cap.:	5	Steering Pos.:	Left hand
Model #:	Cor16	Odometer:	113406km	Transmission:	Automatic
Engine Number:	Cor16-2342GH	Rating CC:	1987cc	Colour:	RED
Reg. No.:	TBA	Import Type:	United States of America	Body Grade:	1.6l

Brief Report of the Accident

On Thursday, April 2, 2021 the Toyota (Car1) motor car was traveling along Old Hope Road in an easterly direction heading towards Liguanea behind Car 2 which was heading in the same direction.

Whilst both cars were being driven, the driver of Car 1 sped up and suddenly lost control of the vehicle which caused it to collide in the rear of Car 2 causing damages.

Road Diagram



Record of Damages

Bonnet:	Minor damages (repairable)	Left Headlight:	Major Damages (Needs replacement)
Right Fender:	Major Damages (Needs replacement)	Radiator:	Minor Damages
Left Fender:	Minor damages (repairable)	Engine Bay:	Minor damages (repairable)
Front Bumper:	Major Damages (Needs replacement)	Fog lights:	Major Damages (Needs replacement)
Crash Bar:	Major Damages (Needs replacement)	Air bags:	Left and Right Curtain, Driver -Deployed
Grill:	Major Damages (Needs replacement)	Left and Right Rear door:	No Damage
Right Headlight:	Major Damages (Needs replacement)	Left and Right Front Door:	No Damage

Pictures of Damages

