

Premises_ID	CTH77
locality	capetown
extra_comments	--
leftover_comments	2 bins at residence, 340l total
identification_comments	34 bilston rd
Date	2019-09-04
collected_percent	10
auditor	Rd
street_address	--
begin_group_xYDXJVv2Z/extra_images	Missing Data
premises_photo	Missing Data
sample_photo	Missing Data
gps	[-33.9777, 18.509529]