

| | |
|------------------------------------|---|
| Premises_ID | CTH130 |
| locality | capetown |
| extra_comments | Formal RDP government house, with 3 backyard shacks. He had a wheelie bin |
| leftover_comments | 180l from bin |
| identification_comments | 18691 Mboya street, house on crn |
| Date | 2019-09-05 |
| collected_percent | 20 |
| auditor | Rd |
| street_address | -- |
| begin_group_xYDXJVv2Z/extra_images | Missing Data |
| premises_photo | Missing Data |
| sample_photo | |
| gps | [-34.002678, 18.581713] |