

Premises_ID	CTH10
locality	--
extra_comments	CTH10
leftover_comments	90 L left
identification_comments	44 sedgemoor rd
Date	2019-09-03
collected_percent	20
auditor	Rd
street_address	--
begin_group_xYDXJVv2Z/extra_images	Missing Data
premises_photo	Missing Data
sample_photo	Missing Data
gps	[-33.949447, 18.38327]