

Site report

FotoObra · Lisboa

Client —	Period 01.10.2026 – 04.10.2026	Responsible Your name
-------------	--	---------------------------------

SUMMARY

Example report with photos from different jobs in Lisbon.




01.10.2026 09:00

Apartment: demolition done, opening made, temporary beam in place



02.10.2026 11:00

Showroom: kitchen fronts fitted, worktop tomorrow



03.10.2026 13:00

Showroom: kitchen finished, LED strips under the cabinets connected



04.10.2026 15:00

Apartment: kitchen units and appliances installed