

Independent Survey Summary

Dubai Charter Yacht - marine surveyor's condition summary (sample)

Dubai Charter Yacht (BI-YT-01)

Version v1.0 | 28 Aug 2026

Ref BI-YT-01/SV/1.0

SAMPLE - DEMO DOCUMENT

Illustrative only. Not an offer, not advice, not a legal instrument. Capital at risk.

This summary illustrates the form of an independent marine survey. A licensed marine surveyor inspected hull, machinery, safety equipment and documentation. This sample contains illustrative findings only.

Illustrative findings

Area	Sample finding
Hull & structure	Satisfactory for age; antifouling due within 6 months
Main engines	Service history complete; 120h since overhaul
Safety equipment	Meets commercial charter coding (sample)
Documentation	Registration and insurance in order (sample)

On the basis of the sample inspection described above, the vessel is presented as suitable, subject to the noted maintenance items, for the intended commercial charter use. Valuations and opinions in a live transaction would be issued by the appointed surveyor directly.

PLEASE READ - Sample content. A real survey would be commissioned independently and addressed to the issuer's counsel.