# MARUTI SERVICE CENTER

**Workshop Code :**000049

**NH-14, Tilai, Beside Atithi Family Restaurant, Rampurhat-1, Birbhum,
West Bengal - 731224**

**GSTIN: NA**

## Repair Report

| Complaints<br>Schedule Service 2 -Schedule Service 2 : | Jobcard No: NJ0000492526-91 | Breakdown Id:<br>20250617003206 |
|---|---|---|
| | Repair Report No: NI0000492526-92 | Repair Report Date:25-06-2025 17:44:40 |
| | In Date: 25-06-2025 17:09:43 | |

| **Vehicle Number** | : WB23E0717 | **EME Name** | :Saikat Dutta | **Project:** | : 102 |
|---|---|---|---|---|---|
| **In Odo Reading** | : 333770 | **EME Contact No** | :7872484583 | **Final Approver:** | :<br>Atanu<br>Bairagi |
| **Out Odo Reading** | : 0 | **Address** | : SURI<br>DH/SURI<br>SADAR<br>HOSPITAL | | |
| **Phone Number** | : 9153230050 | | | | |
| **Email** | : sanjoykrk91@gmail.com | | | | |
| **Off Road Time** | : 25-06-2025 13:34:35 | **District:** | : BIRBHUM | | |

**Services**

| # | Service Number | Service Description | Remarks | Qty | Service Total | Labour Total | Total Cost |
|---|---|---|---|---|---|---|---|
| 1 | 30433 | SPECIAL SERVICES | Mandatory Service | 1 | 250.00 | 0 | 250.00 |
| | | | | | **Grand Total :** | | **250.00** |

**Grand Total**

| | **Parts Total :** | **0.00** |
|---|---|---|
| | **Service Total:** | **250.00** |
| | **Grand Total :** | **250.00** |

Amount ( in Words ): INR Two Hundred Fifty rupees Only

**Pending Jobs :**

**Observation :** Ok, for operations

I certify that the work has been done to my satisfaction and that I have taken delivery of the vehicle in good condition, with all items / valuables and parts intact.

This is a system-generated document. Does not require any signature

Authorized Signature

MARUTI SERVICE CENTER

Print Date :25-06-2025 17:44:21