VEHICLE INSPECTION REPORT



Mercedes-Benz GLA Class Hatchback GLA 180 Urban Edition 5dr Auto

YE18TPZ

Present

Present

Missing

Present

Damaged

Inspection Information

Inspection Date: 20/03/2020 Vehicle Condition: Clean Location: London, UNIT 4, 152 New Rd,
Rainham

Inspection ID: #I029324014 Inspection Condition: Dry

Vehicle Infomation

Car Body type: Hatchback Gear box: Automatic Type: **MERCEDES** 2014 Manufacturer: Model year: Doors: Model range: **GLA-CLASS Chassis number:** EF561E98970469GZ Seat: 5 Model: **GLA Diesel Hatchback** Fuel type: Diesel Color: Silver Derivative: GLA 180 Urban Edition 5dr Auto Drive train: Four Wheel Drive Remaining Warranty: 1.5 Years / 15,000 Miles

Documents/Keys Information

Service Infomation

Service History: Full V5: Present **Service Book: Last Serviced at:** Road tax: Tools: Xx xxxx xxx XXXX Last Service: 07/20/2021 Compressor kit: Keys: 2 Last Service by: **Former Owners:** Spare wheel: Xxx xxxxx xxx XXXX **MOT Expiry:** 31/07/2021 Locking wheel nut key **Book Pack:** Yes Tax Expires: 31/07/2021 Locking wheel nut key locatoin: XXX

Equipment

DAB Air Conditioning Reversing camera **Auto Climate Control Dual Zone Climate Sat Nav Functioning Automatic Lights Automatic Lights** Stop / Start **Automatic Wipers Heated Seats Traction Control Heated Front Screen Bluetooth Media Connectivity Cruise Control Full Leather Trim Privacy Glass**

Tyre Infomation

Wheel	Туре	Tyre depth	Tyre make	Tyre size
NSF	Alloy	5.50	Continental	265/45r20 108y
OSF	Alloy	4.95	Continental	265/45r20 108y
OSR	Alloy	4.75	Continental	265/45r20 108y
NSR	Alloy	4.10	Continental	265/45r20 108y
Spare	Space Saver	5.90	Continental	265/45r20 108y

Damage Infomation

Exterior Damages







Damage Part: **Damage Description:**

Door Lorem Ipsum is simply dummy text of the printing.

Bumper 5'5 MM Dent

Windshield Glass broken

Additional Images

















Interior Damages



Damage Part:

Damage Description:

Additional Images



Seat cover change







