

## DRAFT SHEET

Vessel's name: \_\_\_\_\_ KEROS VOYAGER \_\_\_\_\_

IMO No: \_\_\_\_\_ 9390587 \_\_\_\_\_

Type of work: \_\_\_\_\_ **Replacement of one unit** \_\_\_\_\_

Engine(s) Maker: \_\_\_\_\_ **HYUNDAI-MAN B&W** \_\_\_\_\_

Engine(s) Type: \_\_\_\_\_ **6S60MC-C** \_\_\_\_\_

Engine's Serial Number(s): \_\_\_\_\_ **AA2830** \_\_\_\_\_

Running Hours Before Overhaul: \_\_\_\_\_ **66923** \_\_\_\_\_

Running Hours Since Last Overhaul: \_\_\_\_\_

Responsible Service Engineers: DEGTYAROV VALENTYN, KONDRATYIEV DMYTRO, BURYKIN VYACHESLAV, BULYHIN YURII

Joining Date: \_\_\_\_\_ 25/01/23 \_\_\_\_\_

Engine(s)' Preliminary Inspection Notes
<p>Engine Condition</p> <p>Satisfactory, no special remarks</p>
<p>Special Tools</p> <p>Satisfactory, no special remarks</p>
<p>Spares</p> <p>Available</p>

Date & Working Time	General Work Description	Special Notes
26/01 09.00 – 27/01 06.00	<p>Inspection of new unit, removing packing and conserving material, preparation fo installation.</p> <p>Preparation of currently installed unit for dismounting.</p> <p>Assembling of new unit, mounting of new piton head, preparation for mounting.</p> <p>Piping disconnection, untightening of hydraulic bolts, dismounting of cylinder head.</p> <p>Dismounting of old unit (piston, stuffing box, liner).</p> <p>Overhauling of stuffing box.</p> <p>Mounting of new unit.</p> <p>Cylinder head's mounting, connection of piping, tightening of hydraulic bolts.</p> <p>Checking &amp; inspection of proper operation of new unit – no observations.</p>	n/a

DEGTYAROV VALENTYN

