## Pointman Services, Inc

403 Main Street, Suite 200 Buffalo, NY 14203 (716) 408-8724

hayes@pointman.com https://pointman.com

### **RECIPIENT**

George Costello 1207 Delaware Ave Buffalo, NY NY



# **INVOICE #11110**

### **SERVICE DETAILS**

1207 Delaware Ave Buffalo, NY NY

**Job:** #11110

Service Date: 12/19/2019

#### **CONTACT DETAILS**

Home: (555) 555-1989 Mobile: (555) 555-1990

## **WORK COMPLETED**

## **Time and Materials Job**

Work performed under Time and Materials

Item	Qty	Rate	Price
LABORSTD	1	\$99.00	\$99.00
Standard Labor			
GENPART	1	\$0.00	\$0.00
A Generic Part			
		Subtotal	\$99.00
Customer Signature (01/29/2020)			
	Invo	oice Subtotal	\$99.00
		Tax (%)	\$0.00
	Inv	voice Total	\$99.00

# **NOTES**

## **Work Done**

- 1. Heat Exchanger Inspected for cracks & deterioration
- 2. Burners Removed & cleaned if necessary
- 3. Fan Switch Checked & adjusted
- 4. Pilot & Pilot Assembly Cleaned & adjusted as necessary
- 5. Safety Controls Operationally inspected
- 6. Gas Line
- 7. Combustion Air
- 8. Flue Pipe
- 9. Temperatures & Performance
- 10. Panels
- 11. Controls & Safeties
- 12. Lubrication
- 13. Belts & Pulleys
- 14. Air Filter
- 15. Voltage & Amp
- 16. Thermostat Checked & calibrated