

Daily Operations & Site Progress Report

Mucheru World of Golf Dam 3 excavation progress, Greens 1 & 3 polythene membrane installation & red soil levelling, land acquisition follow-up meeting & timber posts relocation; Chaka Farms dairy yield, compound upkeep & canine command drills; Kabete Residence outdoor fireplace excavation, metal gates/fence paintwork & sentry house upgrades.

DAM HAULAGE TRIPS

75 Trips

Excavated topsoil & earth
damping

EXCAVATOR RUN

TIME

9h 00m

Dam 3 basin excavation
& loading

OPERATIONS COST

KES

151,500.00

Excavator (76.5k) +
Tippers (75k)

CHAKA DAIRY YIELD

4.0 Litres

Morning: 2.0L | Evening:
2.0L

1. Mucheru World of Golf — Dam 3 Excavation, Greens



1 & 3 Membranes, Meeting & Logistics

Dam 3 deepening, tipper damping haulage, Greens 1 & 3 polythene lining and red soil levelling, land acquisition consultation & tree posts relocation

Overseen by: Mr. Gichuhi, Ken & Kinoti

Dam 3 Excavation, Tipper Haulage & Financial Operations Summary

- Dam 3 Deepening in Progress:** Heavy excavation progressed intensively at **Dam 3**, with the Sunward SWE210 hydraulic excavator scooping and cutting into the reservoir floor to expand the basin bowl depth and profile the embankment slopes.
- Excavator Operating Hours (9h 00m):** The excavator ran at full operational capacity for **9 hours** (@ KES 8,500/hr = **KES 76,500.00**), executing continuous bulk digging and tipper loading.
- Damping Trucks Haulage (75 Trips):** Damping tipper lorries completed **75 total trips** (@ KES 1,000/trip = **KES 75,000.00**), hauling excavated earth and topsoil from Dam 3 to designated course damping and contour zones.
- Total Daily Operations Expenditure:** Combined equipment expenditure for the day amounted to **KES 151,500.00**.
- Front Loader Equipment Status:** The front loader was non-operational throughout today's shift.

EQUIPMENT / RESOURCE	OPERATING TIME / VOLUME	UNIT RATE (KES)	TOTAL COST (KES)	OPERATIONAL SCOPE & STATUS
Hydraulic Excavator	9 Hours 00 Minutes	@ KES 8,500 / hr	KES 76,500.00	Dam 3 basin deepening & tipper loading
Front Loader	0 Hours (Nil)	—	KES 0.00	Not Operational Today
Damping Tipper Trucks	75 Total Trips	@ KES 1,000 / trip	KES 75,000.00	Hauling & dumping excavated earth across course
TOTAL OPERATIONS & EQUIPMENT COST:			KES 151,500.00	

 Equipment Operational Note

The front loader remained idle/non-operational today; all bulk earthmoving and truck loading duties were handled directly by the hydraulic excavator.

 Greens 1 & 3 Polythene Membrane Installation & Red Soil Levelling

- **Polythene Membrane Liner Installation:** Heavy-duty impermeable black polythene membrane was carefully measured, cut, and laid along the sub-base perimeter of **Green No. 1** and **Green No. 3** over the hardcore stone bed to establish clean hydraulic containment.
- **Red Soil Spreading & Perimeter Locking:** Teams deployed wheelbarrows and shovels to distribute rich red topsoil immediately over the polythene liner margins, securing the edges firmly in place.
- **Red Soil Surface Levelling:** Systematic manual levelling and rough grading conducted across the red soil layer on Greens 1 and 3 to build up the required putting surface sub-grade elevation.

 Greens Foundation Milestone: Greens 1 & 3 Membrane Lining Complete

Polythene membrane positioning and red soil base spreading have been successfully completed on Greens 1 and 3, setting the stage for final rootzone contouring.

 Land Acquisition Follow-Up Meeting & Timber Posts Relocation

- **Land Acquisition Follow-Up Meeting:** A strategic follow-up consultation regarding ongoing land acquisition was hosted on-site at the property today to align on boundary surveys, documentation, and expansion plans.
- **Relocation of Tree Posts at Golf Site (Overseen by Kinoti):** Dedicated logistics crews under Kinoti's supervision loaded felled tree posts, timber logs, and branches onto tractor trailers,

transporting and neatly stacking them at designated staging points across the golf site for property boundary fencing.

 Mucheru World of Golf Video Documentation

 [Dam 3: Reservoir Deepening & Excavation Progress \(Part 1\)](#)



 [Dam 3: Earthmoving & Basin Excavation Progress \(Part 2\)](#)



 Mucheru World of Golf Visual Documentation



Dam 3 Reservoir Basin Deepening
Sunward SWE210 hydraulic excavator scooping and cutting dense earth from the central basin bowl floor of Dam 3.



Dam 3 Embankment Slope Profiling
Excavator bucket carving and establishing uniform embankment slopes and perimeter depths along the Dam 3 reservoir rim.



Damping Trucks Earthmoving (75 Trips)
Blue FAW tipper lorry tipping a fresh load of excavated earth, completing 75 total haulage trips across the course.



Greens 1 & 3 Polythene Membrane & Red Soil
Black impermeable polythene membrane placed along the stone sub-base boundary with red topsoil spread along the perimeter.



Red Soil Spreading & Foundation Levelling

Field workers shovelling, spreading, and rough levelling red soil over the stone foundation and membrane layer on the green.



Polythene Liner Edge & Stone Sub-Base

Detailed view of the polythene liner edge containing the hardcore stone foundation as red topsoil is backfilled.



Red Soil Staging & Green Rootzone Build

Wheelbarrow teams staging red soil heaps across the green footprint to build up consistent rootzone layers.



Tractor Hauling Felled Timber & Posts

Farm tractor and red trailer hauling heavy loads of timber posts and branches across the golf course field.



Relocated Timber Posts Stockpile

Organized stockpile of trimmed timber posts and fence poles neatly stacked at the golf site under Kinoti's supervision.



2. Chaka Farms — Dairy Yield, Compound Care, Canine Obedience & Nutrition

Daily milking logs, general compound and lawn grooming, kennel manners, spin/down/paw commands & dietary food ration reduction



Dairy Production & Milking Yield Logs

Overseen by: **Kamandau**

- **Morning & Evening Milking Logs:** Daily milking concluded under Kamandau's supervision, recording a total daily yield of **4.0 Litres** of fresh milk (Morning: 2.0 Litres | Evening: 2.0 Litres).

PRODUCTION SESSION	MORNING MILKING	EVENING MILKING	TOTAL DAILY YIELD
Fresh Milk Yield	2.0 Litres	2.0 Litres	4.0 Litres



General Compound Cleanliness & Lawn Maintenance

Overseen by: **Margaret & Monica**

- **Compound Upkeep & Grounds Sweeping:** Comprehensive cleanliness routines executed across all farm compound yards, paved walkways, and garden perimeters.
- **Lawn Care & Maintenance:** Mowing, edging, and landscape maintenance carried out to sustain pristine farm grounds.



Canine Unit Care, Advanced Commands & Nutrition Management

Overseen by: **Willy**

- **Kennel Sanitation:** Morning cleaning, washing, and sanitization of all canine accommodation stalls and runs.
- **Kennel Manners & Impulse Control:** Impeccable threshold discipline maintained, with dogs holding steady sit-stays before door opening and meal distribution.
- **Advanced Command Drills (Spin, Down, Paw & Patience):** High-intensity obedience sessions focusing on **spin commands**, **down-stay commands**, **paw gestures**, and extended impulse control with excellent responsiveness.
- **Dietary Management (Food Ration Reduction):** Daily feed rations have been strategically reduced starting today as part of their regulated nutrition, weight management, and active conditioning protocol.

 [Commands Training — Session 1](#) 

 [Commands Training — Session 2](#) 

 [Commands Training — Session 3](#) 

 [Commands Training — Session 4](#) 

 [Commands Training — Session 5](#) 

 [Commands Training — Session 6](#) 

 [Commands Training — Session 7](#) 

 [Spin & Down Commands Training](#) 



3. Kabete Residence — Fireplace Excavation, Gates/Fence Paintwork & Sentry Upgrades

Outdoor fireplace foundation clearance, perimeter metal gates & fence post painting, staircase handrails and sentry house renovations

Overseen by: [Njoki](#)

Outdoor Fireplace Foundation Clearance & Excavation

- **Sunken Fireplace Pit Excavation:** Ground teams made substantial progress clearing soil, tree roots, and stone overburden around the circular outdoor fireplace hearth.
- **Stepped Amphitheater Shaping:** Excavation workers shaped and leveled the tiered seating perimeter surrounding the central stone fire pit.

Metal Gates, Perimeter Fence Posts & Staircase Handrails Paintwork

- **Pedestrian & Garden Gates Painting:** Black gloss protective finish applied across metal boundary gates and garden access sheet-metal doors.
- **Perimeter Fence Posts:** Painting of metal chain-link fence upright posts completed along garden boundaries.
- **Staircase Handrails Painting:** Black metal handrails along the outdoor garden staircase behind the glass room freshly painted.

Main Gate Sentry House Renovations

- **Sentry House Parapet Roof Work:** Exterior parapet surface preparation and painting ongoing atop the stone guardhouse at the main gate.

- **Washroom Wooden Door Painting:** Solid mahogany panel door for the sentry house washroom stained and polished.

📷 Kabete Residence Visual Documentation



Fireplace Stepped Foundation

Stepped circular seating pit and hearth foundation excavation ongoing.



Fireplace Ground Clearance

Workers clearing soil and tree roots around the outdoor fireplace.



Sunken Fireplace Basin Excavation

Detailed view of the sunken fireplace pit excavation and levelling.



Gate Paint Application

Painter applying black protective coating to the metal garden gate.




Metal Boundary Gate Painted

Pedestrian perimeter fence gate coated in protective gloss black paint.



Garden Access Gate Finished

Completed black paintwork on the garden sheet-metal gate.



Fence Posts Painting

Perimeter chain-link metal fence posts being coated in black paint.



Staircase Handrails Painted

Black metal staircase handrails painted behind the glass room.



Main Gate Sentry House Parapet

Painter working on the stone sentry house roof parapet at the main gate.



Sentry House Washroom Door

Polished mahogany panel door for the main gate sentry washroom.



Compiled by Dennis Ndirangu

Operations & Site Progress Reporting • August 17, 2026

Mucheru World of Golf • Chaka Farms • Kabete Residence

Status: Verified Daily Operations Log