

Daily Operations & Site Progress Report

Mucheru World of Golf Dam 3 excavation (7h) & 72 tipper trips, Dam 2 levelling, Tee Box 9 levelling & soil grading (8h Backhoe), Greens 18 & 11 drainage trenching, timber haulage & Green 5/7 irrigation; Chaka Farms dairy yield (7.0L), veterinary kid treatment, animal feeds procurement, compound lawn irrigation & canine unit training graduation; Kabete Residence fireplace clearance & demolition, water pump base masonry & servicing, stairs & river grills/bench paintworks, sentry house completion & domestic pet care.

DAM HAULAGE TRIPS

72 Trips

Excavated soil damping

HEAVY MACHINERY
RUN TIME

15.0 Hours

Excavator: 7h | Backhoe: 8h

MACHINERY
OPERATIONS COST

KES

183,500.00

Excavator, Backhoe & 72 Trips

CHAKA DAIRY YIELD

7.0 Litres

Morning: 4.5L | Evening: 2.5L

1. Mucheru World of Golf — Dam Excavation, Tee Box 9



Levelling, Green Trenching & Soil Grading

Dam 3 deepening & 72 tipper haulage trips, Dam 2 basin shaping, Tee Box 9 levelling, manual sub-surface trenching on Greens 18 & 11, timber haulage & greens irrigation

Overseen by: Mr. Gichuhi & Ken



Dam 3 Excavation, Dam 2 Shaping, Tee Box 9 Levelling & Financial Operations Summary

- Dam 3 Excavation in Progress (7h 00m):** Heavy excavation progressed at **Dam 3**, with the Sunward SWE210 hydraulic tracked excavator running for **7 hours** (@ KES 8,500/hr = **KES 59,500.00**), actively cutting into the central basin floor and loading excavated spoil into tipper trucks.
- Backhoe Operations & Levelling (8h 00m):** The backhoe loader operated for **8 hours** (@ KES 6,500/hr = **KES 52,000.00**), levelling the **Dam 2** basin terrain and slopes, executing full levelling of **Tee Box No. 9**, and spreading dumped soil across fairway corridors.
- Damping Tipper Haulage (72 Trips):** Damping tipper lorries completed **72 total trips** (@ KES 1,000/trip = **KES 72,000.00**), hauling excavated earth and overburden from Dam 3 to designated course damping and contour zones.

- **Total Daily Machinery Expenditure:** Combined heavy equipment and earthmoving operations cost for the day amounted to **KES 183,500.00**.
- **Timber Posts & Brush Relocation (Overseen by Kinoti):** Completed **1 tractor trailer trip** loading and transporting felled tree branches, brushwood, and timber posts across the golf site for area clearance.

EQUIPMENT / RESOURCE	OPERATING TIME / VOLUME	UNIT RATE (KES)	TOTAL COST (KES)	OPERATIONAL SCOPE & TARGET LOCATIONS
Hydraulic Excavator	7 Hours 00 Minutes	@ KES 8,500 / hr	KES 59,500.00	Dam 3 basin deepening, embankment profiling & tipper loading
Backhoe Loader	8 Hours 00 Minutes	@ KES 6,500 / hr	KES 52,000.00	Dam 2 levelling/shaping, Tee Box 9 levelling & dumped soil grading
Damping Tipper Lorries	72 Total Trips	@ KES 1,000 / trip	KES 72,000.00	Excavated topsoil and overburden haulage from Dam 3
Tractor Logistics (Kinoti)	1 Trip	Internal / Farm Tractor	—	Loading and relocating timber posts across the golf site
TOTAL MACHINERY & OPERATIONS COST:			KES 183,500.00	



Sub–Surface Drainage Trenching (Greens 18 & 11) & Turf Irrigation (Greens 5 & 7)

- **Digging Trenches on Greens No. 18 & No. 11:** Ground crews executed manual sub–surface drainage trenching across the levelled green foundations for **Green No. 18** and **Green No. 11**, digging along white chalked grid lines with pickaxes, shovels, and wheelbarrows.
- **Watering Greens No. 5 & No. 7 (Overseen by Willy):** Rotary pop–up and riser sprinkler irrigation systems were operated to water and maintain established lush turfgrass cover on **Green No. 5** and **Green No. 7**.



Aerial Drone Survey & Progress Video

- **Comprehensive Site Aerial Survey:** High–definition aerial drone footage captured the full landscape progress across Mucheru World of Golf, highlighting Green 18 trenching grid, active Dam 3 excavation, tipper haulage, and adjacent constructed green profiles.

Mucheru World of Golf Visual Documentation



Aerial Survey: Green 18 Trenching & Dam 3

High-angle drone view displaying Green 18 drainage grid, active Dam 3 excavator with tipper trucks, and completed green foundation.



Dam 3 Basin Excavation & Truck Loading (7h)

Sunward SWE210 tracked excavator digging the Dam 3 reservoir bowl and loading excavated spoil into a heavy tipper lorry.



Dam 3 Reservoir Deepening

Heavy hydraulic excavator actively profiling the Dam 3 reservoir basin slopes and deepening the central water retention zone.



Dam 2 Basin Levelling & Grading (8h Backhoe)

Yellow backhoe loader grading and pushing earth mounds across the floor of Dam 2 to establish a smooth bed profile.



Dam 2 Embankment Slope Shaping

Backhoe loader working along the perimeter slope, profiling and shaping the outer containment embankment of Dam 2.



Dam 2 Finished Grade & Tree Island

Graded and levelled Dam 2 perimeter floor with the central natural acacia tree island neatly preserved.



Greens 18 & 11 Sub-Surface Trenching

Ground crews using pickaxes, hoes, and shovels to excavate drainage channels along chalked grid layout lines.



Manual Green Drainage Excavation

Site workers excavating uniform drainage trenches across the putting green and clearing spoil using wheelbarrows.



Fairway & Tee Box 9 Soil Grading

Front loader spreading and levelling large mounds of excavated earth dumped along fairway corridors and Tee Box 9.



Earth Spoil Ridge Contouring

Heavy backhoe loader levelling a continuous ridge of dumped earth to match the natural course elevation.



Soil Mound Distribution

Loader scooping and distributing dumped earth across access tracks to eliminate rough terrain unevenness.



Levelled & Compacted Ground Profile

Smooth, graded, and compacted fairway access corridor following machine levelling operations.



Timber Relocation (Overseen by Kinoti)

Red tractor trailer loaded with felled branches, timber posts, and cleared brushwood for haulage (1 trip).



Turf Irrigation on Greens 5 & 7

Rotary pop-up sprinklers spraying wide water arcs across established green turf under Willy's supervision.



Active Green Sprinkler Coverage

Panoramic view of rotary sprinklers providing complete moisture coverage across the circular green putting surface.

2. Chaka Farms — Dairy Yield, Veterinary Treatment, Feed Procurement, Compound Irrigation & Canine Graduation



Milking yield logs (7.0L total), veterinary checkup & goat treatment, Joy Max feed & Cattlephos maziwa purchase, compound lawn irrigation, canine training completion



Dairy Production, Veterinary Care & Livestock Nutrition

Overseen by: **Kamandau**

- **Dairy Milking Yield (7.0 Litres Total):** Daily milking concluded under Kamandau's supervision, recording a strong total daily yield of **7.0 Litres** of fresh milk (Morning Session: **4.5 Litres** | Evening Session: **2.5 Litres**).
- **Veterinary Examination & Goat Kid Treatment:** A certified veterinary doctor visited the farm to examine an ailing goat kid in the goat pen; medical diagnosis was performed and appropriate treatment was successfully administered.
- **Joy Max Animal Feed Procurement:** Procured **1 bag (70 kg)** of high-grade **Joy Max Animal Feed** to ensure fortified nutritional intake for farm livestock.

- **Cattlephos Maziwa Mineral Purchase:** Purchased **Cattlephos Maziwa** high-phosphorus dairy mineral supplement to support optimal lactation, milk quality, and overall herd health.

PRODUCTION SESSION	MORNING YIELD (LITRES)	EVENING YIELD (LITRES)	TOTAL DAILY VOLUME (LITRES)
Fresh Milk Yield	4.5 Litres	2.5 Litres	7.0 Litres

 Compound Cleanliness, Grounds Maintenance & Lawn Irrigation

Overseen by: **Margaret, Monica & Willy**

- **Main House Lawn & Guest House Flower Irrigation (Overseen by Willy):** Deployed rotary pop-up and impact sprinkler systems to thoroughly irrigate the grass lawns surrounding the main house and flowerbeds around the guest house.
- **General Compound Cleanliness (Overseen by Margaret & Monica):** Comprehensive compound upkeep, path sweeping, and garden maintenance executed across the residential and farm yards.

 Canine Unit Training Milestone: Formal Course Completion & Off-Leash Field Exercise

Overseen by: **Willy**

- **Canine Training Completed:** Today marked the official **completion of formal manners, obedience, and pack socialization training** for the 5 White Swiss Shepherds.
- **Off-Leash Walking & Field Exercise:** The pack participated in extensive off-leash walking, free-run conditioning, and socialized exercising across both the farm compound and the open golf field.
- **Pack Commands & Synchronization:** Dogs demonstrated impeccable mastery of "sit-stay", "down-stay", and threshold patience drills, showcasing extraordinary discipline and responsiveness.

 Milestone Achievement: Canine Unit Manners & Obedience Training Completed

All 5 White Swiss Shepherds have officially completed their obedience and socialization training curriculum today, demonstrating exemplary field manners, pack stability, and perfect handler recall.

 **Canine Pack Exercise & Field Drills (Session 1)** 

 **Off-Leash Walking & Recall Practice (Session 2)** 

Canine Unit Field Conditioning & Agility (Session 3)

Official Canine Unit Photo Album

Access the complete high-resolution photo collection from today's canine training graduation session on Google Drive.

[Open Dog Album](#) 

Chaka Farms & Canine Graduation Visual Documentation



Veterinary Checkup & Kid Treatment

Veterinary doctor in yellow jacket examining and administering clinical treatment to a young goat kid in the slatted shed.



Main House Lawn Pop-Up Irrigation

Rotary pop-up sprinkler spraying fine water stream across the front lawn and stone-bordered flowerbeds under Willy's oversight.



Compound Grounds Irrigation

Long-reach impact sprinklers providing comprehensive irrigation across the expansive homestead lawn.



Pack Graduation: Seated Formation

All 5 White Swiss Shepherds demonstrating synchronized "sit-stay" discipline on the green lawn before the circular clubhouse tower.



Advanced Command: Down-Stay Drill

Four Swiss Shepherds holding a steady "down-stay" command along the perimeter of the irrigated golf field.



Pack Synchronization & Calm Demeanor

The entire canine unit resting calmly in formation in the lush grass during off-leash field socialization.



Golf Field Socialization & Distraction Control

Pack seated calmly in the field adjacent to active sprinkler irrigation, demonstrating zero reaction to water distractions.



Attentive Command Response

Alert and responsive pack posture as the dogs await the handler's release command during the graduation drill.

3. Kabete Residence — Fireplace Demolition, Water Pump Elevation & Servicing, River Trail Paintworks & Pet Care



Fireplace clearance & demolition, main water pump disconnection & plinth raising, river water pump servicing, stairs & river grills painting, sentry cabin & bench paint completion, pet care

Overseen by: **Njoki**

🔥 Outdoor Fireplace Clearance, Demolition & Water Pump Base Elevation

- **Fireplace Clearance & Demolition in Progress:** Ground crews actively executed excavation, red soil overburden clearance, and stone structure demolition inside the circular outdoor fireplace pit to prepare the area for new masonry works.
- **Disconnecting Main Water Pump:** Technicians isolated electrical lines and disconnected the main water booster pump unit and manifold piping to facilitate elevating the pump base.
- **Rising the Base for Main Water Pump in Progress:** Masons actively raised and cast a reinforced concrete masonry plinth/base for the main water pump to elevate the installation above ground level, enhancing flood protection and maintenance access.

- **Servicing Water Pump Near the River in Progress:** Plumbers performed comprehensive mechanical and electrical servicing on the secondary water pump and electronic pressure controller located inside the protective metal cage enclosure down near the river.

Paintworks Milestones: Sentry House, River Stairs Grills & Riverside Benches

- **Sentry House Near Fireplace Paintworks Complete (100%):** Both the interior light finishes and exterior weather-resistant dark gloss coat on the sentry house cabin near the fireplace were fully completed.
- **Paint Works for Stairs Grills Towards River in Progress:** Painters applied anti-corrosive black gloss paint along the tubular steel handrails of the long stone staircase leading down towards the river nature trail.
- **Riverbank Barrier Grills Paint Works in Progress:** Application of protective black metal paint ongoing on the perimeter security grills installed along the river edge amidst the lush foliage.
- **Riverside Resting Benches Paintworks Complete (100%):** Completed full black gloss paint restoration on the metal and slat resting benches positioned along the serene riverside path.

Paintwork Milestones Completed: Fireplace Sentry Cabin & Riverside Benches (100%)

Interior and exterior paintworks on the fireplace sentry cabin and the riverside trail resting benches have reached 100% completion today, alongside steady progress on river staircase handrail painting and water pump plinth elevation.

Resident Domestic Pets Care & Nutrition

- **Ajabu the Golden Retriever:** Evening feeding, grooming, and veranda relaxation attended to under Njoki's care on the tiled patio.
- **Resident Cats (Aiko & Reo):** Evening meal served together in clean individual stainless steel bowls on the tiled patio.

Kabete Residence Visual Documentation



Outdoor Fireplace Clearance & Demolition

Site workers clearing excavated soil and demolishing old masonry structures within the circular fireplace pit.



Main Water Pump Manifold Disconnection

Technician uncoupling PPR piping and electrical connections to isolate the booster pump for foundation elevation.



Pump Chamber Base Preparation

Overview of the booster pump and pressure controller housing following pipe disconnection prior to plinth raising.




Raising Water Pump Masonry Plinth

Mason laying mortar and building up the raised concrete base for the water booster pump to prevent water logging.



River Water Pump Servicing & Maintenance

Plumber servicing the electronic pressure control unit and pipe couplings on the water pump down by the river.



Fireplace Sentry Cabin Exterior (100%)

Completed dark gloss paintwork on the glazed sentry cabin frame and door near the fireplace with wet paint notice.



Sentry House Interior & Exterior Finish

Complete view of the sentry booth featuring fresh exterior coating and clean white interior finishes.



River Staircase Steel Handrail Painting

Painter applying anti-corrosive black gloss paint along the continuous handrail down the stone river trail.



Riverbank Perimeter Grills Painting

Application of protective black metal coating along the barrier grills situated directly beside the river.



Riverside Resting Bench Complete (100%)

Fresh black gloss paintwork completed on the steel resting bench along the riverside walking trail.



Riverside Trail Seating Rest Area

Perspective view showing the newly painted resting benches nestled along the serene nature pathway.



Ajabu the Golden Retriever Dinner Time

Resident Golden Retriever Ajabu enjoying his evening meal from his bowl on the tiled residential veranda.



Resident Cats Evening Dinner

Resident cats eating their evening dinner together from clean stainless steel bowls on the tiled floor.



Compiled by Dennis Ndirangu

Operations & Site Progress Reporting • August 19, 2026

Mucheru World of Golf • Chaka Farms • Kabete Residence

Status: Verified Daily Operations Log