DAILY OPERATIONS REPORT

Saturday, 10th October 2026

Daily Operations Progress Report

Comprehensive field operational briefing covering golf course engineering, precision agronomy, irrigation automation, drainage hydraulics, livestock dairy production, and estate landscaping across Mucheru World of Golf and Chaka Farms.

COURSE AGRONOMY & SAND BEDS

Greens 7 & 18

Green 7 Leveled • Green 18 50% Sand

IRRIGATION AUTOMATION DELIVERY

Hunter Solenoids

Valves Received for All Greens

DAIRY MILK PRODUCTION

6.0 Litres

5.0L Sold • 1.0L Staff (100% Reconciled)

DAM & DRAINAGE NETWORK

Dams 1, 2 & 3

Active Inflows • PVC Pipes Connected

Executive Summary — Saturday Operations Overview

Field operations on Saturday, 10th October 2026 maintained outstanding momentum across active project sites, achieving major agronomic, civil drainage, and irrigation technology milestones at Mucheru World of Golf, alongside fully reconciled dairy production, livestock disease control, rock garden landscape construction, and canine unit training at Chaka Farms:

> ### Key Milestone Accomplishments Across Active Sites
>
> Riversand top layer fully spread and precision-leveled across Green 7; riversand spreading commenced on Green 18 reaching 50% surface coverage over pumice; consignment of Hunter automatic solenoid valves delivered for all 18 greens; orange PVC drainage pipes hauled and connected along excavated network trenches; continuous water replenishment inflows maintained for Dams 1, 2, and 3; 100% reconciled dairy milk production (6.0L total); full cattle spraying completed in the paddock crush; and rock garden stepped stone terracing constructed.

- **Mucheru World of Golf:** Agronomy crews applied and precisely leveled the golden riversand top layer across Green 7 over its volcanic pumice sub-base. On Green 18, riversand application advanced smoothly with the green reaching approximately 50% surface coverage. Civil trenching teams excavated dual-purpose inlet and outlet drainage trenches connecting greens and teebox corridors. The farm tractor and trailer hauled shipments of orange PVC drainage pipes from the greenhouse to active corridors, where plumbing crews connected the pipelines directly into drainage trenches. A major technology milestone was achieved with the delivery of Hunter automatic solenoid valves for all greens, establishing automated control for the course-wide sprinkler irrigation network. Hydraulic replenishment continued steadily with active water inflows into Dams 1, 2, and 3, overseen on site by Mr. Gichuhi and Ken alongside Joe Kamau, Peter Githinji, and Carol. Full operational progress was compiled to YouTube (**https://youtu.be/ngfA6jmb-G4**).
- **Chaka Farms:** Dairy milking operations supervised by Kamandau yielded 6.0 Litres of gross cow milk (3.5L morning / 2.5L evening), fully reconciling commercial sales of 5.0 Litres (2.5L morning / 2.5L evening) and internal farm disbursements of 1.0 Litre (0.5L Gladys staff ration and 0.5L Maasai security ration) with 100% volume accuracy. Kamandau conducted thorough cattle spraying in the paddock handling crush using a knapsack sprayer to protect against ticks and external parasites. Willy advanced rock garden construction with stepped stone terracing, conducted canine unit kennel manners, cleaning, paw commands, afternoon paddock walking, and home compound obedience training, noting that the canine 3–month tick injection period expires tomorrow. Margaret and Monica maintained compound cleanliness and grounds upkeep.

Mucheru World of Golf

Overseen by: Mr. Gichuhi & Ken | On Site: Joe Kamau, Peter Githinji & Carol

Green 7 Riversand Leveled, Green 18 Sand Applied (50%), Solenoid Delivery & PVC Drainage Connection

Operations at Mucheru World of Golf on Saturday, 10th October 2026 registered major agronomic, civil drainage, and irrigation technology achievements under the supervision of Mr. Gichuhi and Ken, with technical leadership and oversight from Joe Kamau, Peter Githinji, and Carol on site:

> ### Mucheru World of Golf Operations Summary
>
> Riversand was applied and completely leveled across Green 7; riversand spreading commenced on Green 18, reaching 50% coverage over the pumice foundation; drainage trenches were dug for green and teebox inlets and outlets; the farm tractor hauled PVC pipes from the greenhouse; crew connected PVC pipes in trenches; Hunter automatic solenoid valves arrived for all greens; and active water replenishment continued into Dams 1, 2, and 3.

- **Riversand Spreading & Precision Leveling on Green 7:** Following initial delivery, wheelbarrow teams under Joe Kamau's supervision transported golden riversand across Green 7. Ground crews using leveling rakes and straightedges spread and leveled the sand layer uniformly over the volcanic pumice bed to establish the finished agronomic growing profile.
- **Riversand Application Commenced on Green 18 (50% Coverage):** Sand application operations initiated on Green 18. Wheelbarrow crews hauled riversand from stockpiles, spreading it halfway across the compacted pumice base, achieving approximately 50% complete sand coverage.
- **Drainage Trench Excavation for Greens & Teeboxes:** Manual trenching crews with picks and shovels actively dug deep network trenches designed for excess stormwater drainage outlets and incoming water supply lines serving putting greens and championship teeboxes.
- **Delivery of Hunter Solenoid Valves for All Greens:** A complete consignment of heavy-duty Hunter automatic solenoid valves was delivered on site. These electronic valves will be installed across all greens to enable automated on/off control of irrigation water flow through the sprinkler network.
- **PVC Pipe Haulage by Farm Tractor & Trench Connection:** The farm tractor and red cargo trailer hauled multiple loads of orange PVC drainage pipes from greenhouse storage across to the golf site. Plumbing crews laid the pipes into the excavated trenches, aligning and jointing connections to ensure uninterrupted gravity flow.
- **Continuous Water Inflow into Dams 1, 2 & 3:** Water inlet feeder channels and pipelines discharging into Dam 1, Dam 2, and Dam 3 operated continuously, sustaining active water storage replenishment across the property's reservoir system.

🎬 Video Documentation — Mucheru World of Golf Daily Operations

📹 VIDEO RECORDING

Comprehensive video field documentation capturing Saturday's operations at Mucheru World of Golf: riversand application and leveling on Green 7, halfway riversand progress on Green 18, excavation of inlet and outlet drainage trenches, farm tractor PVC pipe haulage, pipeline jointing in trenches, inspection of delivered Hunter automatic solenoid valves, and continuous water inflows into Dams 1, 2, and 3.

▶ Watch on YouTube

URL: https://youtu.be/ngfA6jmb-G4

⛳ Course Agronomy & Engineering Status Audit — Putting Greens (1 – 18)

Audited by: Dennis

18-hole putting green status audit showing the latest work completed and current condition for each green as of October 10, 2026:

GREEN	CURRENT TECHNICAL & AGRONOMIC STATE	MILESTONE STATUS
Green 1	Surplus red soil (from 1 truck delivery) applied and leveled around collar and surrounds (Oct 2).	Surplus Red Soil Applied
Green 2	Surplus red soil (from 1 truck delivery) applied and leveled around collar and surrounds (Oct 2).	Surplus Red Soil Applied
Green 3	Surplus red soil (from 1 truck delivery) applied and leveled around collar and surrounds (Oct 2).	Surplus Red Soil Applied
Green 4	Outlet drainage trench excavated across fairway corridor to safely discharge runoff (Oct 5).	Outlet Drainage Dug
Green 5	Connected PVC pipes to green outlet drainage trench for excess runoff and sprinkler lines (Oct 9).	Drainage PVC Connected
Green 6	Surplus red soil applied to raise and level surrounds (Sep 28).	Apron Raised • Palms Placed
Green 7 TODAY	Riversand applied over pumice bed and precisely leveled across entire green surface (Oct 10).	Riversand Leveled
Green 8	Connected PVC pipes to outlet drainage trench to convey excess runoff and house supply lines (Oct 9).	Drainage PVC Connected
Green 9	Surplus red soil (from 1 truck delivery) applied and leveled around collar and surrounds (Oct 2).	Surplus Red Soil Applied
Green 10	Surplus red soil (from 1 truck delivery) applied and leveled around collar and surrounds (Oct 2).	Surplus Red Soil Applied
Green 11	Riversand application in progress over pumice bed; partial coverage completed (Oct 3).	Riversand in Progress
Green 12	Surplus red soil (from 1 truck delivery) applied and leveled around collar and surrounds (Oct 2).	Surplus Red Soil Applied
Green 13	Surplus red soil spread around surrounds to raise and match green level (Sep 29).	Surplus Red Soil Applied
Green 14	Connected PVC pipes to green outlet drainage trench to remove surplus stormwater (Oct 9).	Drainage PVC Connected
Green 15	Riversand applied over pumice bed across most part of green (Oct 3).	Riversand Applied (Most Part)
Green 16	Riversand applied over pumice bed across most part of green; application ongoing to completion (Oct 9).	Riversand in Progress
Green 17	Surplus red soil spread around surrounds to raise and align levels (Sep 29).	Surplus Red Soil Applied
Green 18 TODAY	Riversand spreading commenced over pumice bed; approximately 50% surface coverage completed (Oct 10).	Riversand in Progress (50%)

🏌️ Course Engineering Status Audit — Championship Teeboxes (1 – 18)

Audited by: Dennis

Comprehensive 18-hole championship teebox platform audit tracking earthwork leveling, structural embankments, and playing corridor alignments as of October 10, 2026:

TEEBOX	CURRENT TECHNICAL & EARTHWORK STATE	PLATFORM STATUS
Tee 1	Championship launch platform completely reshaped, cut, and graded to design elevation using Backhoe Loader (Sep 24); received 1 lorry red soil delivery (Sep 26).	Platform Reshaped
Tee 2	Playing launch platform completely reshaped, contoured, and graded using Backhoe Loader (Sep 24); received 1 lorry red soil delivery (Sep 26).	Platform Reshaped
Tee 3	Playing launch platform completely reshaped, contoured, and graded using Backhoe Loader (Sep 24); received 1 lorry red soil delivery (Sep 26).	Platform Reshaped
Tee 4	Championship launch platform completely reshaped, cut, and graded using Backhoe Loader (Sep 23); received 1 lorry red soil delivery (Sep 26).	Platform Reshaped
Tee 5	Main perimeter drainage pipeline backfilled all the way past Maina's place (Oct 2).	Drainage Backfilled
Tee 6	Precision leveling and compaction completed; fresh delivery of 1 lorry red loam topsoil unloaded at platform surrounds (Sep 26).	Red Soil In • Leveled
Tee 7	Both number 7 teebox platforms actively reshaped, cut, and leveled by crew under Joe Kamau and supervisors (Oct 4).	Both Platforms Reshaped
Tee 8	Graded, leveled, and contour-adjusted; fresh delivery of 1 lorry red loam topsoil unloaded directly on platform (Sep 26).	Red Soil In • Graded
Tee 9	Playing platform leveled and surrounding perimeter ground graded (Sep 1); received 1 lorry red soil delivery (Sep 26).	Platform Leveled
Tee 10	Graded and compacted platform serving the start of the back-nine playing corridor; received 1 lorry red soil delivery (Sep 26).	Platform Compacted
Tee 11	Playing launch platform actively shaped, graded, and refined to final architectural contours and levels (Oct 8).	Shaped & Refined
Tee 12	Both championship and forward platforms actively shaped, leveled, and refined to finished design elevation (Oct 8).	Shaped & Refined
Tee 13	Playing platform earthworks completely finished, shaped, and refined to final design elevation and contours (Oct 7).	Finished & Refined
Tee 14	Launch platform earthworks completely finished, shaped, and refined to final playing contour (Oct 7).	Finished & Refined
Tee 15	Launch platform shaping completely finished; terrace cut to design elevation and precision leveled (Oct 6).	Platform Reshaped
Tee 16	Surplus red soil moved onto platform; launch terrace completely reshaped and leveled (Oct 5).	Platform Reshaped
Tee 17	Launch platform reshaped, cleared of brush, and graded to playing corridor alignment (Oct 6).	Platform Reshaped
Tee 18	Championship tee platform leveled; perimeter approach cleared and graded (Sep 1); received 1 lorry red soil delivery (Sep 26).	Platform Leveled

Operations Agronomy & Engineering Synthesis

Putting Greens & Hydraulic Progress: Riversand fully spread and leveled on Green 7; Green 18 reached 50% sand coverage; Hunter automatic solenoid valves delivered for all greens; orange PVC drainage pipes connected along trenches; all 18 greens (100%) have subgrade foundations excavated and membrane lined; 100% have volcanic pumice layers compacted; active water replenishment continuing for Dams 1, 2, and 3.
Championship Teebox Platforms: Teeboxes 11, 12, 13, and 14 completely shaped, graded, and refined; drainage and water inlet trenches excavated connecting teebox and green zones; course playing corridors primed for grass planting.

📸 Photographic Field Evidence — Mucheru World of Golf

Sequential photographic field documentation covering riversand spreading and leveling on Green 7, Green 18 riversand progress (50%), solenoid delivery, drainage trench digging, PVC pipe tractor haulage and connection, and dam water storage (Dams 1, 2 & 3):

Riversand Applied and Leveled on Green 7
Crew using leveling rakes and wheelbarrows to spread and level the golden riversand layer over Green 7 pumice bed.

Initial Riversand Application on Green 7
Wheelbarrow team pushing riversand across the compacted volcanic pumice foundation at Green 7.

Joe Supervising Sand Transport to Green 7
Joe Kamau overseeing the field team loading and transporting riversand from stockpile to Green 7.

Green 18 Halfway Riversand Coverage (50%)
High-angle view of Green 18 showing riversand applied across 50% of the green over the pumice sub-base.

Hunter Automatic Solenoid Valve Delivery
Close-up inspection of the delivered Hunter solenoid valve designed for automated water flow control on greens.

Boxed Delivery of Hunter Solenoids for All Greens
Package containing Hunter automatic solenoid valves delivered to automate irrigation flow across all 18 greens.

Manual Drainage Trench Excavation

Laborers digging drainage and water supply trenches with picks along ballast gravel piles and orange PVC pipes.

Connecting Orange PVC Pipes in Trench

Orange PVC drainage pipe aligned and connected inside the freshly excavated trench line across the fairway.

Farm Tractor Hauling PVC Pipes

Farm tractor and trailer transporting a full load of orange PVC drainage pipes across the golf site.

Loading PVC Pipes at Greenhouse

Tractor loaded with orange PVC pipes at the greenhouse storage area ready for transit to active trench lines.

Aerial Drone Perspective of Dam 1

High-altitude drone shot showing Dam 1 filled with water, lined slopes, anchor trenches, and surrounding landscape.

Dam 1 Water Reservoir Status

Ground perspective of Dam 1 showcasing active water storage volume, liner placement, and perimeter bunds.

Dam 3, Greens & Drainage Trenches Network

Comprehensive aerial view showing Dam 3, multiple greens with pumice and sand beds, and interconnected trench lines.

Dam 3 Channel & Green 18 Overview

Aerial drone capture showing Dam 3 reservoir corridor alongside Green 18 with its halfway riversand bed.

Dam 3 Water Reservoir Ground View

Ground-level perspective of Dam 3 lined reservoir holding water with supply lines along the embankment.

Dam 2, Dam 1 & Course Drainage Aerial

Broad aerial view showing Dam 2 with island feature, Dam 1 in background, nursery green, and course trench network.



Drainage Trenches Network & Green 7 Sand Bed

Aerial perspective highlighting Green 7 fully covered in golden sand alongside Dam 2 and extensive trench routes.

Chaka Farms

Milking & Cattle: Kamandau | Rock Garden & Canine: Willy | Compound Maintenance: Margaret & Monica

Dairy Production (6.0L Reconciled), Cattle Spraying, Rock Garden Setup & Canine Care

Farm operations on Saturday, 10th October 2026 maintained strict operational standards across livestock management, landscape civil construction, veterinary disease control, canine unit routines, and general estate cleanliness:

> **Chaka Farms Progress Summary**
>
> Dairy milking yielded 6.0 Litres gross with 100% mathematical reconciliation (5.0L commercial sales, 1.0L internal staff rations); Kamandau carried out complete cattle spraying in the race crush; Willy advanced rock garden construction with stone terracing, conducted canine kennel manners, cleaning, paw command, afternoon walking, and compound obedience training; and Margaret & Monica maintained pristine compound cleanliness.

- **Dairy Production & Milking Operations (Kamandau):** Milking routines yielded 3.5 Litres in the morning and 2.5 Litres in the evening, totaling 6.0 Litres gross harvest. Commercial sales accounted for 5.0 Litres (2.5L morning + 2.5L evening), while 1.0 Litre was allocated on-farm for staff rations (0.5L Maasai security + 0.5L Gladys), achieving 100% volume reconciliation with zero discrepancy.
- **Cattle Spraying & Parasite Control (Kamandau):** Kamandau conducted thorough cattle spraying in the paddock handling crush using a manual knapsack sprayer, applying approved acaricide to protect the herd against ticks, biting flies, and vector-borne infections.
- **Rock Garden Setup & Construction (Willy):** Willy commenced the layout and construction of a landscaped rock garden. Stepped earthen planting mounds were sculpted and lined with selected natural building stones to create distinct raised terraced beds for ornamental plantings.
- **Canine Unit Care, Manners & Training (Willy):** Willy conducted structured kennel manners drills, stall sanitization, paw command exercises, and afternoon paddock walking. Additionally, obedience and patience drills were executed within the home compound to reinforce calm behavior around moving people.
- **Canine Tick Control Injection Reminder:** Willy noted that the 3-month tick control injection for the canine unit expires tomorrow (October 11th), requiring a fresh veterinary administration to maintain immunity.
- **Estate Compound Cleanliness (Margaret & Monica):** Margaret and Monica carried out comprehensive sweeping, litter collection, and maintenance across farm courtyards, pathways, and compound perimeters.

🥛 Daily Dairy Milking Yield Ledger & Volume Reconciliation

Complete volumetric breakdown of daily milk production, commercial sales, and internal farm rations recorded on Saturday, 10th October 2026:

Category / Transaction	Morning Session	Evening Session	Daily Total
Gross Milk Harvested	3.5 Litres	2.5 Litres	**6.0 Litres**
Commercial Milk Sales (Dispatched)	2.5 Litres	2.5 Litres	**5.0 Litres**
Internal Farm Allocation — Maasai Security	—	—	**0.5 Litres**
Internal Farm Allocation — Gladys (Staff)	—	—	**0.5 Litres**
Internal Farm Allocation — Goat Kids (Weaned)	0.0 Litres	0.0 Litres	0.0 Litres
Total Volume Accounted For	**3.5 Litres**	**2.5 Litres**	**6.0 Litres (100% Reconciled)**

Milk Reconciliation Formula Verification

Total Gross Milk Harvested (6.0L) = Commercial Sales (5.0L) + Internal Allocations (0.5L Maasai + 0.5L Gladys). 100% accounted for with zero discrepancy.

⚠️ Canine Unit Veterinary Notice — Tick Control Injection Due

The 3-month tick control injection period for the canine unit concludes tomorrow (Sunday, October 11th). A fresh injection is required to maintain ongoing tick and parasite prevention.

🎬 Video Documentation — Chaka Farms Canine Unit Training

Field video recordings documenting Saturday's canine unit obedience, patience, and kennel manners training drills conducted by Willy:

Obedience & Patience Training

🎥 VIDEO RECORDING

Willy conducting obedience and patience training drills with the dogs in the home compound, maintaining focus and discipline despite human activity.

📁 Access on Google Drive

`Obedience & Patience.mp4 (7.5 MB)`

Kennel Manners Drill

🎥 VIDEO RECORDING

Willy conducting kennel entry/exit restraint and boundary manners drills with the canine unit, reinforcing calm behavior and attentiveness.

📁 Access on Google Drive

`Kennel manners.mp4 (8.9 MB)`

📸 Photographic Field Evidence — Chaka Farms

Sequential photographic field documentation covering cattle spraying in the race crush and rock garden stepped stone terracing construction:

Cattle Spraying for Tick and Parasite Control
Kamandau using a knapsack sprayer to treat dairy cattle against ticks and external parasites in the paddock crush.

Rock Garden Terracing & Stone Mound Setup
Willy setting up stepped earthen mounds lined with natural stone perimeter borders for rock garden landscaping.

D **Compiled by Dennis**

Saturday, 10th October 2026 • Operations Reporting