


Vehicle Condition Report

Front side



Roof Condition: Not visible

Windshield Condition: Not visible

Hood Condition: Major damage

Grill Condition: Major damage

Front Bumper Condition: Major damage


Right Mirror Condition: Not visible

Left Mirror Condition: Not visible

Front Right Light Condition: Major damage

Front Left Light Condition: Major damage

Back side



Rear Window Condition: Not visible

Trunk Tgate Condition: Major damage


Trunk Cargo Area Condition: Major damage

Rear Bumper Condition: Major damage

Right Tail Light Condition: Not visible

Left Tail Light Condition: Not visible

Right side



Right Rear Quarter Condition: Not visible

Right Rear Door Condition: Not visible


Right Front Door Condition: Not visible

Right Fender Condition: Major damage

Right Front Tire Condition: Not visible

Right Rear Tire Condition: Not visible

Left side



Left Rear Quarter Condition: Major damage

Left Rear Door Condition: Not visible

Left Front Door Condition: Not visible

Left Fender Condition: Major damage

Left Front Tire Condition: Not visible

Left Rear Tire Condition: Not visible