


## Front side



Roof Condition: Not visible

Windshield Condition: Not visible

Hood Condition: Minor damage

Grill Condition: Minor damage


Front Bumper Condition: Major damage

Front Lights Condition: Minor damage

Front Left Tire Condition: Not visible

Front Right Tire Condition: Not visible

## Back side



Rear Window Condition: Not visible

Trunk Tgate Condition: Major damage

Trunk Cargo Area Condition: Major damage


Rear Bumper Condition: Major damage

Tail Lights Condition: Major damage

Rear Left Tire Condition: Not visible

Rear Right Tire Condition: Not visible

## **Right side**




Right Rear Quarter Condition: Major damage

Right Rear Door Condition: Seems OK

Right Front Door Condition: Seems OK

Right Fender Condition: Minor damage

## **Left side**



Mirrors Condition: Not visible

Left Fender Condition: Minor damage

Left Front Door Condition: Seems OK

Left Rear Door Condition: Seems OK

Left Rear Quarter Panel Condition: Major damage