Integrity.
Flexibility.
Quality.



Hugh Scullin
Consultant

Relevant Qualifications

- Bachelor of Science (Honours)
- NATA Accredited Inspection Surveyor
- NATA Accredited Airborne Contaminant Exposure Sampler

Professional Overview

Consultant with a strong grounding in contaminated land and hands-on experience across hazardous materials and occupational hygiene. Hugh delivers projects from fieldwork through to reporting, including site contamination assessments, asbestos and landfill gas monitoring, hazardous building materials surveys, and mould and air quality assessments. He places particular emphasis on strong client relationships, robust data collection, and clear, evidence-based conclusions that give clients confidence to move their projects forward.

Contaminated Land – Select Experience

Lipman Pty Ltd – Soil Contamination Assessment and Waste Classification
Hugh assessed soil across an approximately 1.1-hectare area of Girraween Public School following the demolition of demountable buildings. This involved test pit sampling at 22 locations, evaluation against primary school land use criteria, waste classification of fill for off-site disposal, and recommendations for a Remedial Action Plan to address bonded asbestos contamination.

VG Project Group – Detailed Site Contamination Assessment
Hugh undertook a Detailed Site Contamination Assessment of an active market garden site in Bossley Park, supporting a State Significant Development Application for a seniors housing development. This included a desktop site history review, site walkover, and soil and groundwater sampling, with results evaluated against NEPM (2013) criteria and recommendations for asbestos delineation and a Remedial Action Plan.

Penrith City Council – Landfill Gas Monitoring Program
Hugh undertakes monthly landfill gas monitoring at Gipps Street Recreation Precinct, a former landfill in Claremont Meadows, in accordance with the Site's Long-Term Environmental Management Plan.

Hazardous Materials and Asbestos – Select Experience

CoHaus Projects – Hazardous Building Materials Survey
Hugh undertook a hazardous building materials survey of three single-storey dwellings in Randwick. This involved the inspection and sampling of suspected hazardous materials, including asbestos, lead in paint and dust, synthetic mineral fibres and polychlorinated biphenyls. He prepared a hazardous building materials register to guide their management and removal before any demolition works were carried out.

ADDRESS
Suite G03, Building 2
Pymble Corporate Centre
20 Bridge Street
Pymble NSW 2073

CONTACT
(02) 9889 2488
help@getex.com.au

WWW.GETEX.COM.AU

NATA WORLD RECOGNISED ACCREDITATION
Certified System Quality ISO 9001 SAI GLOBAL
Certified System OHS ISO 45001 SAI GLOBAL

Integrity.
Flexibility.
Quality.

Hugh Scullin
Consultant

Hazardous Materials and Asbestos – Select Experience (continued)

Penrith City Council – Asbestos Monitoring and Excavation Supervision
Hugh was the on-site consultant for fencing installation works at Gipps Street Recreation Precinct, a former landfill in Claremont Meadows with asbestos-impacted fill contained beneath a capping layer. Work included:

- Supervision of excavation works in accordance with the Site's Long-Term Environmental Management Plan, including inspection of spoil and post holes for asbestos and breaches of the capping layer.
- Asbestos air monitoring, continuous landfill gas monitoring, clearance inspections and validation sampling, and preparation of the validation report.

Barker College – Hazardous Building Materials Survey
Hugh undertook a hazardous building materials survey of four buildings across two properties in Mount Victoria. This involved the identification and assessment of asbestos, lead in paint, lead in dust, metallic lead, synthetic mineral fibres, polychlorinated biphenyls and ozone depleting substances, and preparation of a hazardous building materials register with risk-ranked management recommendations.

Occupational Hygiene – Select Experience

Whelan Property – Mould Assessment, Remediation Planning and Validation
Hugh delivered the full mould assessment and remediation process for a residential unit in North Strathfield that had been uninhabitable for approximately four years due to persistent water ingress. This included visual inspection and microbial sampling, a Mould Remediation Action Plan to direct the contractor, and post-remediation validation, including follow-up validation after further remediation.

Hunter Ridge Property Group – Air Quality Assessment
Hugh undertook an outdoor air quality assessment to determine the suitability of a proposed childcare centre in Kurmond with respect to traffic and industrial emissions. This involved continuous monitoring of gases, particulates and VOCs at two outdoor play areas over the centre's operating hours, assessed against NEPM guidelines.

ADDRESS
Suite G03, Building 2
Pymble Corporate Centre
20 Bridge Street
Pymble NSW 2073

CONTACT
(02) 9889 2488
help@getex.com.au

WWW.GETEX.COM.AU

NATA WORLD RECOGNISED ACCREDITATION
Certified System Quality ISO 9001 SAI GLOBAL
Certified System OHS ISO 45001 SAI GLOBAL