

# Inspection Report - Flat 2002

**Project:** Highland

**Building:** Tower D

**Floor:** Floor 20

**Flattype:** 1 BHK

**Generated On:** 26-08-2025

## Summary

**193**

TOTAL CHECKPOINTS

**28**

PENDING

**165**

COMPLETED

**0**

REJECTED

## Stage:

### Checklist: Polish Checklists

QUESTION	STATUS	ATTEMPT DETAILS
<b>Polish Finish is Uniform without Patches or Polish Droplets on the frames</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 10:45
<b>The polish on the top surface of the shutter is Uniformly applied.</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 10:45

## **Checklist: Carpentry Checklists**

---

QUESTION	STATUS	ATTEMPT DETAILS
<b>All hardwares fixed properly as per the approved drawing and dimensions, Tower bolt and handles fixed properly, peep hole is in place</b>	PENDING_FOR_APPROVAL Attempt 1  (2 attempts)	<p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Rejected_By_Checker 26-08-2025 10:47</p>  <p>towerbolt extra screw holes observed</p>
		<b>Attempt 2</b>
		<p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Created</p>
<b>Lock slot is cut properly, lock plate, Architrave is fixed properly</b>	COMPLETED  (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 10:47</p>
<b>The hinge slots are properly cut, and the hinges are fixed properly.</b>	COMPLETED  (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 10:47</p>

QUESTION	STATUS	ATTEMPT DETAILS
<b>Is the hinges screw heads flushed with plates</b>	<b>COMPLETED</b> (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b></p> <p><b>Jayant Yadav</b></p> <p>Status: Completed</p> <p>26-08-2025 10:48</p> 
<b>The intumescent strip has been properly fixed on the main door and kitchen door shutters.</b>	<b>COMPLETED</b> (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b></p> <p><b>Jayant Yadav</b></p> <p>Status: Completed</p> <p>26-08-2025 10:47</p>
<b>Is any undulations observed in Door shutter Laminate</b>	<b>COMPLETED</b> (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b></p> <p><b>Jayant Yadav</b></p> <p>Status: Completed</p> <p>26-08-2025 10:49</p>

QUESTION	STATUS	ATTEMPT DETAILS
<b>Is the 3mm gap is maintained at door frame bottom and sealant is applied</b>	<span>PENDING_FOR_MATCH</span> Attempt 1 (2 attempts)	<b>CHECKER</b> <b>Jayant Yadav</b> Status: Rejected_By_Checker 26-08-2025 10:50 
		<b>Attempt 2</b> <b>CHECKER</b> <b>Jayant Yadav</b> Status: Created

<b>Gap Between Door Shutter and Frame &amp; Shutter Edges with Flooring is uniform &amp; within tolerance limits.</b>	<span>PENDING_FOR_MATCH</span> Attempt 1 (2 attempts)	<b>CHECKER</b> <b>Jayant Yadav</b> Status: Rejected_By_Checker Remarks: bottom gap is not maintained properly 26-08-2025 10:50 
---	--	--

QUESTION	STATUS	ATTEMPT DETAILS
		<p><b>Attempt 2</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Created</p>
<b>Magnetic Door catches &amp; PVC buffers installed at the Correct Location and Securely Fixed</b>	<b>COMPLETED</b> (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 10:50</p>
<b>Is the lock and other hardwares fixed properly and working smoothly.</b>	<b>COMPLETED</b> (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 10:50</p>

## Checklist: Flooring Checklists

QUESTION	STATUS	ATTEMPT DETAILS
<b>Floor tiles no crack, chipped off observed</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 10:53
<b>Hollow sound is observed in floor tile or skirting</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 10:53
<b>Flooring tiles / marble observed without any leapages/ offsets</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 10:53

## Checklist: Skirting Checklists

QUESTION	STATUS	ATTEMPT DETAILS
<b>Is the Skirting aligned with Finished top Edge &amp; without offset.</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 10:53
<b>The top surface of the tile skirting has been properly finished using a Facile diamond hand pad</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 10:53

## **Checklist: AL Window Checklists**

---

QUESTION	STATUS	ATTEMPT DETAILS
<b>Aluminium window &amp; locks are working smoothly</b>	<b>COMPLETED</b> (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 10:58</p>
<b>Anchor fasteners are provided as per drawing</b>	<b>PENDING_FOR_APPROVAL</b> (2 attempts)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Rejected_By_Checker 26-08-2025 10:58</p> 
		<p><b>Attempt 2</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Created</p>
<b>The shutter lock is functioning properly</b>	<b>COMPLETED</b> (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 10:58</p>

QUESTION	STATUS	ATTEMPT DETAILS
<b>No damage or peeling of the coating was observed on the window.</b>	<b>COMPLETED</b> (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 10:58</p>
<b>The roller was functioning properly during the operation of the sliding shutter.</b>	<b>COMPLETED</b> (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 10:58</p>
<b>The coating on the living balcony track angle is observed to be proper.</b>	<b>COMPLETED</b> (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 10:58</p>
<b>Silicone sealant has been properly filled around the window periphery</b>	<b>COMPLETED</b> (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 10:58</p>
<b>Gasket is fixed properly, drain caps are provided</b>	<b>COMPLETED</b> (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 10:58</p>

QUESTION	STATUS	ATTEMPT DETAILS
<b>No cracks/ scratches are observed on the window glass</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b> <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 10:58

## **Checklist: Painting Checklists**

---

QUESTION	STATUS	ATTEMPT DETAILS
<b>Internal painting is done up to the mark without any patch work is balance or without any shade variation of paint</b>	<b>COMPLETED</b> (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:04</p>
<b>The wall paint finish is found to be uniform.</b>	<b>PENDING_FOR_APPROVAL</b> (2 attempts)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Rejected_By_Checker 26-08-2025 11:04</p> 
		<p><b>Attempt 2</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Created</p>
<b>The skirting projection from the wall is observed to be proper and uniform</b>	<b>COMPLETED</b> (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:04</p>

QUESTION	STATUS	ATTEMPT DETAILS
<b>The wall internal corners of rooms paint is found to be proper &amp; uniform</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:04
<b>The walls are observed without any undulations</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:04
<b>No Cracks observed in walls</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:04
<b>Is the surface preparation done properly for wallpaper fixing</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:04

## Checklist: Flase Ceiling Checklists

QUESTION	STATUS	ATTEMPT DETAILS
<b>No Cracks observed in false ceiling</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:04
<b>Finishing around the lights and sprinkler is done properly</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:04
<b>Cove area facia edges are in line and level and thickness maintained</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:04
<b>Is the false ceiling joints finished evenly without any undulations</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:05

## **Checklist: Electrical Checklists**

---

QUESTION	STATUS	ATTEMPT DETAILS
All switches ,switch plates fixed properly in line and level.	PENDING_FOR_CHECKER Attempt 1  (2 attempts)	<p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Rejected_By_Checker 26-08-2025 11:07</p> 
		<p><b>Attempt 2</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Created</p>
The chart has been fixed on the distribution board	COMPLETED  (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:07</p>
All lights are working properly	COMPLETED  (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:07</p>

QUESTION	STATUS	ATTEMPT DETAILS
<b>Main DB box fixed properly with All screws available and SLD is provided</b>	<b>PENDING_FOR_MATCH</b> Attempt 1 (2 attempts)	<b>CHECKER</b> <b>Jayant Yadav</b> Status: Rejected_By_Checker 26-08-2025 11:06 
	<b>Attempt 2</b>	<b>CHECKER</b> <b>Jayant Yadav</b> Status: Created

## Checklist: AC Checklists

QUESTION	STATUS	ATTEMPT DETAILS
<b>No Water Leakage Observed in Internal AC Unit</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:05
<b>AC IDU is fixed in line and level</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:05

## Checklist: Polish Checklists

QUESTION	STATUS	ATTEMPT DETAILS
<b>Door frame polishing is carried out upto the mark</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:07
<b>The polish on the top surface of the shutter is Uniformly applied.</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:07

## **Checklist: Carpentry Checklists**

---

QUESTION	STATUS	ATTEMPT DETAILS
<b>All hardwares fixed properly as per the approved drawing and dimensions</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:07
<b>Lock slot is cut properly, lock plate, Architrave is fixed properly</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:07
<b>Hinges screws are fixed properly, screw heads flushed with plates</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:07
<b>The intumescent strip has been properly fixed on the door shutters.</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:07
<b>The hinge slots are properly cut, and the hinges were fixed.</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:08

QUESTION	STATUS	ATTEMPT DETAILS
<b>Screws are provided and fixed as per the hinge screw holes.</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:08
<b>Is the 3mm gap is maintained at door frame bottom and sealant is applied</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:08
<b>Proper and equal gap is maintained between door shutter and flooring.</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:08
<b>The gap between the frame and the shutter should be proper and uniform.</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:08

QUESTION	STATUS	ATTEMPT DETAILS
<b>Is the lock and other hardwares fixed properly and working smoothly.</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:08

## Checklist: Flooring Checklists

QUESTION	STATUS	ATTEMPT DETAILS
<b>Floor tiles no crack, chipped off observed</b>	<b>PENDING_FOR_MATCH</b> Attempt 1 (2 attempts)	<b>CHECKER</b> <b>Jayant Yadav</b> Status: Rejected_By_Checker 26-08-2025 11:40 
		<b>Attempt 2</b>
		<b>CHECKER</b> <b>Jayant Yadav</b> Status: Created
<b>Floor ling observed without any leapages/ offsets</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b> <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:40

## **Checklist: Carpentry Checklists**

---

QUESTION	STATUS	ATTEMPT DETAILS
<b>Floor tiles no crack, chipped off observed</b>	<b>COMPLETED</b> (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:43</p>
<b>Floor ling observed without any leapages/ offsets</b>	<b>COMPLETED</b> (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:43</p>
<b>Hinges screws are fixed properly, screw heads flushed with plates</b>	<b>COMPLETED</b> (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:44</p>
<b>The intumescent strip has been properly fixed on the door shutters.</b>	<b>COMPLETED</b> (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:44</p>
<b>The hinge slots are properly cut, and the hinges were fixed.</b>	<b>COMPLETED</b> (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:44</p>

QUESTION	STATUS	ATTEMPT DETAILS
<b>Screws are provided and fixed as per the hinge screw holes.</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:45
<b>Is the 3mm gap is maintained at door frame bottom and sealant is applied</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:45
<b>Proper and equal gap is maintained between door shutter and flooring.</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:45
<b>The gap between the frame and the shutter should be proper and uniform.</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:45

QUESTION	STATUS	ATTEMPT DETAILS
<b>Is the lock and other hardwares fixed properly and working smoothly.</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:45

## **Checklist: Dado Checklists**

---

QUESTION	STATUS	ATTEMPT DETAILS
No hollow sound / debonding of tiles is observed	COMPLETED (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:48</p>
No cracks observed in Dado tile	PENDING_FOR_CHECKER (2 attempts)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Rejected_By_Checker 26-08-2025 11:46</p> 
		<p><b>Attempt 2</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Created</p>
No dado tiles are chipped off, edges not magaed	COMPLETED (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:48</p>

QUESTION	STATUS	ATTEMPT DETAILS
<b>No hollowness is observed in the marble jamb of the kitchen door opening.</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:48
<b>After fixing the CP connector, no tile damage or cracks are observed.</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:48
<b>Below kitchen Platform Dado tiles are not chipped off, no cracks observed</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:47
<b>All bird mouth joints are finished properly with emery.</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:48
<b>Kitchen platform top marble/ quartz drip mould is provided on edge</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:47

QUESTION	STATUS	ATTEMPT DETAILS
<b>Kitchen opening marble is fixed in proper line and plumb, marble is not chipped off, No cracks observed in marble jambs, joints of marble jambs are finished properly.</b>	<span style="background-color: #c8f7e4; border-radius: 10px; padding: 2px 10px; border: 1px solid #c8f7e4;">COMPLETED</span> (1 attempt)	<b>Attempt 1</b> <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:48

## Checklist: Skirting Checklists

QUESTION	STATUS	ATTEMPT DETAILS
<b>skirting is fixed properly in line without any offsets</b>	<span style="background-color: #c8f7e4; border-radius: 10px; padding: 2px 10px; border: 1px solid #c8f7e4;">COMPLETED</span> (1 attempt)	<b>Attempt 1</b> <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:48

## **Checklist: Modular Kitchen Checklists**

---

QUESTION	STATUS	ATTEMPT DETAILS
All cabinets working smoothly, hinges of approved make are provided.	<span style="background-color: #c8f7e4; border-radius: 10px; padding: 2px 10px; color: green;">COMPLETED</span> (1 attempt)	<b>Attempt 1</b> <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:50
Gas pump/ Spring hinges provided	<span style="background-color: #c8f7e4; border-radius: 10px; padding: 2px 10px; color: green;">COMPLETED</span> (1 attempt)	<b>Attempt 1</b> <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:50
All cabinet shutters are intact, coating is not damaged	<span style="background-color: #c8f7e4; border-radius: 10px; padding: 2px 10px; color: green;">COMPLETED</span> (1 attempt)	<b>Attempt 1</b> <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:50
Proper alignment is observed in the top and bottom unit shutters	<span style="background-color: #c8f7e4; border-radius: 10px; padding: 2px 10px; color: green;">COMPLETED</span> (1 attempt)	<b>Attempt 1</b> <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:50 

QUESTION	STATUS	ATTEMPT DETAILS
<b>The cabinet's internal screw caps were found okay</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:50
<b>No rust is found on the bottom unit shutter hinges</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:50
<b>Top storages are provided with pivot hinges/ kechi hinges</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:50
<b>All horizontal partitions are provided with load capacity stickers</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:50
<b>The drawer for the cutlery tray closes smoothly and properly</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:50

QUESTION	STATUS	ATTEMPT DETAILS
<p><b>Marble Countertop is Polished and Crack-Free &amp; Joint Between Marble Countertop and Dado Wall is properly Sealed with Silicone.</b></p>	<p><b>COMPLETED</b> (1 attempt)</p>	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:50</p>

## Checklist: AL Window Checklists

QUESTION	STATUS	ATTEMPT DETAILS
<b>The shutter lock is functioning properly</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:51
<b>No damage or peeling of the coating was observed on the window.</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:51
<b>Silicone sealant has been properly filled around the window periphery</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:50
<b>The roller was functioning properly during the operation of the sliding shutter.</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:51

## Checklist: Electrical Checklists

QUESTION	STATUS	ATTEMPT DETAILS
<b>Switches and Sockets Properly fixed and functional</b>	<b>PENDING_FOR_APPROVAL</b> Attempt 1 (2 attempts)	<b>CHECKER</b> <b>Jayant Yadav</b> Status: Rejected_By_Checker 26-08-2025 11:52 
	<b>Attempt 2</b>	<b>CHECKER</b> <b>Jayant Yadav</b> Status: Created

## Checklist: Plumbing Checklists

QUESTION	STATUS	ATTEMPT DETAILS
<b>WC , Washbasin, and Shower Fixtures Installed and Leak-Free.</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:53
<b>All Accessories like Towel Rod, Brush Holder, Partition Glass, Mirror are fixed properly.</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:53
<b>Darin pipes fixing, saddling is done properly and connections are leakfree</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:53

## **Checklist: Polish Checklists**

---

QUESTION	STATUS	ATTEMPT DETAILS
<b>Door frame polishing is carried out upto the mark</b>	<b>PENDING_FOR_MAKER</b> Attempt 1  (2 attempts)	<p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Rejected_By_Checker 26-08-2025 11:11</p>  <p>frame polish not upto the mark</p>
		<b>Attempt 2</b>
		<p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Created</p>
<b>The polish on the top surface of the shutter is Uniformly applied.</b>	<b>PENDING_FOR_MAKER</b> Attempt 1  (2 attempts)	<p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Rejected_By_Checker 26-08-2025 11:11</p> 

QUESTION	STATUS	ATTEMPT DETAILS
		<p><b>Attempt 2</b></p> <p><b>CHECKER</b></p> <p><b>Jayant Yadav</b></p> <p>Status: Created</p>

## **Checklist: Carpentry Checklists**

---

QUESTION	STATUS	ATTEMPT DETAILS
<b>All hardwares fixed properly as per the approved drawing and dimensions</b>	<b>COMPLETED</b> <small>(1 attempt)</small>	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:13
<b>Lock slot is cut properly, lock plate, Architrave is fixed properly</b>	<b>COMPLETED</b> <small>(1 attempt)</small>	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:13
<b>Hinges screws are fixed properly, screw heads flushed with plates</b>	<b>COMPLETED</b> <small>(1 attempt)</small>	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:13
<b>Is the 3mm gap is maintained at door frame bottom and sealant is applied</b>	<b>PENDING FOR MARKER</b> <small>(2 attempts)</small>	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Rejected_By_Checker 26-08-2025 11:13  

QUESTION	STATUS	ATTEMPT DETAILS
		<p><b>Attempt 2</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Created</p>

---

<p><b>Proper and equal gap is maintained between door shutter and flooring.</b></p>	<p><b>PENDING_FOR_MATCH</b> Attempt 1 (2 attempts)</p>	<p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Rejected_By_Checker 26-08-2025 11:14</p> 
		<p><b>Attempt 2</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Created</p>

---

<p><b>Is any undulations observed in Door shutter Laminate</b></p>	<p><b>COMPLETED</b> (1 attempt)</p>	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:14</p>
--	---	--

QUESTION	STATUS	ATTEMPT DETAILS
<b>Is the lock and other hardwares fixed properly and working smoothly.</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:14

## **Checklist: Flooring Checklists**

---

QUESTION	STATUS	ATTEMPT DETAILS
<b>Floor tiles no crack, chipped off observed</b>	<b>PENDING_FOR_MATCH</b> Attempt 1  (2 attempts)	<p><b>CHECKER</b></p> <p><b>Jayant Yadav</b></p> <p>Status: Rejected_By_Checker 26-08-2025 11:17</p>  <p>grinder scratches observed on floor tile</p>
		<b>Attempt 2</b>
		<p><b>CHECKER</b></p> <p><b>Jayant Yadav</b></p> <p>Status: Created</p>
<b>Floor ling observed without any leapages/ offsets</b>	<b>COMPLETED</b>  (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b></p> <p><b>Jayant Yadav</b></p> <p>Status: Completed 26-08-2025 11:17</p>

QUESTION	STATUS	ATTEMPT DETAILS
<b>Skirting is fixed properly in line without any offsets</b>	<b>PENDING_FOR_MARKER</b> Attempt 1 (2 attempts)	<b>CHECKER</b> <b>Jayant Yadav</b> Status: Rejected_By_Checker 26-08-2025 11:17 
		<b>Attempt 2</b> <b>CHECKER</b> <b>Jayant Yadav</b> Status: Created

## **Checklist: AL Window Checklists**

---

QUESTION	STATUS	ATTEMPT DETAILS
<b>Aluminium window is working smoothly</b>	<b>COMPLETED</b> (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:19</p>
<b>Anchor fasteners are provided as per drawing</b>	<b>COMPLETED</b> (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:19</p>
<b>The shutter lock is functioning properly</b>	<b>COMPLETED</b> (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:19</p>
<b>No damage or peeling of the coating was observed on the window.</b>	<b>COMPLETED</b> (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:19</p>
<b>The roller is functioning properly during the operation of the sliding shutter.</b>	<b>COMPLETED</b> (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:19</p>

QUESTION	STATUS	ATTEMPT DETAILS
<b>Silicone sealant has been properly filled around the window periphery</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b> <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:19
<b>Gasket is fixed properly, drain caps are provided</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b> <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:19
<b>No cracks/scratches are observed on the window glass</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b> <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:19

## Checklist: Painting Checklists

QUESTION	STATUS	ATTEMPT DETAILS
<b>Internal painting is done up to the mark, No undulations/ patch work is balance</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:20
<b>Ensure the shade variation is not observed in painted walls</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:20
<b>No Cracks observed in walls</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:20

## Checklist: False ceiling Checklists

QUESTION	STATUS	ATTEMPT DETAILS
<b>No Cracks observed in false ceiling</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:21
<b>Cove area facia edges are in line and level and thickness maintained</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:21
<b>Finishing around the lights and sprinkler is done properly</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:21

## Checklist: Electrical Checklists

QUESTION	STATUS	ATTEMPT DETAILS
All switches ,switch plates fixed properly in line and level.	<span>COMPLETED</span> (1 attempt)	<span>Attempt 1</span>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:21
All lights are working properly	<span>COMPLETED</span> (1 attempt)	<span>Attempt 1</span>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:21

## **Checklist: Flooring Checklists**

---

QUESTION	STATUS	ATTEMPT DETAILS
<b>Is the Slope of Toilet flooring ok</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:54
<b>No offsets are observed Flooring, tile joints filling is done properly</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:54
<b>Is the tile cutting is done properly Around nahani trap</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:54
<b>Saddling bracket supports are ok for WC trap of above floor</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:54
<b>The toilet flooring threshold angle has been properly fixed</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:54

QUESTION	STATUS	ATTEMPT DETAILS
<b>Floor tile is not damaged/ Chipped off,</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:54

## **Checklist: Flooring Checklists**

---

QUESTION	STATUS	ATTEMPT DETAILS
<b>Is the Slope of Toilet flooring ok</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:24
<b>No offsets are observed Flooring, tile joints filling is done properly</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:24
<b>Is the tile cutting is done properly Around nahani trap</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:24
<b>Saddling bracket supports are ok for WC trap of above floor</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:24
<b>The toilet flooring threshold angle has been properly fixed</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:24

QUESTION	STATUS	ATTEMPT DETAILS
<b>Floor tile is not damaged/ Chipped off,</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:25

## **Checklist: Dado Checklists**

---

QUESTION	STATUS	ATTEMPT DETAILS
<b>No hollow sound / debonding of tiles is observed</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:57
<b>No cracks observed in Dado tile</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:56
<b>All bird mouth joints are finished properly with emery.</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:56
<b>No dado tiles are chipped off, edges not magaed</b>	<b>PENDING_FOR_MAKER</b> (2 attempts)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Rejected_By_Checker 26-08-2025 11:57  

QUESTION	STATUS	ATTEMPT DETAILS
		<p><b>Attempt 2</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Created</p>
<b>No cracks observed in Ledge wall top marble</b>	<b>COMPLETED</b> (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:56</p>
<b>In Windows &amp; Door Jamb No hollow sound detected; Tiles are properly bonded.</b>	<b>COMPLETED</b> (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:57</p>

## **Checklist: Dado Checklists**

---

QUESTION	STATUS	ATTEMPT DETAILS
<b>No hollow sound / debonding of tiles is observed</b>	<b>PENDING_FOR_CHECKER</b> Attempt 1  (2 attempts)	<p><b>CHECKER</b></p> <p><b>Jayant Yadav</b></p> <p>Status: Rejected_By_Checker 26-08-2025 11:33</p> 
		<b>Attempt 2</b>
		<p><b>CHECKER</b></p> <p><b>Jayant Yadav</b></p> <p>Status: Created</p>
<b>No cracks observed in Dado tile</b>	<b>COMPLETED</b>  (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b></p> <p><b>Jayant Yadav</b></p> <p>Status: Completed 26-08-2025 11:33</p>
<b>All bird mouth joints are finished properly with emery.</b>	<b>COMPLETED</b>  (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b></p> <p><b>Jayant Yadav</b></p> <p>Status: Completed 26-08-2025 11:33</p>

QUESTION	STATUS	ATTEMPT DETAILS
<b>No dado tiles are chipped off, edges not magaed</b>	<b>COMPLETED</b> (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:33</p>
<b>No cracks observed in Ledge wall top marble</b>	<b>PENDING_FOR_CHECKER</b> (2 attempts)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Rejected_By_Checker 26-08-2025 11:33</p> 
		<p><b>Attempt 2</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Created</p>
<b>In Windows &amp; Door Jamb No hollow sound detected; Tiles are properly bonded.</b>	<b>COMPLETED</b> (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:33</p>

## Checklist: Polish Checklists

QUESTION	STATUS	ATTEMPT DETAILS
<b>Door frame polishing is carried out upto the mark</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:57
<b>The polish on the top surface of the shutter is Uniformly applied.</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:57

## Checklist: Polish Checklists

QUESTION	STATUS	ATTEMPT DETAILS
<b>Door frame polishing is carried out upto the mark</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:27
<b>The polish on the top surface of the shutter is Uniformly applied.</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:27

## **Checklist: Carpentry Checklists**

---

QUESTION	STATUS	ATTEMPT DETAILS
<b>All hardwares fixed properly as per the approved drawing and dimensions</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 12:00
<b>Lock slot is cut properly, lock plate, Architrave is fixed properly</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 12:00
<b>Hinges screws are fixed properly, screw heads flushed with plates</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 12:00
<b>Is the 3mm gap is maintained at door frame bottom and sealant is applied</b>	<b>PENDING_FOR_MAKER</b> (2 attempts)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Rejected_By_Checker 26-08-2025 12:00   <p>door frame is fixed below the floor tile gap is not provided</p>

QUESTION	STATUS	ATTEMPT DETAILS
		<p><b>Attempt 2</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Created</p>
<b>Proper and equal gap is maintained between door shutter and flooring.</b>	<b>COMPLETED</b> (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 12:00</p>
<b>Is any undulations observed in Door shutter Laminate</b>	<b>COMPLETED</b> (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 12:00</p>

## **Checklist: Carpentry Checklists**

---

QUESTION	STATUS	ATTEMPT DETAILS
<b>All hardwares fixed properly as per the approved drawing and dimensions</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:37
<b>Lock slot is cut properly, lock plate, Architrave is fixed properly</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:37
<b>Hinges screws are fixed properly, screw heads flushed with plates</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:37
<b>Is the 3mm gap is maintained at door frame bottom and sealant is applied</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:37

QUESTION	STATUS	ATTEMPT DETAILS
<b>Proper and equal gap is maintained between door shutter and flooring.</b>	<b>PENDING_FOR_MAKER</b> Attempt 1  (2 attempts)	<p><b>CHECKER</b></p> <p><b>Jayant Yadav</b></p> <p>Status: Rejected_By_Checker 26-08-2025 11:37</p>  <p>wooden packing in frame bottom</p>
		<b>Attempt 2</b>
		<p><b>CHECKER</b></p> <p><b>Jayant Yadav</b></p> <p>Status: Created</p>
<b>Is any undulations observed in Door shutter Laminate</b>	<b>COMPLETED</b>  (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b></p> <p><b>Jayant Yadav</b></p> <p>Status: Completed 26-08-2025 11:37</p>

## Checklist: False ceiling Chekclists

QUESTION	STATUS	ATTEMPT DETAILS
<p><b>The toilet false ceiling finishing was found to be satisfactory.</b></p>	<p>PENDING_FOR_APPROVAL</p> <p>(2 attempts)</p>	<p><b>CHECKER</b></p> <p><b>Jayant Yadav</b></p> <p>Status: Rejected_By_Checker</p> <p>26-08-2025 12:01</p> 
		<p><b>Attempt 2</b></p> <p><b>CHECKER</b></p> <p><b>Jayant Yadav</b></p> <p>Status: Created</p>
<p><b>The trap door size and finish were observed to be satisfactory.</b></p>	<p>COMPLETED</p> <p>(1 attempt)</p>	<p><b>Attempt 1</b></p> <p><b>CHECKER</b></p> <p><b>Jayant Yadav</b></p> <p>Status: Completed</p> <p>26-08-2025 12:01</p>

## Checklist: False ceiling Checklists

QUESTION	STATUS	ATTEMPT DETAILS
<p><b>The toilet false ceiling finishing was found to be satisfactory.</b></p>	<p>PENDING_FOR_APPROVAL</p> <p>(2 attempts)</p>	<p><b>CHECKER</b></p> <p><b>Jayant Yadav</b></p> <p>Status: Rejected_By_Checker</p> <p>26-08-2025 11:27</p>  <p>False ceiling board crack at corner near door</p>
		<p><b>Attempt 2</b></p> <p><b>CHECKER</b></p> <p><b>Jayant Yadav</b></p> <p>Status: Created</p>
<p><b>The trap door size and finish were observed to be satisfactory.</b></p>	<p>COMPLETED</p> <p>(1 attempt)</p>	<p><b>Attempt 1</b></p> <p><b>CHECKER</b></p> <p><b>Jayant Yadav</b></p> <p>Status: Completed</p> <p>26-08-2025 11:27</p>

## Checklist: Mirror Checklists

QUESTION	STATUS	ATTEMPT DETAILS
<b>The gypsum on the back side wall behind the mirror was observed to have a proper finish</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 12:01
<b>Is the mirror fixed properly</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 12:02

## Checklist: Mirror Checklists

QUESTION	STATUS	ATTEMPT DETAILS
<b>The gypsum on the back side wall behind the mirror was observed to have a proper finish</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:29
<b>Is the mirror fixed properly</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:29

## Checklist: Glass Partition Checklists

QUESTION	STATUS	ATTEMPT DETAILS
<b>Is the glass partition fixed properly and sealant is applied / gasket is provided in gap near wall tile</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 12:02

## Checklist: Glass Partition Checklists

QUESTION	STATUS	ATTEMPT DETAILS
<b>Is the glass partition fixed properly and sealant is applied / gasket is provided in gap near wall tile</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:38

## Checklist: Plumbing Checklists

QUESTION	STATUS	ATTEMPT DETAILS
All CP fitting installed and working properly	<span>COMPLETED</span> (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 12:02</p>
Shower mixer/diverter working properly	<span>COMPLETED</span> (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 12:02</p>
Is the Wash basin bottle trap fixed without any leakage	<span>COMPLETED</span> (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 12:02</p>
All valves are Working properly without any leakage	<span>COMPLETED</span> (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 12:02</p>

## Checklist: Plumbing Checklists

---

QUESTION	STATUS	ATTEMPT DETAILS
All CP fitting installed and working properly	COMPLETED (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:38</p>
Shower mixer/diverter working properly	COMPLETED (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:38</p>
Is the Wash basin bottle trap fixed without any leakage	COMPLETED (1 attempt)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:38</p>
All valves are Working properly without any leakage	PENDING_FOR_MATCHING (2 attempts)	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Rejected_By_Checker 26-08-2025 11:38</p> 

QUESTION	STATUS	ATTEMPT DETAILS
		<p><b>Attempt 2</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Created</p>

## Checklist: Waterproofing Checklists

QUESTION	STATUS	ATTEMPT DETAILS
<b>Any leakages observed in ceiling of toilet</b>	<span style="background-color: #a9f5d0; border-radius: 50%; padding: 2px 5px; font-weight: bold;">COMPLETED</span> <small>(1 attempt)</small>	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 12:02</p>

## Checklist: Waterproofing Checklists

QUESTION	STATUS	ATTEMPT DETAILS
<b>Any leakages observed in ceiling of toilet</b>	<span style="background-color: #a9f5d0; border-radius: 50%; padding: 2px 5px; font-weight: bold;">COMPLETED</span> <small>(1 attempt)</small>	<p><b>Attempt 1</b></p> <p><b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:39</p>

## Checklist: Service Window Checklists

QUESTION	STATUS	ATTEMPT DETAILS
<b>the service duct window closes and locks properly.</b>	<b>PENDING_FOR_APPROVAL</b> (2 attempts)	<b>CHECKER</b> <b>Jayant Yadav</b> Status: Rejected_By_Checker 26-08-2025 12:03  <b>Attempt 2</b> <b>CHECKER</b> <b>Jayant Yadav</b> Status: Created
<b>No Sacrches are observed on froasted glass and windo frame</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b> <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 12:03
<b>Service window sealant is applied from outside</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b> <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 12:03

## Checklist: Service Window Checklists

QUESTION	STATUS	ATTEMPT DETAILS
<b>the service duct window closes and locks properly.</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:39
<b>No Sacrches are observed on froasted glass and windo frame</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:39
<b>Service window sealant is applied from outside</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 11:39

## Checklist: Painting Checklists

QUESTION	STATUS	ATTEMPT DETAILS
<b>All drain pipes and water supply pipes painted as per color codes</b>	PENDING_FOR_CHECKER Attempt 1  (2 attempts)	<b>CHECKER</b> <b>Jayant Yadav</b> Status: Rejected_By_Checker 26-08-2025 12:05 
		<b>Attempt 2</b>  <b>CHECKER</b> <b>Jayant Yadav</b> Status: Created

## Checklist: Painting Checklists

QUESTION	STATUS	ATTEMPT DETAILS
<b>All drain pipes and water supply pipes painted as per color codes</b>	<b>PENDING_FOR_APPROVAL</b> (2 attempts)	<b>CHECKER</b> <b>Jayant Yadav</b> Status: Rejected_By_Checker 26-08-2025 11:35  <p>due to water flows out of Gysen painting is damaged</p>
		<b>Attempt 2</b> <b>CHECKER</b> <b>Jayant Yadav</b> Status: Created

## Checklist: DUCT Checklists

QUESTION	STATUS	ATTEMPT DETAILS
<b>All Plumbing brackets PVC caps are provided.</b>	<b>COMPLETED</b> (1 attempt)	<b>Attempt 1</b> <b>CHECKER</b> <b>Jayant Yadav</b> Status: Completed 26-08-2025 12:05

## Checklist: DUCT Checklists

QUESTION	STATUS	ATTEMPT DETAILS
All Plumbing brackets PVC caps are provided.	PENDING_FOR_CHECKER 1 (2 attempts)	<p><b>CHECKER</b></p> <p><b>Jayant Yadav</b></p> <p>Status: Rejected_By_Checker</p> <p>26-08-2025 11:31</p> 
	Attempt 2	<p><b>CHECKER</b></p> <p><b>Jayant Yadav</b></p> <p>Status: Created</p>