



REPUBLIC OF NAMIBIA
VEHICLE BREAKDOWN RECORD

OFFICE / MINISTRY / DEPARTMENT / MUNICIPALITY
Kavango East Regional Council
Office / Ministry / Department / Municipality
Government Building, Rundu, Namibia
+264 66 123 456 · transport@kavangoeast.gov.na



A. INCIDENT SUMMARY				B. VEHICLE / TRIP		
Type	Vehicle Breakdown	Severity	Medium	Vehicle	GRN-81768 · Toyota	Trip authority TA-2026-KERC-00009
Status	Resolved	Reported by	John Shikongo		Corolla Quest	
C. LOCATION / TIME						
Occurred at	09 August 2026			Location	B8, 18 km east of Rundu	
D. DESCRIPTION						
Description	Vehicle developed an overheating warning during official duty and was stopped safely.					
E. DAMAGE / DEFECTS						
Details	Coolant hose leak identified. No consequential engine damage recorded.			Safe determination	Vehicle safe after technical clearance; all passengers safe.	
F. EVIDENCE						
NO.	EVIDENCE REFERENCE					
1	breakdown-front-view.jpg					
2	coolant-hose-inspection.jpg					
G. RESPONSE / ACTION						
Action taken	Roadside assistance attended; hose replaced and vehicle cleared after inspection.					

H. ACKNOWLEDGEMENT

Anna Nghikembua
Responsible officer
Digitally approved · 2026-08-09T16:30:00+02:00



VERIFICATION CODE
VER-8F34021

VERIFY ONLINE
grnfleet.na/v/TA-2026-457

FINGERPRINT
8f34421b8ce2..31jk10jm
KAVANGO EAST REGIONAL COUNCIL · OFFICIAL DIGITAL RECORD