



PROMACH PTE. LTD.

8 Temasek Boulevard Level 42, Suntec Tower Three, Singapore-038988
Tel: 6829 2136, E-mail: enquiry@promachpl.com, Website: www.promachpl.com
Company UEN / GST No: 202008249W



Customer's Name: _____

Service Report / Delivery Order

Address: _____

CHANGI GENERAL HOSPITAL
LEVEL-1 pharmacy (MB Building)

NO. 4122

Date: 18/07/26

Description:

* LEVEL-2 AHU, precool-1 unit and

Aircleaner - @ Nos

* Monthly Service Completed

Remarks:

This month Service Completed

* precool unit coil choke need to chemical wash

☐ Regular Service

☐ Warranty Service

☐ Complaints

Completed by (1) kabilan

(2) manimuthu

(3) _____

Work completed to our satisfaction

M. J. 18/07/26

Customer's Signature/Date



dun & bradstreet
D-U-N-S NUMBER 659837257
© [2020] Promach Pte Ltd. All Rights Reserved.



PROMACH PTE. LTD.

8 Temasek Boulevard
Level 42, Suntec Tower Three, Singapore-038988.
Tel: 6829 2136. E-mail: enquiry@promachpl.com
Website: www.promachpl.com
Company REG/GST No: 202008249W

Location : Changi General Hospital

Service Month : 18/07/26

LEVEL -1 pharmacy Entrance - 2 unit
Air curtain - Servicing Report - Monthly
Aircurtain - ② Nos
SERIAL NO - ① 25060281
② 25060278

S/No	Description	Check	Remarks
	Fan coil - Indoor Unit	☒ Yes NA	
1	Check Blower Motor in proper function	☒ Yes NA	
2	Wipe down housing exterior to remove dust and grime.	☒ Yes NA	
3	Clean fan blowers thoroughly, ensuring dust removal from blades.	☒ Yes NA	
4	Check fan balance and rotation for smooth operation.	☒ Yes NA	
5	Vacuum and flush the condensate drain line to remove debris or blockages	☒ Yes NA	
6	Test controller functions to verify responsiveness and communication with the air curtain unit.	☒ Yes NA	

Notes (if any):

Aircurtain Running is Normal

Serviced By:

Kabilan / marimuthu

Technician
PROMACH PTE. LTD.

Acknowledged By:

[Signature]

Changi General Hospital
Representative

Changi General Hospital					Air Curtain attached Check List						
S.No	Equipment List	Equipment Brand	Equipment Model	Service Location	1	2	3	4	5	6	Date of Serviced
1	Aircurtain - ①	KDK	3015UA	Pharmacy Entrance	✓	✓	✓	✓	✓	✓	19/7/26
2	Aircurtain - ②	KDK	3015UA	"	✓	✓	✓	✓	✓	✓	18/7/26
3											
4											
5											
6											
7											
8											
9											
10											
11											
12											
13											
14											
15											

K. Subileem / Navimurthu
Serviced by promach

N. S. Paul
User / Tenant Sign



PROMACH PTE. LTD.

8 Temasek Boulevard
Level 42, Suntec Tower Three, Singapore-038988.
Tel: 6829 2136. E-mail: enquiry@promachpl.com
Website: www.promachpl.com
Company REG/GST No: 202008249W

Location

: Changi General Hospital

Service Month :

July [18/07/26]

LEVEL: 2 AHU

Air Handling Unit - Service Report - Monthly

S/No	Description	Check		Remarks
1	Check filter manometer & replace filter if necessary	☒ Yes	NA	
2	Change air filter, filter frames & AHU frame slot	☒ Yes	NA	
3	Flushing cooling coil with water & comb dented fins	☒ Yes	NA	
4	Clean fan motor, impeller, fan scroll & blower blade	☒ Yes	NA	
5	Check and ensure the chilled water Actuator Function	☒ Yes	NA	
6	Clean dust off from AHU housing, Piping & ducts	☒ Yes	NA	
7	Carry out housing keeping works within the surrounding of the ahu room	☒ Yes	NA	
8	Lubricate fan & motor bearing clean of the grime & hardened grease from the housings.	☒ Yes	NA	
9	Record the running current for the motor (3 Monthly) R: <u>5.3</u> amps Y: <u>5.5</u> amps B: <u>5.2</u> amps			
10	Record the megger for the motor (3 monthly) R: <u>5.1</u> ohms Y: <u>5.6</u> ohms B: <u>5.2</u> ohms			

Notes (if any):

AHU Running is Normal

Serviced By:

Kabilan / Marimuthu
Technician
PROMACH PTE. LTD.

Acknowledged By:

[Signature]
Changi General Hospital
Representative

Changi General Hospital					Air Handling Unit attached Check List								Date of Serviced
S.No	Equipment List	Equipment Brand	Equipment Model	Service Location	1	2	3	4	5	6	7	8	
1	AHU-L2-1-10	Daikin	DMP2TB-1421B	LEVEL-2	✓	✓	✓	✓	✓	✓	✓	✓	18/07/2026
2													
3													
4													
5													
6													
7													
8													
9													
10													
11													
12													
13													
14													
15													

Kabilan / moorimudra

Serviced by promach

M. S. S.

Used Tenant Sign



PROMACH PTE. LTD.

8 Temasek Boulevard
Level 42, Suntec Tower Three, Singapore-038988.
Tel: 6829 2136. E-mail: enquiry@promachpl.com
Website: www.promachpl.com
Company REG/GST No: 202008249W

Location : Changi General Hospital

Service Month : 18/07/26 [July]

Level: 2 AHU Room inside

Pre - cool Unit - Servicing Report - Monthly

S/No	Description	Check		Remarks
1	Wash filters media, filter frames and clean filter slot	☒ Yes	NA	
2	Check the coil face and comb the coil fins if necessary	☒ Yes	NA	
3	Check & clean the blowers	☒ Yes	NA	
4	Check for abnormal noises while the unit is running	☒ Yes	NA	
5	Clean condensate tray & remove any sludge / jelly in the tray. Replace the anti fungi tablet in drain pans	☒ Yes	NA	
6	Vacuum & clean the condensate drain line	☒ Yes	NA	
7	Check & record the off coil temperature _____ °C	☒ Yes	NA	
8	Check the thermostat settings	☒ Yes	NA	

Notes (if any):

Coil dirty Need to chemical wash

Serviced By:

Kabilan/Maximurthi
Technician
PROMACH PTE. LTD.

Acknowledged By:

[Signature]
Changi General Hospital
Representative

Changi General Hospital					Air Handling Unit attached Check List								Date of Serviced
S.No	Equipment List	Equipment Brand	Equipment Model	Service Location	1	2	3	4	5	6	7	8	
1	PFCU-L2-3-1	DAIKIN	e1000	LEVEL-2 PFCU-L2-3-1	✓	✓	✓	✓	✓	✓	✓	✓	18/07/26
2													
3													
4													
5													
6													
7													
8													
9													
10													
11													
12													
13													
14													
15													

Kabilan / Mponi muthu
 Serviced by promach


 User/Tenant Sign



PROMACH PTE. LTD.

8 Temasek Boulevard
Level 42, Suntec Tower Three, Singapore-038988.
Tel: 6829 2136. E-mail: enquiry@promachpl.com
Website: www.promachpl.com
Company REG/GST No: 202008249W

Location : Changi General Hospital

Service Month : July [18/07/26]

Level: 1 Pharmacy Exit Near

Air curtain - Servicing Report - Monthly

Aircurtain - 2 Nos

SERIAL NO : 3 → 25060277

4 → 25060278

S/No	Description	Check	Remarks
	<u>Fan coil - Indoor Unit</u>	☒ Yes NA	
1	Check Blower Motor in proper function	☒ Yes NA	
2	Wipe down housing exterior to remove dust and grime.	☒ Yes NA	
3	Clean fan blowers thoroughly, ensuring dust removal from blades.	☒ Yes NA	
4	Check fan balance and rotation for smooth operation.	☒ Yes NA	
5	Vacuum and flush the condensate drain line to remove debris or blockages	☒ Yes NA	
6	Test controller functions to verify responsiveness and communication with the air curtain unit.	☒ Yes NA	

Notes (if any):

Aircurtain Running is Normal

Serviced By:

Kabilan / Mari Mathan

Technician
PROMACH PTE. LTD.

Acknowledged By:

[Signature]

Changi General Hospital
Representative

Changi General Hospital					Air Curtain attached Check List						Date of Serviced
S.No	Equipment List	Equipment Brand	Equipment Model	Service Location	1	2	3	4	5	6	
1	Aircurtain - ③	KDK	3015 UA	Pharmacy Exit Near	✓	✓	✓	✓	✓	✓	18/07/2026
2	Aircurtain - ④	KDK	3015 UA	Pharmacy Exit Near	✓	✓	✓	✓	✓	✓	18/07/2026
3											
4											
5											
6											
7											
8											
9											
10											
11											
12											
13											
14											
15											

Kabilan / Mani.muthu
Served by promach

M. S. S.
User / Tenant Sign