

Equipment Inspection Report

Report number	INS-2026-0851
Equipment tag	P-101-B
Equipment description	Centrifugal pump, crude charge, motor driven (standby)
Unit / area	CDU-1, Pump House B
Service	Crude oil, 62 °C, standby
Inspection date	29 August 2026
Inspector	R. Nair, Inspection Engineer
Procedure reference	SOP-PMP-114 Rev. 4

1. Measured values

Parameter	Measured	Instrument
Casing wall thickness (minimum)	6.2 mm	UT gauge CM-114
Bearing vibration, drive end	2.1 mm/s RMS	Vib analyser VA-07
Bearing vibration, non-drive end	1.8 mm/s RMS	Vib analyser VA-07
Bearing housing temperature	61 °C	IR thermometer IR-22
Discharge pressure	18.6 bar, stable $\pm$ 0.1 bar	PI-1015 / panel trend
Motor current	stable $\pm$ 1 %	Panel trend
Suction strainer differential	0.18 bar	PDI-1010
Mechanical seal	No visible leakage	Visual

2. Observations

- 2.1 No abnormal noise detected during the inspection period.
- 2.2 Discharge pressure and motor current both stable over a ten minute observation.
- 2.3 External surfaces in good condition. Paint intact. No visible corrosion.
- 2.4 Coupling guard complete and correctly fastened.
- 2.5 Lubrication log signed 18 August 2026. Quarterly verification current.

3. Inspector remarks

All measured parameters within the acceptable range stated in the governing procedure. No deviations recorded. Equipment fit for continued standby service.