



# Run Sheet

## John Paul Barron 22/03/2025

<b>Date</b>	22/03/2025	<b>Depot</b>	Warrington	<b>Driver</b>	Barron, John Paul	<b>Jobs on Run</b>	6
-------------	------------	--------------	------------	---------------	-------------------	--------------------	---

Job # 4120916	Customer	Vista Retail Support Limited		Job Address
SLA Window	21/03/2025 09:00 - 22/03/2025 17:00	Contact Name	.	MCDONALDS - CAPGEMINI THE RIVERSIDE RETAIL PARK WHARF STREET, CUERDLEY WARRINGTON LANCASHIRE WARRINGTON WA1 2GZ
Activity	NON TECH EXCHANGE	Contact Phone	.	
Priority	ND 1700			
Ref 1	3229168			
Ref 2				
No. of Parts	1			

Instructions 1	Instructions 2
3229168 Spare Sticky printer not cutting receipts    Swap out required Monday-Sunday 7am-11pm	***BACK DOOR SWAP ONLY*** MCD-PTR-LAB3-KIT Till No: Please record serial and Asset in and out without fail on every single call including unused parts(RE DOA). Asset tags can be found in small package attached to the box. Call your depot if there is no asset tag. Please complete the call closure field with what action was taken on site. Call closure must take place real time before you leave site. If this is not possible on your PDA call the details into your depot or call the CSC.

## Job Notes

For more information about the study, please contact Dr. [REDACTED] at [REDACTED].

## In Items

Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?
18984562101	MCD-PTR-LAB3-	MCD-PTR-LAB3-KIT				

## Returned Items

Request	Part	Description	Serial	Asset	Part Status	Customer Damage?
18984562301						

Engineer Closure Notes	On Site Time	Off Site Time
<b>Customer Print</b>		
<b>Customer Signature</b>		



# Run Sheet

John Paul Barron 22/03/2025

Date	22/03/2025	Depot	Warrington	Driver	Barron, John Paul	Jobs on Run	6
------	------------	-------	------------	--------	-------------------	-------------	---

Job # 4120861	Customer	Xerox (UK) Technical***DO NOT INVOICE***		Job Address
SLA Window	22/03/2025 09:00 - 22/03/2025 12:00	Contact Name	Stephen Brisco Manager	Everything Everywhere Limited Westmorland Shopping Centre, Unit 12 Westmorland Shopping Centre IP 10.19.107.50 KENDAL LA9 4LR
Activity	REPAIR WITH PARTS	Contact Phone	01252339290	
Priority	4HR			
Ref 1	11644190			
Ref 2				
No. of Parts	3			

Instructions 1	Instructions 2
<p>Intervention #: 1 SLA: 21/03/2025 15:39-----ASSET INFORMATION---ProductName: COLOR MFP CX510de Color MFP HV 7527-63DeviceTagCustomer: SerialNumber: 752723946VT2GProductIdentifier: 38C5022Model: 7527-636Physical Location:</p> <p>---ACCOUNT INFORMATION---MPS ACCOUNTMonday to Saturday 09:00 to 17:00 &amp; Sunday 10:00 to 16:00. Including public holidays Christmas Day excludedSERVICE PARTNER HOLDS BONDED GOLD STOCK OF DEVICES IF REQUIREDENGINEER TO RECORD PAGE COUNTOutput Device Qty SLAE460dn - A4 Mono MFP 951 NBD FixX548de - A4 Colour MFP 395 4 Hr FixC544dn - A4 Colour 274 NBD FixCX510de - A4 Colour MFP 49 4 Hr FixMS510dn - A4 Mono 37 NBD Fix</p>	<p>-----ACTIVITY DESCRIPTION----Help Desk Reference INC17254697. 200.03 Paper Jams. Talked Stephen through cleaning the pick rollers. All guides in the tray are set correctly. Contact Stephen Brisco on 01539 797470. IP 10.19.107.50. SLA Expires 21/03 15:39.----INSTRUCTIONS-----Technical Notes -----Tech to investigate pick / feed issues from tray 1.CB.</p>

Job Notes

In Items						
Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?
189843190	40X5168	C54x SVC Pick Arm Roll				
189843183	40X7614	CS31x SVC Pick Paper Pick Asse				
189843187	40X7645	CS31x SVC Tray Insert Primary				



# Run Sheet

John Paul Barron 22/03/2025

Date	22/03/2025	Depot	Warrington	Driver	Barron, John Paul	Jobs on Run	6
------	------------	-------	------------	--------	-------------------	-------------	---

Job # 4120746	Customer	Paypoint Network Limited - UK		Job Address
SLA Window	21/03/2025 14:34 - 22/03/2025 13:00	Contact Name	MANAGER	LIVESEY SUPERSTORE LIVESEY SUPERSTORE 170-172 LIVESEY BRANCH
Activity	TECH EXCHANGE	Contact Phone	07305162786	ROAD BLACKBURN BB2 4QR
Priority	4HR			
Ref 1	02237819			
Ref 2				
No. of Parts	0			

Instructions 1	Instructions 2
34036344//31126284//T3	Swap reason: Printer Fault

Job Notes

#### In Items

Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?

Returned Items

Engineer Closure Notes	On Site Time	Off Site Time
Customer Print		
Customer Signature		



# Run Sheet

## John Paul Barron 22/03/2025

<b>Date</b>	22/03/2025	<b>Depot</b>	Warrington	<b>Driver</b>	Barron, John Paul	<b>Jobs on Run</b>	6
-------------	------------	--------------	------------	---------------	-------------------	--------------------	---

<b>Job #</b> 4120745	<b>Customer</b>	Vista Retail Support Limited		<b>Job Address</b>
<b>SLA Window</b>	21/03/2025 14:32 - 22/03/2025 17:00	<b>Contact Name</b>		WHITBREAD RIVERSWAY DRIVE LANCASHIRE BLACKBURN BB3 0SN
<b>Activity</b>	TECH EXCHANGE	<b>Contact Phone</b>		
<b>Priority</b>	ND 1700			
<b>Ref 1</b>	3228681			
<b>Ref 2</b>				
<b>No. of Parts</b>	1			

Instructions 1	Instructions 2
3228681- Cash drawer on till 2 is physically broken	Replace WHIT-CDR-CBS-0822 Till No: Please record serial and Asset in and out without fail on every single call including unused parts(RE DOA). Asset tags can be found in small package attached to the box. Call your depot if there is no asset tag. Please complete the call closure field with what action was taken on site. Call closure must take place real time before you leave site. If this is not possible on your PDA call the details into your depot or call the CSC.

## Job Notes

## In Items

Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?
18983996301	WHIT-CDR-CBS-0821	IT-CDR-CBS-0822				

## Returned Items

Request	Part	Description	Serial	Asset	Part Status	Customer Damage?
18983996601						

Engineer Closure Notes

<b>Customer Print</b>	
<b>Customer Signature</b>	



# Run Sheet

John Paul Barron 22/03/2025

Date	22/03/2025	Depot	Warrington	Driver	Barron, John Paul	Jobs on Run	6
------	------------	-------	------------	--------	-------------------	-------------	---

Job # 4120953	Customer	Computacenter - Kingfisher			Job Address
SLA Window	22/03/2025 09:00 - 22/03/2025 17:00	<b>Contact Name</b>		Rebecca Driscoll	KINGFISHER INFORMATION TECHNOLOGY (
Activity	TECH EXCHANGE	<b>Contact Phone</b>		01695 577412	Units 4-6, Hattersley Centre, Hattersley Way.
Priority	ND 1700				Units 4-6, Hattersley Centre, Hattersley Way.
Ref 1	24291911				L39 2AN
Ref 2					
No. of Parts	1				

Instructions 1	Instructions 2
Description: HOST NAME: KF8CG8140ZX9 IP ADDRESS OF PC: IP incorrect e correct one is 10.69.6.104 PED Model: PEDVX820 DUET OPERATING SYST: win10 MANAGER OR TILL: TIII TILL NO: TIII04 CONTACT NAME/CONTACT	No Instructions

Job Notes

In Items

Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?
18984349501	4222593	KING:HP EliteDesk 800 G3 Mini				

Returned Items

Request	Part	Description	Serial	Asset	Part Status	Customer Damage?
18984349701	4222593	KING:HP EliteDesk 800 G3 Mini				

Engineer Closure Notes	On Site Time	Off Site Time
Customer Print		
Customer Signature		



# Run Sheet

John Paul Barron 22/03/2025

Date	22/03/2025	Depot	Warrington	Driver	Barron, John Paul	Jobs on Run	6
------	------------	-------	------------	--------	-------------------	-------------	---

Job # 4120636	Customer	Vista Retail Support Limited		Job Address
SLA Window	21/03/2025 13:25 - 22/03/2025 17:00	Contact Name		SUPERDRUG STORES PLC UNIT 6, PARSONAGE RETAIL PARK LEIGH WN7 5SJ
Activity	TECH EXCHANGE	Contact Phone		
Priority	ND 1700			
Ref 1	3215542			
Ref 2				
No. of Parts	1			

Instructions 1	Instructions 2
3215542- HHT screen unresponsive. Soft rebooted battery swapped - no joy. Please replace TC51 S/N: 18067522502402 SUP-SCN-HHT-ZEB-TC51  3107985 - HHT Scanner not scanning. Please attend site with replacement TC52	Replace SUP-SCN-HHT-ZEB-TC51 Till No: Please record serial and Asset in and out without fail on every single call including unused parts(REF DOA). Asset tags can be found in small package attached to the box. Call your depot if there is no asset tag. Please complete the call closure field with what action was taken on site. Call closure must take place real time before you leave site. If this is not possible on your PDA call the details into your depot or call the CSC.

Job Notes

In Items						
Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?
18983563301	SUP-SCN-HHT-ZEB-TC51					

Returned Items						
Request	Part	Description	Serial	Asset	Part Status	Customer Damage?
18983563501						

Engineer Closure Notes					On Site Time	Off Site Time
					Customer Print	
					Customer Signature	



# Run Sheet

## Daniel Hanson 22/03/2025

**Date** 22/03/2025 **Depot** Warrington **Driver** Hanson, Daniel **Jobs on Run** 12

Job # 4120870	Customer	Paypoint Network Limited - UK		Job Address
SLA Window	21/03/2025 15:51 - 22/03/2025 13:00	Contact Name	JAMIE	SPAR STORES SPAR STORES STATION ROAD VALLEY HOLYHEAD LL65 3EB
Activity	TECH EXCHANGE	Contact Phone	01407740320	
Priority	4HR			
Ref 1	02236450			
Ref 2				
No. of Parts	2			

Instructions 1	Instructions 2
v200000000000//33095//Sunmi	<p>Pictures of damaged device as requested</p> <p>Whether the cable is inserted into the dock or straight into the terminal both have a loose connection</p> <p>we have tried various cables to eliminate that as the issue. When wiggling the cable enough it will find a point where we are able to charge the device but if knocked even slightly it can stop the charge. The crack across the screen is also making the application unresponsive at certain button presses.</p> <p>Anything you can do to resolve these issues would be gratefully appreciated</p> <p>Kind Regards</p> <p>Jamie (Store Manager)</p> <p>SPAR 602 Valley Station Road Valley Anglesey LL65 3EB 01407 740 320 Acc 17430 Drop 117</p>

## Job Notes

In Items						
Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?
18984412702	Sumni V2 Pro Cradle	Sumni V2 Pro Cradles	NF04219R02245			
18984412701	Sumni V2 Pro Device	Sumni V2 Pro Device	V264217G20405			

## Returned Items

Request	Part	Description	Serial	Asset	Part Status	Customer Damage?

Engineer Closure Notes	On Site Time	Off Site Time
<b>Customer Print</b>		
<b>Customer Signature</b>		



# Run Sheet

Daniel Hanson 22/03/2025

Date	22/03/2025	Depot	Warrington	Driver	Hanson, Daniel	Jobs on Run	12
------	------------	-------	------------	--------	----------------	-------------	----

Job # 4120957	Customer	Paypoint Network Limited - UK		Job Address
SLA Window	21/03/2025 16:33 - 22/03/2025 13:00	Contact Name	MANAGER	CYBI NEWS CYBI NEWS 36 THOMAS STREET HOLYHEAD LL65 1RS
Activity	TECH EXCHANGE	Contact Phone	07732201966	
Priority	4HR			
Ref 1	02237967			
Ref 2				
No. of Parts	0			

Instructions 1	Instructions 2
34049107//31185742//T3	Swap reason: Network/Comms Fault

Job Notes

#### In Items

Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?

Returned Items

Engineer Closure Notes	On Site Time	Off Site Time
Customer Print		
Customer Signature		



# Run Sheet

Daniel Hanson 22/03/2025

Date	22/03/2025	Depot	Warrington	Driver	Hanson, Daniel	Jobs on Run	12
------	------------	-------	------------	--------	----------------	-------------	----

Job # 4120803	Customer	Fujitsu Services Limited - Star Trains - P2PE			Job Address
SLA Window	21/03/2025 15:08 - 22/03/2025 18:00	Contact Name	LLANDUDNO JUNCTION NLC2485 TFW STA	TRANSPORT FOR WALES	Conway Road GWYNEDD LLANDUDNO LL31 9NB
Activity	TECH EXCHANGE	Contact Phone	02920 320178		
Priority	ND 1800				
Ref 1	C5306726				
Ref 2					
No. of Parts	2				

Instructions 1	Instructions 2
Previous DOA - Device swapped and new asset tag updated with Star. However device would not pair. Kept getting error message connection failed. It started connected to Bluetooth but didn't get any further. Tried removing and retrying a few times and several reboots but no joy. Libby at Star couldn't offer any other solution and told me to DOA and they will rebook. New device left on site at her request. P2pe followed as usual ND 21/03/2025 20:00 SLA: ND 21/03/2025 20:00 PART2=_SXASSET-LABELSV2 PART3= PART4= ALT1= ALT2= ALT3= ALT4= TEXT= _TWMIUM020DEVICE x 1 _SXASSET-LABELSV2 x 1	Problem: [P2PE] Miura M020 PED faulty Root Cause: Unknown Action: Engineer MUST follow the P2PE process. Device MUST be paired before leaving site.**WHOLE PED MUST BE REPLACED**. Contact STAR Service Desk for assistance. Test: In Use URL: Call history: ##### Call 5306726   Problem   Web Service   qws_uk   Thu 20 Mar 2025 07:35:34   A+C+P  agent.loginname=qws_uk equipment.assettag=STRGB00000AT027TA23 contract.pkey=23200 call.poms=1 call.zip=LL31 9NB call.address=Conway Road call.customerid=INC17246920 call.problem=NLC2485 LLANDUDNO JUNCTION 020-112828 PED - Blank screen NLC 2485 Site LLAND call.modifiedby=QWebServices call.busimpact=Urgent (TD) category.name=GBR/STR/workpackage/TWMIUM020PED call.priority=2-Medium call.datereported=3/20/2025 8:34:59 AM  ##### Call 5306726   Problem   Web Service   qws_uk   Thu 20 Mar 2025 07:35:34   A+C+P  NLC2485...

Job Notes

In Items

Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?
18984208601	_TWMIUM020DE	M2P:M020 TFW MOBILE LIVE	02000303002020	106851		
18984209301	_SXASSET-LABEL	_SXASSET-LABELSV2				

Returned Items

Request	Part	Description	Serial	Asset	Part Status	Customer Damage?
18984208801	_TWMIUM020DE	M2P:M020 TFW MOBILE LIVE	02000303002020	106851		
18984209501	_SXASSET-LABEL	_SXASSET-LABELSV2				

Engineer Closure Notes	On Site Time	Off Site Time
Customer Print		
Customer Signature		



# Run Sheet

Daniel Hanson 22/03/2025

Date	22/03/2025	Depot	Warrington	Driver	Hanson, Daniel	Jobs on Run	12
------	------------	-------	------------	--------	----------------	-------------	----

Job # 4121048	Customer	Computacenter - Kingfisher			Job Address
SLA Window	22/03/2025 09:00 - 22/03/2025 17:00	Contact Name	Matthew Cash-Francis		KINGFISHER INFORMATION TECHNOLOGY (
Activity	TECH EXCHANGE	Contact Phone	+44 1745 343331		Rhyl Trade Park, Ffordd Derwen, Rhyl Trade Park, Ffordd Derwen, LL18 2AZ
Priority	ND 1700				
Ref 1	24292021				
Ref 2					
No. of Parts	1				

Instructions 1	Instructions 2
Till Number: 3 IP ADDRESS OF PC: 10.66.248.103 Description: HOST NAM KF4CE9211L6R **Model at site is HP Z2 Mini G4 Workstation** CONTACTME/CONTACT NUMBER: Matthew Cash-Francis // +44 1745 343331	No Instructions

Job Notes

Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?
18984799601	4222594	KING:HP EliteDesk Z2 MiniG4 En				



# Run Sheet

Daniel Hanson 22/03/2025

Date	22/03/2025	Depot	Warrington	Driver	Hanson, Daniel	Jobs on Run	12
------	------------	-------	------------	--------	----------------	-------------	----

Job # 4120865	Customer	Vista Retail Support Limited		Job Address
SLA Window	21/03/2025 15:40 - 22/03/2025 17:00	Contact Name		SUPERDRUG STORES PLC UNIT 3A, 2 BROUGHTON SHOPPING PARK CHESTER ROAD BROUGHTON CH4 0DP
Activity	TECH EXCHANGE	Contact Phone		
Priority	ND 1700			
Ref 1	3228923			
Ref 2				
No. of Parts	1			

Instructions 1	Instructions 2
<p>3228923 POS 99 Cashier side screen keeps flickering on and off when moved. checked for a loose connection but can't see one. Please replace ASW-MON-WIN-BA92 and cable ASW-CAB-WIN-BA92</p> <p>Monday 9?am?8?pm Tuesday 9?am?8?pm Wednesday 9?am?8?pm Thursday 9?am?8?pm Friday 9?am?8?pm Saturday 9?am?6:30?pm Sunday 11?am?5?pm</p>	<p>Replace ASW-MON-WIN-BA92 Till No: Please record serial and Asset in and out without fail on every single call including unused parts(RE DOA). Asset tags can be found in small package attached to the box. Call your depot if there is no asset tag. Please complete the call closure field with what action was taken on site. Call closure must take place real time before you leave site. If this is not possible on your PDA call the details into your depot or call the CSC.</p>

Job Notes

In Items						
Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?
18984336601	ASW-MON-WIN-BR02S	BA92 monitor PC-touch Blac				

Returned Items						
Request	Part	Description	Serial	Asset	Part Status	Customer Damage?
18984336901						



# Run Sheet

Daniel Hanson 22/03/2025

<b>Date</b>	22/03/2025	<b>Depot</b>	Warrington	<b>Driver</b>	Hanson, Daniel	<b>Jobs on Run</b>	12
-------------	------------	--------------	------------	---------------	----------------	--------------------	----

<b>Job #</b> 4120738	<b>Customer</b>	Vista Retail Support Limited		<b>Job Address</b>
<b>SLA Window</b>	21/03/2025 14:26 - 22/03/2025 17:00	<b>Contact Name</b>		SUPERDRUG STORES PLC UNIT B-C, 36 REGENT STREET WREXHAM LL11 1SA
<b>Activity</b>	TECH EXCHANGE	<b>Contact Phone</b>		
<b>Priority</b>	ND 1700			
<b>Ref 1</b>	3228664			
<b>Ref 2</b>				
<b>No. of Parts</b>	1			

Instructions 1	Instructions 2
<p>3228664- Cash Drawer Faulty on POS 3. Please replace Cash Drawer. SUP-CDR-FT-460MOD03</p> <p>Monday - Saturday 9:00 a.m. ? 5:30 p.m. Sunday 10:00 a.m. ? 4:00 p.m / Pharmacy closed Sunday</p>	<p>Replace SUP-CDR-FT-460MOD03 Till No: Please record serial and Asset in and out without fail on every single call including unused parts(RE DOA). Asset tags can be found in small package attached to the box. Call your depot if there is no asset tag. Please complete the call closure field with what action was taken on site. Call closure must take place real time before you leave site. If this is not possible on your PDA call the details into your depot or call the CSC.</p>

## **Job Notes**

In Items						
Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?
18983956301	SUP-CDR-FT-460	SUP-CDR-FT-460MOD03				

## Returned Items

Request	Part	Description	Serial	Asset	Part Status	Customer Damage?
18983956501						

Engineer Closure Notes	On Site Time	Off Site Time
<b>Customer Print</b>		
<b>Customer Signature</b>		



# Run Sheet

Daniel Hanson 22/03/2025

**Date** 22/03/2025 **Depot** Warrington **Driver** Hanson, Daniel **Jobs on Run** 12

Job # 4120262	Customer	Fujitsu Services Limited - Star Trains		Job Address
SLA Window	21/03/2025 05:28 - 22/03/2025 19:00	Contact Name	ROCK FERRY NLC2189 MER STATION	MERSEYRAIL Bedford Road MERSEYSIDE Birkenhead CH42 2AT
Activity	TECH EXCHANGE	Contact Phone	0151 955 2454	
Priority	ND 1900			
Ref 1	C5306844			
Ref 2				
No. of Parts	1			

Instructions 1	Instructions 2
<p>ND 22/03/2025 19:00  SLA: ND 22/03/2025 19:00 PART2=  PART3=  PART4=  ALT1=_SXNEWND4020MK2  ALT2=  ALT3=  ALT4= TEXT=  _MYNEWND4020MK2 x 1</p>	<p>Problem: [TC] Newbury ND4020 Mark II Required Root Cause: Unknown Action: Engineer to replace the faulty Newbury Data printer at depot. Please record serial numbers in &amp; out.  Test: N/A Depot swap URL:  Call history::  ##### Call 5306844   Problem   Web Service   qws_uk   Fri 21 Mar 2025 05:28:06    A+C+P</p> <p>agent.loginname=qws_uk  equipment.assettag=STRGB000000M4014TRD3  contract.pkey=23200  call.poms=1  call.zip=CH42 2AT  call.address=Bedford Road  call.city=Birkenhead  call.customerid=INC17252828  call.problem=ROCK FERRY NLC2189 ; Subject: Faulty Newbury Printer ; Serial Number 38742  call.modifiedby=QWebServices  call.busimpact=Urgent (TD)  category.name=GBR/STR/workpackage/MEND4020MK2  call.priority=2-Medium  call.datereported=3/21/2025 6:27:30 AM</p> <p>##### Call 5306844   Problem   Web Service   qws_uk   Fri 21 Mar 2025 05:28:06    A+C+P</p> <p>From: John Patten &lt;JPatten@MERSEYRAIL.org&gt;  Sent: Friday...</p>

## Job Notes

## In Items

Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?
18981404501	_MYNEWND4020	MKR:ND4020 MK2:WHITE:MER:RICO	40541			

## Returned Items

Request	Part	Description	Serial	Asset	Part Status	Customer Damage?
18981404701	_MYNEWND4020	MK2:ND4020 MK2:WHITE:MER:RICO	40541			

Engineer Closure Notes

<b>Customer Print</b>	
<b>Customer Signature</b>	



# Run Sheet

Daniel Hanson 22/03/2025

<b>Date</b>	22/03/2025	<b>Depot</b>	Warrington	<b>Driver</b>	Hanson, Daniel	<b>Jobs on Run</b>	12
-------------	------------	--------------	------------	---------------	----------------	--------------------	----

Job # 4120891	Customer	Vista Retail Support Limited	Job Address
SLA Window	21/03/2025 16:02 - 22/03/2025 17:00	Contact Name	
Activity	TECH EXCHANGE	Contact Phone	
Priority	ND 1700		
Ref 1	3229165		
Ref 2			
No. of Parts	1		

Instructions 1	Instructions 2
<p>3229167/3229166/3229165: POS1/POS2 /POS3 printer printing faded. Thermal head cleaned - no joy. Please replace printer and test with store. ASW-PTR-WIN-TH250</p>	<p>Replace ASW-PTR-WIN-TH250 Till No: Please record serial and Asset in and out without fail on every single call including unused parts(RE DOA). Asset tags can be found in small package attached to the box. Call your depot if there is no asset tag. Please complete the call closure field with what action was taken on site. Call closure must take place real time before you leave site. If this is not possible on your PDA call the details into your depot or call the CSC.</p>

## Job Notes

## In Items

Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?
18984500001	ASW-PTR-WIN-T	H250cor TH250 Black USB				

## Returned Items

Request	Part	Description	Serial	Asset	Part Status	Customer Damage?
18984500201						

---

Engineer Closure Notes

Engineer Signature	On Site Time	On Site Time
Customer Print		
Customer Signature		



# Run Sheet

Daniel Hanson 22/03/2025

Date	22/03/2025	Depot	Warrington	Driver	Hanson, Daniel	Jobs on Run	12
------	------------	-------	------------	--------	----------------	-------------	----

Job # 4120893	Customer	Vista Retail Support Limited		Job Address
SLA Window	21/03/2025 16:02 - 22/03/2025 17:00	Contact Name		SAVERS 3 PRINCES PAVEMENT, THE GRANGE SHOPPING CENTRE BIRKENHEAD CH41 2XY
Activity	TECH EXCHANGE	Contact Phone		
Priority	ND 1700			
Ref 1	3229167			
Ref 2				
No. of Parts	1			

Instructions 1	Instructions 2
3229167/3229166/3229165: POS1/POS2 /POS3 printer printing faded. Thermal head cleaned - no joy. Please replace printer and test with store. ASW-PTR-WIN-TH250	Replace ASW-PTR-WIN-TH250 Till No: Please record serial and Asset in and out without fail on every single call including unused parts(RE DOA). Asset tags can be found in small package attached to the box. Call your depot if there is no asset tag. Please complete the call closure field with what action was taken on site. Call closure must take place real time before you leave site. If this is not possible on your PDA call the details into your depot or call the CSC.

Job Notes

In Items

Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?
18984503901	ASW-PTR-WIN-TH250	cor TH250 Black USB				

Returned Items					
Request	Part	Description	Serial	Asset	Part Status
18984504101					

Engineer Closure Notes				On Site Time	Off Site Time
				Customer Print	
				Customer Signature	



# Run Sheet

Daniel Hanson 22/03/2025

**Date** 22/03/2025 **Depot** Warrington **Driver** Hanson, Daniel **Jobs on Run** 12

Job # 4120894	Customer	Vista Retail Support Limited		Job Address
SLA Window	21/03/2025 16:02 - 22/03/2025 17:00	Contact Name		SAVERS 3 PRINCES PAVEMENT, THE GRANGE SHOPPING CENTRE BIRKENHEAD CH41 2XY
Activity	TECH EXCHANGE	Contact Phone		
Priority	ND 1700			
Ref 1	3229166			
Ref 2				
No. of Parts	1			

Instructions 1	Instructions 2
<p>3229167/3229166/3229165: POS1/POS2 /POS3 printer printing faded. Thermal head cleaned - no joy. Please replace printer and test with store. ASW-PTR-WIN-TH250</p>	<p>Replace ASW-PTR-WIN-TH250 Till No: Please record serial and Asset in and out without fail on every single call including unused parts(RE DOA). Asset tags can be found in small package attached to the box. Call your depot if there is no asset tag. Please complete the call closure field with what action was taken on site. Call closure must take place real time before you leave site. If this is not possible on your PDA call the details into your depot or call the CSC.</p>

## Job Notes

## In Items

Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?
18984501501	ASW-PTR-WIN-T	H250cor TH250 Black USB				

## Returned Items

Request	Part	Description	Serial	Asset	Part Status	Customer Damage?
18984501801						

---

Engineer Closure Notes

Engineer Signature	On Site Time	On Site Time
Customer Print		
Customer Signature		



# Run Sheet

## Daniel Hanson 22/03/2025

<b>Date</b>	22/03/2025	<b>Depot</b>	Warrington	<b>Driver</b>	Hanson, Daniel	<b>Jobs on Run</b>	12
-------------	------------	--------------	------------	---------------	----------------	--------------------	----

<b>Job #</b> 4120618	<b>Customer</b>	Fujitsu Services Limited - EE		<b>Job Address</b>
<b>SLA Window</b>	21/03/2025 13:14 - 22/03/2025 17:30	<b>Contact Name</b>	R896 BIRKENHEAD (Connected)	ORANGE (BIRKENHEAD) Unit 28, The Pyramid Shopping Centre, Grange Road MERSEYSIDE Birkenhead CH41 2ZL
<b>Activity</b>	NON TECH EXCHANGE	<b>Contact Phone</b>	0845 0971 896	
<b>Priority</b>	ND 1700			
<b>Ref 1</b>	C5306889			
<b>Ref 2</b>				
<b>No. of Parts</b>	1			

Instructions 1	Instructions 2
ND 22/03/2025 21:00 SLA: ND 22/03/2025 21:00 PART2= PART3= PART4= ALT1= ALT2= ALT3= ALT4= TEXT= _EELENX12TAB x 1	Problem: [BDS] LENOVO X12 TABLET ** BACK DOOR SWAP ** Root Cause: UNKNOWN Action: LENOVO X12 TABLET ** BACK DOOR SWAP ** CONTACT STORE MANAGER AND EXCHANGE NEW TABLET AND CASE *ONLY* - STORE TO RETAINPSU KEYBOARD AND PEN. RECORD SERIAL AND ASSET DETAILS FOR BOTH INGOING AND OUTCOMING UNITS. BOX OLD UNIT AND RETURN VIANORMAL PROCESS Test: N/A URL: Call history:: ##### Call 5306889   Problem   Web Service   qws_uk   Fri 21 Mar 2025 13:10:34   A+C+P  agent.loginname=qws_uk equipment.assettag=EELGB000000O0096TRB2 contract.pkey=22856 call.poms=1 call.zip=CH41 2ZL call.address=Unit 28 The Pyramid Shopping Centre Grange Road call.city=Birkenhead call.customerid=INC17255500 call.problem=FOH-Lenovo x12-Smashed screen   pw-05ns38   Replacement needed call.modifiedby=QWebServices call.busimpact=Total Down (TO) category.name=GBR/EEL/workpackage/LENX12TAB call.priority=3-High call.datereported=3/21/2025 2:10:10 PM  ##### Call 5306889   Problem   Web Service   qws_uk   Fri 21 Mar 2025 13:10:34   ...

## Job Notes

## In Items

Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?
18983448101	_EELENX12TAB	TBT:EHT:X12-TABLET-GEN1				

## Returned Items

Request	Part	Description	Serial	Asset	Part Status	Customer Damage?
18983448301	_EELENX12TAB	TBT:EHT:X12-TABLET-GEN1				

Engineer Closure Notes

<b>Customer Print</b>	
<b>Customer Signature</b>	



# Run Sheet

Daniel Hanson 22/03/2025

Date	22/03/2025	Depot	Warrington	Driver	Hanson, Daniel	Jobs on Run	12
------	------------	-------	------------	--------	----------------	-------------	----

Job # 4120614	Customer	Vista Retail Support Limited	Job Address
SLA Window	21/03/2025 09:00 - 22/03/2025 17:00	Contact Name	MCDONALDS - CAPGEMINI UNIT 18-22 CLAYTON SQUARE SHOPPING CENTRE CHURCH STREET LIVERPOOL MERSEYSIDE LIVERPOOL L1 1QR
Activity	NON TECH EXCHANGE	Contact Phone	
Priority	ND 1700		
Ref 1	3228340		
Ref 2			
No. of Parts	1		

Job Notes						
In Items						
Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?
18983442801	MCD-PTR-STAR	FMCDKIT-STAFVP10				

Returned Items						
Request	Part	Description	Serial	Asset	Part Status	Customer Damage?
18983443001						

Engineer Closure Notes	On Site Time	Off Site Time
<b>Customer Print</b>		
<b>Customer Signature</b>		



# Run Sheet

David Ranson 22/03/2025

Date	22/03/2025	Depot	Warrington	Driver	Ranson, David	Jobs on Run	6
------	------------	-------	------------	--------	---------------	-------------	---

Job # 4120448	Customer	Fujitsu Services Limited - Star Trains			Job Address		
SLA Window	21/03/2025 11:09 - 22/03/2025 19:00	Contact Name	AINTREE NLC2125 MER HUB STATION		MERSEYRAIL Ormskirk Road LANCASHIRE Liverpool L9 5BE		
Activity	TECH EXCHANGE	Contact Phone	0151 955 2440				
Priority	ND 1900						
Ref 1	C5306874						
Ref 2							
No. of Parts	1						

Instructions 1	Instructions 2
ND 22/03/2025 19:00 SLA: ND 22/03/2025 19:00 PART2= PART3= PART4= ALT1=_SXNEWND4020MK2 ALT2= ALT3= ALT4= TEXT= _MYNEWND4020MK2 x 1	Problem: [TC] Newbury ND4020 Mark II Required Root Cause: Unknown Action: Engineer to replace the faulty Newbury Data printer at depot. Please record serial numbers in & out. Test: N/A Depot swap URL: Call history: ##### Call 5306874   Problem   Web Service   qws_uk   Fri 21 Mar 2025 11:09:05   A+C+P  agent.loginnname=qws_uk equipment.assettag=STRGB00000M4057TRD3 contract.pkey=23200 call.poms=1 call.zip=L9 5BE call.address=Ormskirk Road call.city=Liverpool call.customerid=INC17254699 call.problem=NLC2125 Aintree Magnetic strip failure.... NLC 2125 Site Aintree Window 30 Serial call.modifiedby=QWebServices call.busimpact=Urgent (TD) category.name=GBR/STR/workpackage/MEND4020MK2 call.priority=2-Medium call.datereported=3/21/2025 12:08:26 PM  ##### Call 5306874   Problem   Web Service   qws_uk   Fri 21 Mar 2025 11:09:05   A+C+P  NLC2125...

Job Notes

In Items

Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?
18982733101	_MYNEWND4020	MKR:ND4020 MK2:WHITE:MER:RICO	30709			

Returned Items

Request	Part	Description	Serial	Asset	Part Status	Customer Damage?
18982733301	_MYNEWND4020	MKR:ND4020 MK2:WHITE:MER:RICO	30709			

Engineer Closure Notes	On Site Time	Off Site Time
Customer Print		
Customer Signature		



# Run Sheet

David Ranson 22/03/2025

Date	22/03/2025	Depot	Warrington	Driver	Ranson, David	Jobs on Run	6
------	------------	-------	------------	--------	---------------	-------------	---

Job # 4120613	Customer	Paypoint Network Limited - UK			Job Address
SLA Window	21/03/2025 13:12 - 22/03/2025 13:00	Contact Name	MR RAJA SHAFIQ AHMED		RAJA BROTHERS RAJA BROTHERS 33-35 BUTTON LANE MANCHESTER M23 0LZ
Activity	TECH EXCHANGE	Contact Phone	01616704495		
Priority	4HR				
Ref 1	02236964				
Ref 2					
No. of Parts	0				

Instructions 1	Instructions 2
31261520//74544//T3	<p>Following issues causing delays serving customers</p> <p>As shown in the video screen adjustment is no working Key and car reader on the machine do not read the card/key some times Screen freezes requires reboot</p> <p>I hop this answers your question</p> <p>Regards</p> <p>Mo</p>

Job Notes

In Items

Returned Items

Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?

Engineer Closure Notes					On Site Time	Off Site Time
					Customer Print	
					Customer Signature	



# Run Sheet

David Ranson 22/03/2025

Date	22/03/2025	Depot	Warrington	Driver	Ranson, David	Jobs on Run	6
------	------------	-------	------------	--------	---------------	-------------	---

Job # 4120922	Customer	Paypoint Network Limited - UK		Job Address
SLA Window	21/03/2025 16:25 - 22/03/2025 13:00	Contact Name	MANAGER	RAJA GEE CONVENIENCE STORE
Activity	TECH EXCHANGE	Contact Phone	01614787255	RAJA GEE CONVENIENCE STORE
Priority	4HR			17 ROSTREVOR ROAD STOCKPORT SK3 8LQ
Ref 1	02238262			
Ref 2				
No. of Parts	0			

Instructions 1	Instructions 2
37769730//31104413//RP10	Swap reason: Hardware Damage ..... Keypad

Job Notes

#### In Items

Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?

Returned Items

Engineer Closure Notes	On Site Time	Off Site Time
Customer Print		
Customer Signature		



# Run Sheet

David Ranson 22/03/2025

Date	22/03/2025	Depot	Warrington	Driver	Ranson, David	Jobs on Run	6
------	------------	-------	------------	--------	---------------	-------------	---

Job # 4120802	Customer	Vista Retail Support Limited		Job Address
SLA Window	21/03/2025 15:08 - 22/03/2025 17:00	Contact Name		SAVERS UNIT 4A LIME SQUARE OPENSHAW MANCHESTER M11 1DA
Activity	TECH EXCHANGE	Contact Phone		
Priority	ND 1700			
Ref 1	3221237			
Ref 2				
No. of Parts	1			

Instructions 1	Instructions 2
3221237: (SN:19052522500432 ) HHT not connected to network unable to rebuild remotely. Please replace SUP-SCN-HHT-ZEB-TC51	Replace SUP-SCN-HHT-ZEB-TC51 Till No: Please record serial and Asset in and out without fail on every single call including unused parts(REF DOA). Asset tags can be found in small package attached to the box. Call your depot if there is no asset tag. Please complete the call closure field with what action was taken on site. Call closure must take place real time before you leave site. If this is not possible on your PDA call the details into your depot or call the CSC.

Job Notes

In Items

Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?
18984209601	SUP-SCN-HHT-ZEB-TC51					

Returned Items

Request	Part	Description	Serial	Asset	Part Status	Customer Damage?
18984209801						

Engineer Closure Notes	On Site Time	Off Site Time
Customer Print		
Customer Signature		



# Run Sheet

David Ranson 22/03/2025

Date	22/03/2025	Depot	Warrington	Driver	Ranson, David	Jobs on Run	6
------	------------	-------	------------	--------	---------------	-------------	---

<b>Job #</b> 4120805	<b>Customer</b>	Vista Retail Support Limited		<b>Job Address</b>
<b>SLA Window</b>	21/03/2025 09:00 - 22/03/2025 17:00	<b>Contact Name</b>	.	MCDONALDS - CAPGEMINI LUCAS STREET HUDDERSFIELD ROAD OLDHAM LANCASHIRE OLDHAM OL4 2BY
<b>Activity</b>	NON TECH EXCHANGE	<b>Contact Phone</b>	.	
<b>Priority</b>	ND 1700			
<b>Ref 1</b>	3229039			
<b>Ref 2</b>				
<b>No. of Parts</b>	1			

Instructions 1	Instructions 2
Store Access Hours: 24h	***BACK DOOR SWAP ONLY*** MCD-PTR-LAB3-KIT Till No: Please record serial and Asset in and out without fail on every single call including unused parts(RE DOA). Asset tags can be found in small package attached to the box. Call your depot if there is no asset tag. Please complete the call closure field with what action was taken on site. Call closure must take place real time before you leave site. If this is not possible on your PDA call the details into your depot or call the CSC.

**Job Notes**

In Items						
Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?
18984226201	MCD-PTR-LAB3	MCD-PTR-LAB3-KIT				

## Returned Items

Request	Part	Description	Serial	Asset	Part Status	Customer Damage?
18984226401						

Engineer Closure Notes	On Site Time	Off Site Time
<b>Customer Print</b>		
<b>Customer Signature</b>		



# Run Sheet

David Ranson 22/03/2025

<b>Date</b>	22/03/2025	<b>Depot</b>	Warrington	<b>Driver</b>	Ranson, David	<b>Jobs on Run</b>	6
-------------	------------	--------------	------------	---------------	---------------	--------------------	---

<b>Job #</b> 4120812	<b>Customer</b>	Vista Retail Support Limited		<b>Job Address</b>
<b>SLA Window</b>	21/03/2025 15:12 - 22/03/2025 17:00	<b>Contact Name</b>		LIDL CROFT HEAD LANCASHIRE OLDHAM OL2 5WD
<b>Activity</b>	TECH EXCHANGE	<b>Contact Phone</b>		
<b>Priority</b>	ND 1700			
<b>Ref 1</b>	3228803			
<b>Ref 2</b>				
<b>No. of Parts</b>	1			

Instructions 1	Instructions 2
<p>3228803- Brief Description: AutoDispo Zebra App Issue</p> <p>Full Description: AM Interface: This ticket was created by a store employee store deputy manager or store manager.</p> <p>Please select the 'Store Support Information'-Tab below for more information about the incident.</p> <p>If you are an external support provider please read the questions and answers below</p> <hr/> <p>How did you notice the error? : When going to use it this morning</p> <hr/> <p>Please write clearly the error message shown:: : Touch screen not working</p> <hr/> <p>In which menu does the error occur? : Home screen</p> <hr/> <p>Does the error occur across every Zebra device in store? : No</p> <hr/> <p>When did the error first occur? : Today</p> <hr/> <p>Have you restarted the device on which the issue occurs? ....</p>	<p>Replace HHT-ZEB-TC57-LID Till No: Please record serial and Asset in and out without fail on every single call including unused parts(RE DOA). Asset tags can be found in small package attached to the box. Call your depot if there is no asset tag. Please complete the call closure field with what action was taken on site. Call closure must take place real time before you leave site. If this is not possible on your PDA call the details into your depot or call the CSC.</p>

## Job Notes

In Items						
Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?
18984235501	HHT-ZEB-TC57-LID	BHT-ZEB-TC57-LID				

## Returned Items

Request	Part	Description	Serial	Asset	Part Status	Customer Damage?
18984235701						

Engineer Closure Notes

<b>Customer Print</b>	
<b>Customer Signature</b>	



# Run Sheet

## Warehouse manifest

Summary									
Customer Name	Trace Request	Ref 1	Job #	Activity	Address	Engineer	SLA Window	Run Date	Rec'd
Vista Retail Support Limited	18984336601	3228923	4120865	TECH EXCHANGE	SUPERDRUG STORES PLC, UNIT 3A, 2 BROUGHTON SHOPPING PARK, CHESTER ROAD, BROUGHTON, CH4 0DP	Daniel Hanson	21/03/2025 15:40 22/03/2025 17:00	22/03/2025	
Vista Retail Support Limited	18984500001	3229165	4120891	TECH EXCHANGE	SAVERS, 3 PRINCES PAVEMENT, THE GRANGE SHOPPING CENTRE, BIRKENHEAD, CH41 2XY	Daniel Hanson	21/03/2025 16:02 22/03/2025 17:00	22/03/2025	
Vista Retail Support Limited	18984503901	3229167	4120893	TECH EXCHANGE	SAVERS, 3 PRINCES PAVEMENT, THE GRANGE SHOPPING CENTRE, BIRKENHEAD, CH41 2XY	Daniel Hanson	21/03/2025 16:02 22/03/2025 17:00	22/03/2025	
Vista Retail Support Limited	18984501501	3229166	4120894	TECH EXCHANGE	SAVERS, 3 PRINCES PAVEMENT, THE GRANGE SHOPPING CENTRE, BIRKENHEAD, CH41 2XY	Daniel Hanson	21/03/2025 16:02 22/03/2025 17:00	22/03/2025	
Fujitsu Services Limited - EE	18983448101	C5306889	4120618	NON TECH EXCHANGE	ORANGE (BIRKENHEAD), Unit 28, The Pyramid Shopping Centre, Grange Road, MERSEYSIDE, Birkenhead, CH41 2ZL	Daniel Hanson	21/03/2025 13:14 22/03/2025 17:30	22/03/2025	
Fujitsu Services Limited - Star Trains	18981404501	C5306844	4120262	TECH EXCHANGE	MERSEYRAIL, Bedford Road, MERSEYSIDE, Birkenhead, CH42 2AT	Daniel Hanson	21/03/2025 05:28 22/03/2025 19:00	22/03/2025	
Vista Retail Support Limited	18983442801	3228340	4120614	NON TECH EXCHANGE	MCDONALDS - CAPGEMINI, UNIT 18-22 CLAYTON SQUARE SHOPPING CENTRE CHURCH STREET, LIVERPOOL, MERSEYSIDE, LIVERPOOL, L1 1QR	Daniel Hanson	21/03/2025 09:00 22/03/2025 17:00	22/03/2025	
Vista Retail Support Limited	18983956301	3228664	4120738	TECH EXCHANGE	SUPERDRUG STORES PLC, UNIT B-C, 36 REGENT STREET, WREXHAM, LL11 1SA	Daniel Hanson	21/03/2025 14:26 22/03/2025 17:00	22/03/2025	
Computacenter - Kingfisher	18984799601	24292021	4121048	TECH EXCHANGE	KINGFISHER INFORMATION TECHNOLOGY (, Rhyl Trade Park, Ffordd Derwen, , Rhyl Trade Park, Ffordd Derwen, , LL18 2AZ	Daniel Hanson	22/03/2025 09:00 22/03/2025 17:00	22/03/2025	
Fujitsu Services Limited - Star Trains - P2PE	18984208601	C5306726	4120803	TECH EXCHANGE	TRANSPORT FOR WALES, Conway Road, GWYNEDD, LLANDUDNO, LL31 9NB	Daniel Hanson	21/03/2025 15:08 22/03/2025 18:00	22/03/2025	
Fujitsu Services Limited - Star Trains - P2PE	18984209301	C5306726	4120803	TECH EXCHANGE	TRANSPORT FOR WALES, Conway Road, GWYNEDD, LLANDUDNO, LL31 9NB	Daniel Hanson	21/03/2025 15:08 22/03/2025 18:00	22/03/2025	
Paypoint Network Limited - UK	(No Items)	02237967	4120957	TECH EXCHANGE	CYBI NEWS, CYBI NEWS, 36 THOMAS STREET, HOLYHEAD, LL65 1RS	Daniel Hanson	21/03/2025 16:33 22/03/2025 13:00	22/03/2025	
Paypoint Network Limited - UK	18984412702	02236450	4120870	TECH EXCHANGE	SPAR STORES, SPAR STORES, STATION ROAD, VALLEY, HOLYHEAD, LL65 3EB	Daniel Hanson	21/03/2025 15:51 22/03/2025 13:00	22/03/2025	
Paypoint Network Limited - UK	18984412701	02236450	4120870	TECH EXCHANGE	SPAR STORES, SPAR STORES, STATION ROAD, VALLEY, HOLYHEAD, LL65 3EB	Daniel Hanson	21/03/2025 15:51 22/03/2025 13:00	22/03/2025	



# Run Sheet

## Warehouse manifest

Summary									
Customer Name	Trace Request	Ref 1	Job #	Activity	Address	Engineer	SLA Window	Run Date	Rec'd
Fujitsu Services Limited - Star Trains	18982733101	C5306874	4120448	TECH EXCHANGE	MERSEYRAIL, Ormskirk Road, LANCASHIRE, Liverpool, L9 5BE	David Ranson	21/03/2025 11:09 22/03/2025 19:00	22/03/2025	
Vista Retail Support Limited	18984209601	3221237	4120802	TECH EXCHANGE	SAVERS, UNIT 4A LIME SQUARE, OPENSHAW, MANCHESTER, M11 1DA	David Ranson	21/03/2025 15:08 22/03/2025 17:00	22/03/2025	
Paypoint Network Limited - UK	(No Items)	02236964	4120613	TECH EXCHANGE	RAJA BROTHERS, RAJA BROTHERS, 33-35 BUTTON LANE, MANCHESTER, M23 0LZ	David Ranson	21/03/2025 13:12 22/03/2025 13:00	22/03/2025	
Vista Retail Support Limited	18984235501	3228803	4120812	TECH EXCHANGE	LIDL, CROFT HEAD, LANCASHIRE, OLDHAM, OL2 5WD	David Ranson	21/03/2025 15:12 22/03/2025 17:00	22/03/2025	
Vista Retail Support Limited	18984226201	3229039	4120805	NON TECH EXCHANGE	MCDONALDS - CAPGEMINI, LUCAS STREET HUDDERSFIELD ROAD, OLDHAM, LANCASHIRE, OLDHAM, OL4 2BY	David Ranson	21/03/2025 09:00 22/03/2025 17:00	22/03/2025	
Paypoint Network Limited - UK	(No Items)	02238262	4120922	TECH EXCHANGE	RAJA GEE CONVENIENCE STORE, RAJA GEE CONVENIENCE STORE, 17 ROSTREVOR ROAD, STOCKPORT, SK3 8LQ	David Ranson	21/03/2025 16:25 22/03/2025 13:00	22/03/2025	



# Run Sheet

## Warehouse manifest

Summary									
Customer Name	Trace Request	Ref 1	Job #	Activity	Address	Engineer	SLA Window	Run Date	Rec'd
Paypoint Network Limited - UK	(No Items)	02237819	4120746	TECH EXCHANGE	LIVESEY SUPERSTORE, LIVESEY SUPERSTORE, 170-172 LIVESEY BRANCH ROAD, BLACKBURN, BB2 4QR	John Paul Barron	21/03/2025 14:34 22/03/2025 13:00	22/03/2025	
Vista Retail Support Limited	18983996301	3228681	4120745	TECH EXCHANGE	WHITBREAD, RIVERSWAY DRIVE, LANCASHIRE, BLACKBURN, BB3 0SN	John Paul Barron	21/03/2025 14:32 22/03/2025 17:00	22/03/2025	
Computacenter - Kingfisher	18984349501	24291911	4120953	TECH EXCHANGE	KINGFISHER INFORMATION TECHNOLOGY (, Units 4-6, Hattersley Centre, Hattersley Way., Units 4-6, Hattersley Centre, Hattersley Way., L39 2AN	John Paul Barron	22/03/2025 09:00 22/03/2025 17:00	22/03/2025	
Xerox (UK) Technical***DO NOT INVOICE***	189843190	11644190	4120861	REPAIR WITH PARTS	Everything Everywhere Limited, Westmorland Shopping Centre, Unit 12, Westmorland Shopping Centre, IP 10.19.107.50, KENDAL, LA9 4LR	John Paul Barron	22/03/2025 09:00 22/03/2025 12:00	22/03/2025	
Xerox (UK) Technical***DO NOT INVOICE***	189843183	11644190	4120861	REPAIR WITH PARTS	Everything Everywhere Limited, Westmorland Shopping Centre, Unit 12, Westmorland Shopping Centre, IP 10.19.107.50, KENDAL, LA9 4LR	John Paul Barron	22/03/2025 09:00 22/03/2025 12:00	22/03/2025	
Xerox (UK) Technical***DO NOT INVOICE***	189843187	11644190	4120861	REPAIR WITH PARTS	Everything Everywhere Limited, Westmorland Shopping Centre, Unit 12, Westmorland Shopping Centre, IP 10.19.107.50, KENDAL, LA9 4LR	John Paul Barron	22/03/2025 09:00 22/03/2025 12:00	22/03/2025	
Vista Retail Support Limited	18984562101	3229168	4120916	NON TECH EXCHANGE	MCDONALDS - CAPGEMINI, THE RIVERSIDE RETAIL PARK WHARF STREET, CUERDLEY, WARRINGTON, LANCASHIRE, WARRINGTON, WA1 2GZ	John Paul Barron	21/03/2025 09:00 22/03/2025 17:00	22/03/2025	
Vista Retail Support Limited	18983563301	3215542	4120636	TECH EXCHANGE	SUPERDRUG STORES PLC, UNIT 6, PARSONAGE RETAIL PARK, LEIGH, WN7 5SJ	John Paul Barron	21/03/2025 13:25 22/03/2025 17:00	22/03/2025	