



Run Sheet

Daniel Hanson 14/06/2025

Date	14/06/2025	Depot	Warrington	Driver	Hanson, Daniel	Jobs on Run	7
------	------------	-------	------------	--------	----------------	-------------	---

Job # 4179974	Customer	Fujitsu - Star – TFW - TC			Job Address
SLA Window	13/06/2025 09:00 - 14/06/2025 19:00	Contact Name	CHESTER NLC2412 TFW HUB STATION		TRANSPORT FOR WALES City Road CHESHIRE Chester CH1 3NS
Activity	TECH EXCHANGE	Contact Phone	02920 320193		
Priority	ND 1900				
Ref 1	C5313020				
Ref 2					
No. of Parts	1				

Instructions 1	Instructions 2
ND 14/06/2025 19:00 SLA: ND 14/06/2025 19:00 PART2= PART3= PART4= ALT1=_SXNEWND4020MK2 ALT2= ALT3= ALT4= TEXT= _KENEWND4020MK2 x 1	Problem: [TC] Newbury ND4020 Mark II Required Root Cause: Unknown Action: Engineer to replace the faulty Newbury Data printer at depot. Please record serial numbers in & out. Test: N/A Depot swap URL: Call history: ##### Call 5313020 Problem Web Service qws_uk Fri 13 Jun 2025 15:36:04 A+C+P agent.loginnname=qws_uk equipment.assettag=STRGB000000AT016TRD3 contract.pkey=23200 call.poms=1 call.zip=CH1 3NS call.address=City Road call.city=Chester call.customerid=INC17730251 call.problem=CHESTER NLC2412 TFW HUB STATION Newbury Data printer 32574 call.modifiedby=QWebServices call.busimpact=Urgent (TD) category.name=GBR/STR/workpackage/TFWND4020MK2 call.priority=2-Medium call.datereported=6/13/2025 4:35:16 PM ##### Call 5313020 Problem Web Service qws_uk Fri 13 Jun 2025 15:36:04 A+C+P CHESTER NLC2412 TFW HUB STATION Newbury Data printer 32574...

Job Notes

In Items

Returned Items

Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?
19264779001	_KENEWND4020	MR:ND4020 MK2:TFW:RICO	32010			

Engineer Closure Notes					On Site Time	Off Site Time
					Customer Print	
					Customer Signature	



Run Sheet

Daniel Hanson 14/06/2025

Date	14/06/2025	Depot	Warrington	Driver	Hanson, Daniel	Jobs on Run	7
------	------------	-------	------------	--------	----------------	-------------	---

Job # 4179660	Customer	Fujitsu Services Limited - Star Trains - P2PE		Job Address
SLA Window	13/06/2025 10:15 - 14/06/2025 19:00	Contact Name	CHESTER NLC3701 TFW Depot	TRANSPORT FOR WALES (Chester)
Activity	TECH EXCHANGE	Contact Phone	02920 320 193 / 07741 248 780	City Road, Cheshire Cheshire Chester CH1 3NS
Priority	ND 1900			
Ref 1	C5312979			
Ref 2				
No. of Parts	2			

Instructions 1	Instructions 2
ND 14/06/2025 19:00 SLA: ND 14/06/2025 19:00 PART2=_SXASSET-LABELSV2 PART3= PART4= ALT1= ALT2= ALT3= ALT4= TEXT= _TWMIUM020DEVICE x 1 _SXASSET-LABELSV2 x 1	Problem: [P2PE] Miura M020 PED faulty Root Cause: Unknown Action: Engineer MUST follow the P2PE process. Device MUST be paired before leaving site.**WHOLE PED MUST BE REPLACED**. ContactSTAR Service Desk for assistance. Test: In Use URL: Call history: ##### Call 5312979 Problem Web Service qws_uk Fri 13 Jun 2025 10:04:34 A+C+P agent.loginnname=qws_uk equipment.assettag=STRGB00000H8563TA23 contract.pkey=23200 call.poms=1 call.zip=CH1 3NS call.address=City Road Cheshire call.city=Chester call.customerid=INC17728286 call.problem=NLC3701 Chester 020 - 113951 PED - Tamper alert NLC 3701 Site Chester RSPID call.modifiedby=QWebServices call.busimpact=Urgent (TD) category.name=GBR/STR/workpackage/TWMIUM020PED call.priority=2-Medium call.datereported=6/13/2025 11:04:01 AM ##### Call 5312979 Problem Web Service qws_uk Fri 13 Jun 2025 10:04:34 A+C+P...

Job Notes

In Items

Returned Items

Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?
19263055201	_SXASSET-LABELSV2					
19263054601	_TWMIUM020DE	VR2P:M020 TFW MOBILE LIVE	02000303002020116943			

Engineer Closure Notes					On Site Time	Off Site Time
					Customer Print	
					Customer Signature	



Run Sheet

Daniel Hanson 14/06/2025

Date	14/06/2025	Depot	Warrington	Driver	Hanson, Daniel	Jobs on Run	7
-------------	------------	--------------	------------	---------------	----------------	--------------------	---

Job # 4180017	Customer	Fujitsu Services Limited - Star Trains - ME		Job Address	
SLA Window	13/06/2025 16:17 - 14/06/2025 19:00	Contact Name	CHESTER NLC3701 TFW Depot	TRANSPORT FOR WALES (Chester) City Road, Cheshire Cheshire Chester CH1 3NS	
Activity	TECH EXCHANGE	Contact Phone	02920 320 193 / 07741 248 780		
Priority	ND 1900				
Ref 1	C5313021				
Ref 2					
No. of Parts	1				

Instructions 1	Instructions 2
<p>ND 14/06/2025 19:00 SLA: ND 14/06/2025 19:00 PART2= PART3= PART4= ALT1= ALT2= ALT3= ALT4= TEXT= _KEZEBTC56DJ-1PAZU4P x 1</p>	<p>Problem: [ME] Zebra TC56 Set Number ** not working Root Cause: Unknown Action: Engineer to replace the Zebra TC56 retaining the Sim Card & ISM Card as applicable.Engineer to contact Star Support toget the HHT added to the TOC network. Once on the Network Engineer will need to Pair the peripherals.Contact Starsupport for assitan Test: Site to test URL: Call history: ##### Call 5313021 Problem Web Service qws_uk Fri 13 Jun 2025 16:16:35 A+C+P</p> <pre data-bbox="801 770 1191 1015">agent.loginname=qws_uk equipment.assettag=STRGB00000H8563TA23 contract.pkey=23200 call.poms=1 call.zip=CH1 3NS call.address=City Road Cheshire call.city=Chester call.customerid=INC17730378 call.problem=NLC3701 Chester Zebra / TC56</pre> <p>Zebra - cracked screen NLC 3701 Site Name Che call.modifiedby=QWebServices call.busimpact=Urgent (TD) category.name=GBR/STR/workpackage/TC56KE call.priority=2-Medium call.datereported=6/13/2025 5:15:51 PM...</p>

Job Notes

In Items

Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?
19264971401	_KEZEBTC56DJ-1PAZUW	AN HSPA+/LTE/CDMA:BT				

Returned Items

Request	Part	Description	Serial	Asset	Part Status	Customer Damage?
19264971601	_KEZEBTC56DJ-1PAZLW4P	AN HSPA+/LTE/CDMA:BT				

Engineer Closure Notes

		Customer Print
		Customer Signature



Run Sheet

Daniel Hanson 14/06/2025

Date	14/06/2025	Depot	Warrington	Driver	Hanson, Daniel	Jobs on Run	7
------	------------	-------	------------	--------	----------------	-------------	---

Job # 4180019	Customer	Vista Retail Support Limited	Job Address
SLA Window	13/06/2025 16:18 - 14/06/2025 17:00	Contact Name	LIDL PARC DYFFRYN FLINTSHIRE PRESTATYN LL19 9DG
Activity	TECH EXCHANGE	Contact Phone	
Priority	ND 1700		
Ref 1	3306739		
Ref 2			
No. of Parts	1		

Instructions 1	Instructions 2
June store code = 16360778 3306739 - Install 2 headsets mon - sat 8am - 10pm Sunday 10am- 4pm	Replace SPK-VOC-HDSET-S5 Till No: Please record serial and Asset in and out without fail on every single call including unused parts(RE DOA). Asset tags can be found in small package attached to the box. Call your depot if there is no asset tag. Please complete the call closure field with what action was taken on site. Call closure must take place real time before you leave site. If this is not possible on your PDA call the details into your depot or call the CSC.

Job Notes

Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?
19264974501	SPK-VOC-HDSET	SPK-VOC-HDSET-S5				



Run Sheet

Daniel Hanson 14/06/2025

Date	14/06/2025	Depot	Warrington	Driver	Hanson, Daniel	Jobs on Run	7
------	------------	-------	------------	--------	----------------	-------------	---

Job # 4180085	Customer	Centrex Services		Job Address
SLA Window	13/06/2025 17:39 - 14/06/2025 18:00	Contact Name		LIDL LIDL GLAN Y MOR ROAD LLANDUDNO JUNCTION LL31 9RU
Activity	TECH EXCHANGE	Contact Phone		
Priority	ND 1700			
Ref 1	INC11058137			
Ref 2				
No. of Parts	1			

Instructions 1	Instructions 2
Swap/install/test/collect/record serials	access code 17090778 %uE10B Phone Original Fault: we can hear calls but other person cant hear us Troubleshooting Attempted: no-screwed in Long Aerial Fitted?: short ariel Call Number: INC11058137 Store Number: LID1709 Store Name: Landudno Junction- Vale road Type Of Phone: BT Store Contact: SM Tel Number:+443330380249 Store Address: Vale Road LL31 9SJ Llandudno Junction Date Of Attendance: n/a ANY ISSUES AT ALL PLEASE CONTACT 01670 528780 THIS WOULD INCLUDE ANYTHING WHICH PREVENTS A SUCCESFUL RESOLUTION BE IT TECHNICAL ACCESS ISSUES OR QUERIES ON PROCESSES - ANY ISSUES AT ALL PLEASE CONTACT 01670 528780 PLEASE CONTACT CENTREX AFTER 30 MINUTES ON SITE

Job Notes

In Items

Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?
19265242701						

Returned Items

Engineer Closure Notes	On Site Time	Off Site Time
	Customer Print	
	Customer Signature	



Run Sheet

Daniel Hanson 14/06/2025

Date	14/06/2025	Depot	Warrington	Driver	Hanson, Daniel	Jobs on Run	7
------	------------	-------	------------	--------	----------------	-------------	---

Job # 4180104	Customer	Computacenter - Kingfisher		Job Address
SLA Window	14/06/2025 09:00 - 14/06/2025 13:00	Contact Name	Steve Rylance	KINGFISHER INFORMATION TECHNOLOGY (
Activity	TECH EXCHANGE	Contact Phone	+441492878181	Mostyn Broadway Llandudno Gwynedd
Priority	ND 1300			Mostyn Broadway Llandudno Gwynedd
Ref 1	24388945			LL30 1RT
Ref 2				
No. of Parts	1			

Instructions 1	Instructions 2
Till hostname: GBBQ01092SCO83P Till number: 83 Peripheral make/modellease copy and paste CI): ELO 15' TOUCHSCREEN Description of issue: Ctomer display is totally blank does not show any image also the coll	No Instructions

Job Notes

In Items

Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?
19265319101	4601616	KING:ELO ET1502L Prime Disp +Â				

Returned Items

Engineer Closure Notes	On Site Time	Off Site Time
Customer Print		
Customer Signature		



Run Sheet

Daniel Hanson 14/06/2025

Date 14/06/2025 **Depot** Warrington **Driver** Hanson, Daniel **Jobs on Run** 7

Job # 4179636	Customer	Fujitsu - Star – TFW - TC		Job Address
SLA Window	13/06/2025 09:46 - 14/06/2025 18:00	Contact Name	HOLYHEAD NLC7830 TFW Depot	TRANSPORT FOR WALES (Holyhead)
Activity	TECH EXCHANGE	Contact Phone	02920 320 322 / 07741 249 783	Station Approach Gwynedd Holyhead LL65 1DQ
Priority	ND 1800			
Ref 1	C5312973			
Ref 2				
No. of Parts	1			

Instructions 1	Instructions 2
ND 14/06/2025 19:00 SLA: ND 14/06/2025 19:00 PART2= PART3= PART4= ALT1= ALT2= ALT3= ALT4= TEXT= FUJFTP-638WSL110 x 1	<p>Problem: [TC] PRINTER Root Cause: Unknown Action: Swap Fujitsu thermal printer & pair with phone following Engineers documentation.- Device ID xx RSP ID xxxx TFS REFxxxxxxxxx ** NO PARTS TO BE SENT DIRECT TO SITE ** Test: in use URL: Call history::</p> <pre>##### Call 5312973 Problem Web Service qws_uk Fri 13 Jun 2025 09:45:35 A+C+P</pre> <p>agent.loginname=qws_uk equipment.assettag=STRGB000000H8565TRT3 contract.pkey=23200 call.poms=1 call.zip=LL65 1DQ call.address=Station Approach call.city=Holyhead call.customerid=INC17728107 call.problem=NLC7830 Holyhead Fujitsu Thermal Printer</p> <p>FTP printer fault NLC 7830 Site call.modifiedby=QWebServices call.busimpact=Urgent (TD) category.name=GBR/STR/workpackage/TFWFPR call.priority=2-Medium call.datereported=6/13/2025 10:45:11 AM</p> <pre>##### Call 5312973 Problem Web Service qws_uk Fri 13 Jun 2025 09:45:35 A+C+P...</pre>

Job Notes

In Items						
Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?
19262752601	FUJFTP-638WSL1PWR	1PWR:THERMAL W/CHARGER				

Returned Items

Request	Part	Description	Serial	Asset	Part Status	Customer Damage?
19262752801	FUJFTP-638WSL	IPUR: THERMAL W/CHARGER				

Engineer Closure Notes

Customer Print	
Customer Signature	



Run Sheet

John Paul Barron 14/06/2025

Date	14/06/2025	Depot	Warrington	Driver	Barron, John Paul	Jobs on Run	4
------	------------	-------	------------	--------	-------------------	-------------	---

Job # 4179655	Customer	DieboldNixdorf_WIPRO		Job Address
SLA Window	13/06/2025 10:10 - 14/06/2025 17:00	Contact Name	HELEN ASHCROFT	LIVERPOOL LIVERPOOL LIVERPOOL LIVERPOOL
Activity	TECH EXCHANGE P2PE	Contact Phone		ONE 70 SOUTH JO JL030 LIVERPOOL LIVERPOOL L1 8BJ
Priority	ND 1700			
Ref 1	131184091			
Ref 2				
No. of Parts	0			

Instructions 1	Instructions 2
Replace Ingenico L2500 PN 1900001941	Please see KB0106284- PACT Fault: Other 030 - Liverpool. Serialnumber: DeviceCountry: DeviceZIP: DeviceCity: DeviceStreet: DeviceRoom: DeviceContactPerson: DeviceCPPhone: DeviceDescription: POS DesiredDate: 202506081425 Web Logging: Locker: LP1-60-PED TPV Number (8 Digits): 15030060 Serial Number: 192497303461103310962010 Asset Number: PAN00100043 Model Ingenico 2500 Location: 030 - Liverpool Issue: Screen is blue and says Irruption Incident INC6649413 has been placed into the On Hold Awaiting Vendor state. Attempting to transfer to Diebold. DN Engineer to replace Ingenico L2500 PN 1900001941

Job Notes

In Items

Returned Items

Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?

Engineer Closure Notes					On Site Time	Off Site Time
					Customer Print	
					Customer Signature	



Run Sheet

John Paul Barron 14/06/2025

Date	14/06/2025	Depot	Warrington	Driver	Barron, John Paul	Jobs on Run	4
------	------------	-------	------------	--------	-------------------	-------------	---

Job # 4179744	Customer	Fujitsu GBL - H&M * DO NOT INVOICE*		Job Address
SLA Window	14/06/2025 09:00 - 14/06/2025 17:00	Contact Name	GB0333 HANDM	H&M SHIFTSTORE H&M H&M SHIFTSTORE H&M UNIT 16-17, 20 PEEL AVENUE, THE TRAFFORD CENTRE MANCHESTER M17 8BB
Activity	TECH EXCHANGE	Contact Phone	01616021070	
Priority	ND 1900			
Ref 1	C002565371			
Ref 2				
No. of Parts	1			

Instructions 1	Instructions 2
ACCESS GRANTED TRAF729047 *CLICK HERE*	Call Problem: Device: SCO 76 Replace: SSD (TP7000) Miro/part name: 38059276 *** CALL H&M SD WHILE ONSITE FOR ASSISTANCE / TO CONFIRM ALL OK - 0207 660 2572 *** If you are unable to get through to H&M or the TVS desk please ensure your closure contains the required details

Job Notes

In Items

Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?
19263677401	38047988	128HDHP SSD S3 128GB 2.5				

Returned Items

Engineer Closure Notes	On Site Time	Off Site Time
Customer Print		
Customer Signature		



Run Sheet

John Paul Barron 14/06/2025

Date	14/06/2025	Depot	Warrington	Driver	Barron, John Paul	Jobs on Run	4
------	------------	-------	------------	--------	-------------------	-------------	---

Job # 4179941	Customer	Paypoint Network Limited - UK		Job Address
SLA Window	13/06/2025 14:57 - 14/06/2025 13:00	Contact Name	MANAGER	SUREMART LTD SUREMART LTD 7A GREAT CHEETHAM STREET WEST Salford M7 2JB
Activity	TECH EXCHANGE	Contact Phone		
Priority	4HR			
Ref 1	02375543			
Ref 2				
No. of Parts	0			

Instructions 1	Instructions 2
37592348//31267800//PP MINI	Swap reason: Contactless Payment Fault

Job Notes

In Items

Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?

Returned Items

Engineer Closure Notes	On Site Time	Off Site Time
Customer Print		
Customer Signature		



Run Sheet

John Paul Barron 14/06/2025

Date	14/06/2025	Depot	Warrington	Driver	Barron, John Paul	Jobs on Run	4
------	------------	-------	------------	--------	-------------------	-------------	---

Job # 4179597	Customer	Fujitsu Services Limited - Star Trains - P2PE			Job Address
SLA Window	13/06/2025 09:09 - 14/06/2025 19:00	Contact Name	MANCHESTER VICTORIA NLC9654 NT Dep		Northern Rail MT (Manchester) Station Approach, Todd Street, Manchester Lancashire Manchester M3 1WY
Activity	TECH EXCHANGE	Contact Phone	0161 822 2094		
Priority	ND 1900				
Ref 1	C5312962				
Ref 2					
No. of Parts	2				

Instructions 1	Instructions 2
ND 14/06/2025 19:00 SLA: ND 14/06/2025 19:00 PART2=_SXASSET-LABELSV2 PART3= PART4= ALT1= ALT2= ALT3= ALT4= TEXT= _NRMIUM020DEVICE x 1 _SXASSET-LABELSV2 x 1	Problem: [P2PE] Miura M020 PED faulty Root Cause: Unknown Action: Engineer MUST follow the P2PE process. Device MUST be paired before leaving site.**WHOLE PED MUST BE REPLACED**. Contact STAR Service Desk for assistance. Test: In Use URL: Call history: ##### Call 5312962 Problem Web Service qws_uk Fri 13 Jun 2025 07:11:35 A+C+P agent.loginnname=qws_uk equipment.assettag=STRGB00000H8497TA23 contract.pkey=23200 call.poms=1 call.zip=M3 1WY call.address=Station Approach Todd Street Manchester call.customerid=INC17727300 call.problem=NLC9654 Manchester Victoria 020-042874 PED - Tamper alert NLC 9654 Site Manc call.modifiedby=QWebServices call.busimpact=Urgent (TD) category.name=GBR/STR/workpackage/NRMIUM020PED call.priority=2-Medium call.datereported=6/13/2025 8:10:54 AM ##### Call 5312962 Problem Web Service qws_uk Fri 13 Jun 2025 07:11:36 A+C+P...

Job Notes

In Items

Returned Items

Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?
19262553301	_NRMIUM020DE	M2P:M020 NORTHERN MOBILE LIVE	02000303002020	116914		
19262553701	_SXASSET-LABEL	SXASSET-LABELSV2				

Engineer Closure Notes					On Site Time	Off Site Time
					Customer Print	
					Customer Signature	



Run Sheet

David Ranson 14/06/2025

Date	14/06/2025	Depot	Warrington	Driver	Ranson, David	Jobs on Run	2
------	------------	-------	------------	--------	---------------	-------------	---

Job # 4180036	Customer	Computacenter Limited		Job Address
SLA Window	14/06/2025 09:00 - 14/06/2025 13:00	Contact Name	Richard Mullin	LLOYDS BANKING GROUP PLC (008102783
Activity	TECH EXCHANGE	Contact Phone	+447801549414	16 Market Place, 16 Market Place, OL1 1JG
Priority	ND 1300			
Ref 1	24388081			
Ref 2				
No. of Parts	1			

Instructions 1	Instructions 2
Device - PED Make - Moby Device - PED PPD - No Part - 4444195 Ingenicoobi 8500 Bluetooth PED Serial Number / Asset -	No Instructions

Job Notes

In Items

Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?
19263977101	4444195	Moby 8500 Bluetooth Ped				

Returned Items

Request	Part	Description	Serial	Asset	Part Status	Customer Damage?
19263977301	4444195	Moby 8500 Bluetooth Ped				

Engineer Closure Notes	On Site Time	Off Site Time
Customer Print		
Customer Signature		



Run Sheet

David Ranson 14/06/2025

Date	14/06/2025	Depot	Warrington	Driver	Ranson, David	Jobs on Run	2
------	------------	-------	------------	--------	---------------	-------------	---

Job # 4179667	Customer	Paypoint Network Limited - UK		Job Address
SLA Window	14/06/2025 08:00 - 14/06/2025 12:00	Contact Name	MANAGER	KIRKHOLT KIRKHOLT 21-24 THE STRAND ROCHDALE OL11 2JG
Activity	TECH EXCHANGE	Contact Phone	/	
Priority	Priority MC			
Ref 1	02373663			
Ref 2				
No. of Parts	0			

Instructions 1	Instructions 2
34039528//31130193//T3	<p>Case Number: 02373663</p> <p>Swap type: Swap Required</p> <p>Swap reason: Physical Damage</p> <p>Device Type: PP1</p> <p>TID Number: 34039528</p> <p>Serial Number:</p> <p>Site ID: 31130193</p> <p>Description: Case 02370540</p>

Job Notes

In Items						
Request	Part	Description	Serial	Asset	Part Consumed/Delivered	Transit Damage?

Returned Items						
Request	Part	Description	Serial	Asset	Part Status	Customer Damage?

Engineer Closure Notes					On Site Time	Off Site Time
					Customer Print	
					Customer Signature	



Run Sheet

Warehouse manifest

Summary									
Customer Name	Trace Request	Ref 1	Job #	Activity	Address	Engineer	SLA Window	Run Date	Rec'd
Fujitsu - Star – TFW - TC	19264779001	C5313020	4179974	TECH EXCHANGE	TRANSPORT FOR WALES, City Road, CHESHIRE, Chester, CH1 3NS	Daniel Hanson	13/06/2025 09:00 14/06/2025 19:00	14/06/2025	
Fujitsu Services Limited - Star Trains - P2PE	19263055201	C5312979	4179660	TECH EXCHANGE	TRANSPORT FOR WALES (Chester), City Road, Cheshire, Cheshire, Chester, CH1 3NS	Daniel Hanson	13/06/2025 10:15 14/06/2025 19:00	14/06/2025	
Fujitsu Services Limited - Star Trains - P2PE	19263054601	C5312979	4179660	TECH EXCHANGE	TRANSPORT FOR WALES (Chester), City Road, Cheshire, Cheshire, Chester, CH1 3NS	Daniel Hanson	13/06/2025 10:15 14/06/2025 19:00	14/06/2025	
Fujitsu Services Limited - Star Trains - ME	19264971401	C5313021	4180017	TECH EXCHANGE	TRANSPORT FOR WALES (Chester), City Road, Cheshire, Cheshire, Chester, CH1 3NS	Daniel Hanson	13/06/2025 16:17 14/06/2025 19:00	14/06/2025	
Vista Retail Support Limited	19264974501	3306739	4180019	TECH EXCHANGE	LIDL, PARC DYFFRYN, FLINTSHIRE, PRESTATYN, LL19 9DG	Daniel Hanson	13/06/2025 16:18 14/06/2025 17:00	14/06/2025	
Computacenter - Kingfisher	19265319101	24388945	4180104	TECH EXCHANGE	KINGFISHER INFORMATION TECHNOLOGY (, Mostyn Broadway Llandudno Gwynedd , Mostyn Broadway Llandudno Gwynedd , LL30 1RT	Daniel Hanson	14/06/2025 09:00 14/06/2025 13:00	14/06/2025	
Centrex Services	19265242701	INC11058137	4180085	TECH EXCHANGE	LIDL, LIDL, GLAN Y MOR ROAD, LLANDUDNO JUNCTION, LL31 9RU	Daniel Hanson	13/06/2025 17:39 14/06/2025 18:00	14/06/2025	
Fujitsu - Star – TFW - TC	19262752601	C5312973	4179636	TECH EXCHANGE	TRANSPORT FOR WALES (Holyhead), Station Approach, Gwynedd, Holyhead, LL65 1DQ	Daniel Hanson	13/06/2025 09:46 14/06/2025 18:00	14/06/2025	



Run Sheet

Warehouse manifest

Summary									
Customer Name	Trace Request	Ref 1	Job #	Activity	Address	Engineer	SLA Window	Run Date	Rec'd
Computacenter Limited	19263977101	24388081	4180036	TECH EXCHANGE	LLOYDS BANKING GROUP PLC (008102783, 16 Market Place, , 16 Market Place, , OL1 1JG	David Ranson	14/06/2025 09:00 14/06/2025 13:00	14/06/2025	
Paypoint Network Limited - UK	(No Items)	02373663	4179667	TECH EXCHANGE	KIRKHOLT, KIRKHOLT, 21- 24 THE STRAND, ROCHDALE, OL11 2JG	David Ranson	14/06/2025 08:00 14/06/2025 12:00	14/06/2025	



Run Sheet

Warehouse manifest

Summary									
Customer Name	Trace Request	Ref 1	Job #	Activity	Address	Engineer	SLA Window	Run Date	Rec'd
DieboldNixdorf_WIPRO	(No Items)	131184091	4179655	TECH EXCHANGE P2PE	LIVERPOOL LIVERPOOL, LIVERPOOL LIVERPOOL, ONE 70 SOUTH JO, JL030 LIVERPOOL, LIVERPOOL, L1 8BJ	John Paul Barron	13/06/2025 10:10 14/06/2025 17:00	14/06/2025	
Fujitsu GBL - H&M * DO NOT INVOICE*	19263677401	C002565371	4179744	TECH EXCHANGE	H&M SHIFTSTORE H&M, H&M SHIFTSTORE H&M, UNIT 16-17, 20 PEEL AVENUE,, THE TRAFFORD CENTRE, MANCHESTER, M17 8BB	John Paul Barron	14/06/2025 09:00 14/06/2025 17:00	14/06/2025	
Fujitsu Services Limited - Star Trains - P2PE	19262553301	C5312962	4179597	TECH EXCHANGE	Northern Rail MT (Manchester), Station Approach, Todd Street, Manchester, Lancashire, Manchester, M3 1WY	John Paul Barron	13/06/2025 09:09 14/06/2025 19:00	14/06/2025	
Fujitsu Services Limited - Star Trains - P2PE	19262553701	C5312962	4179597	TECH EXCHANGE	Northern Rail MT (Manchester), Station Approach, Todd Street, Manchester, Lancashire, Manchester, M3 1WY	John Paul Barron	13/06/2025 09:09 14/06/2025 19:00	14/06/2025	
Paypoint Network Limited - UK	(No Items)	02375543	4179941	TECH EXCHANGE	SUREMART LTD, SUREMART LTD, 7A GREAT CHEETHAM STREET WEST, SALFORD, M7 2JB	John Paul Barron	13/06/2025 14:57 14/06/2025 13:00	14/06/2025	