The Findings from Real System

NS306 Productions Company has provided you with data files containing the processing times recorded for parts A100, A200, and A300 at Work Cell 4. The data indicates that their previous assumption of a constant processing time does not hold true for the Work Cell 4 which is an automated station. Consequently, you are expected to analyze the provided data to determine the processing time distribution for Work Cell 4.

As a result of the new examinations, the outputs of the actual system have also changed as follows.

Performance Criteria	Value (Minutes)	ε
Total Time for A100	75.67	7.567
Waiting Time for A100	67.39	6.739
Total Time for A200	75.77	7.577
Waiting Time for A200	68.29	6.829
Total Time for A300	75.96	7.596
Waiting Time for A300	67.94	6.794

Please determine the appropriate processing times for the parts at Work Cell 4 and take into account the outputs of the new system.