

## B Safety and Traffic Management

The Company provided all workers with reflecting jackets.

In addition, company has put in place enough warning sign posts to alert the road users on the ongoing works especially close to places where bush clearing and heavy grading activities are taking place.

### 5.6 Conclusion

The company mobilised and continue to mobilise enough equipment and personnel to handle the work appropriately and work progress is expected to improve with the improvement of weather conditions.

### Progress photos

#### Heavy grading ing progress





Completed sections





Common excavation to spoil and widen road width



Compiled by: **Barohooza Julius**

**Managing Director**

