

**FILE:** AE-0218055**DATE:** April 16, 2018**PAGE:** 1 of 1

## INSPECTION CERTIFICATION

<b>CLIENT</b>	Pembina Pipelines (Grande Prairie)		
<b>LOCATION</b>	8-13-63-5 W6M		
<b>ATTENTION</b>	Tim Stewart		
<b>INSPECTION OF</b>	<b>OVERHEAD CRANE (Inlet Compressor #3)</b>		
	Make: <b>UCANU</b>	Model: <b>2 Ton</b>	Serial: <b>491076</b>

An annual structural inspection was performed on the above noted equipment. Visual and magnetic particle inspections was performed by David Lario, MSc., P.Eng., FEC, CGSB MPI II, CWB II on April 16, 2018 of the following items:

- |                        |                        |                         |
|------------------------|------------------------|-------------------------|
| 1. Columns (4)         | 6. End Trucks (2)      | 8. Chain Hoist (CM,     |
| 2. Support Girders (1) | 7. Trolley (CM, Model: | Model: 622, Serial: TF- |
| 3. Bridge (1)          | 633, Serial: UE-S,     | B, 2 Ton)               |
| 4. Bridge Stops (2)    | Capacity: 2 Ton)       | 9. Hook (1)             |
| 5. Bridge Drive (1)    |                        |                         |

Based upon our inspection findings the above inspected equipment is certified safe for service when operated in accordance with the original equipment manufacturers specifications.

**Certification Date:** April 16, 2018  
**Next Inspection Date:** April 16, 2019

<b>ENGINEER</b>	David Lario, MSc., P.Eng., FEC
<b>CWB NO.:10349</b>	Visual II
<b>CGSB NO.: 12520</b>	Magnetic Particle II



April 16, 2018

M65014

APEGA PERMIT: P12933