Ln. Er. A. Venkatachalam M.E., M.I.E., F.I.V

Chartered Civil Engineer

Regd. Valuer for Income Tax, Wealth Tax (04/05-06)

District Panel Engineer Class - IA

E-mail: arrulassociatesppm@gmail.com



ARRUL ASSOCIATES

81/1D, Chairman Building, Sankari Main Road, Ottamethai, Pallipalayam - 638 006.

Cell: 98427 - 57507

98427 - 22200

Panel Valuer for * State Bank of India * Canara Bank * Corporation Bank * IOB * IDBI * Indian Bank

* Repco Bank * Pallavan Grama Bank * TMB * Dhanalaxmi Bank * South Indian Bank

VALUATION OF PROPERTY (LAND & BUILDING)

REPORT ON VALUATION

Ref.No. 10

Date: 12.11.2020

PART A - BASIC DATA

GENERAL: I.

.]	Purpose of valuation	:	Bank Security Purpose. Canara Bank, Park Road, Erode.
ľ	a. Date of Inspectionb. Date on which the valuation is made		10.11.2020
3.	Name of the reported owner with present address and phone number Name of the owner(s) and his/their addresses(es) with Phone No.(details of share of each owner in case of joint ownership)		Mr. A. THANGAVEL, S/o. Mr. Arumuga Gounder. Door No: 1.199, 1.199/1, Poolakkattur, Sankagiri Main Road, Pallipalayam Village & Post, Kumarapalayam Taluk, Namakkal District. Cell No: 98652 65000 "M/s. THANGAVEL FABRICS PRIVATE
	Name of the Company Documents produced for		LIMITED"
4.	perusal: i) Document		Refer to Xerox copy of Sale Deed Document No: 3736, Date: 15.12.2010
	ii) Legal Opinion iii) Previous Report		: My Pervious Valuation Report Date: 14.02.2018

		7		-
5.	Brief description of the property taken for valuation (Including leasehold/freehold etc)		Industrial (Free Hold)	
6.	Scope of valuation	:	Bank Credit Purpose	
7.	If this report is to be used for any bank purpose, state the name of the bank and branch, if known	:	Bank Purpose in CANARA Bank, Park Road, Erode Branch.	
1				

II. DESCRIPTION OF THE PROPERTY:

	th Din		Ir. A. THANGAVEL,
	Postal address of the property with Pin	٠ [5/o. Mr. Arumuga Gounder
1	code	1	,
	·		S.F.No: 279, 280,
			Plot No: 17, 18,
1			V.V. Nagar,
1			Poolakkattur,
			Pallipalayam Agraharam Village,
	·		Kumarapalayam Taluk,
			Namakkal District.
			Pin Code - 638 008
	Cit /T	:	Pallipalayam
2.	City/Town	:	Yes
	Residential Area	:	
	Commercial Area	1:	Yes
	Industrial Area	 -	High/Middle/Poor
3.	Classification of the Area		Urban/Semi Urban/Rural
	1 Constinuit	1:	Panchayat Limit
4.	Coming under Corporation Limit	1.	Tallettay at 222-2
	/Village Panchayat/Municipality	 	
5.		1	
	State/Central Govt. enactments		
	(e.g. Urban Land Ceiling Act) or notified		
	under agency	1	
	area/scheduled area/cantonment		
	area	+	
6.		:	
	conversion to house site plots		
	is contemplated		

Plot No. / Nagar/Survey No. Door No. / Plot No S.F. No. / T.S. No. / R.S. No. Village / Block Taluk / Ward Mandal/District/Municipality/ Corporation	 V.V. Nagar, Poolakkattur, Plot No: 17, 18, S.F.No: 279, 280, Pallipalayam Agraharam Village, Kumarapalayam Taluk, Namakkal District. Panchayat Limit. As per Document (Plot No: 17)
Boundary Details North	Piot No: 16
South	Plot No: 18
	Thangavel Vagaiyara Property
East	30'0" Width North South Road
West	10,665.00 Sq.ft
Extent of land	As per Document (Plot No: 18)
Boundary Details	Plot No: 17 & 30'0" Width South North Road
North	PWD Vaikkal
South	Thangavel Vagaiyara Property
East	
Wesi	Plot No: 19
Extent of land	8,021.00 Sq.ft
	As per Actual (Plot No: 17)
Boundary Details	Thangavel Fabrics (p) Ltd
North	Thangavel Fabrics (P) Ltd
South	
East	Thangavel Fabrics (P) Ltd
West	30'0" Width North South Road
	10,665.00 Sq.ft
Extent of land	As per Actual (Plot No: 18)
Boundary Details	
North	Thangavel Fabrics
South	PWD Vaikkal
East	Thangavel Vagaiyara Property Cha
West	Plot No: 19
Extent of land	8,021.00 Sq.ft
9. Latitude, Longitude	and : 11.383769

0. Property tax receipt ref	erred	T	ax Receipt Not Available
Assessment number Tax amount Receipt in the	name of connection	:	E.B. Connection Available
11. Electricity service consumer number	Connection		
In the name of Other details, if any 12. Property is presently	·	:	Owner / Tenants/ Both / Vacant
13. If tenanted fully,What is the gross mon14. If occupied by both	nthly rent?	:	Owner Occupied
By assuming the enti	able monthly rent?		Rs Rs

III. PROCEDURE OF VALUATION:

1 F.S.I.	tion Details : 2 RCC Roof ity Room –	Discussed in Part B,C,D,E &F Plot Coverage Ground Floor – 0.005

(Describe the property details)

PART B - LAND

1. Dimension of the site	As per document (1a) Plot No: 17	As per Document 1(b) Plot No: 18
North		109'0" 110'0"
South	84'0"	72'6"
East	130'0'	126
	The state of the s	EREDEN

Page 4

		1	130′0″	74'0"
1 1	West			8,021.00 Sq.ft
	Extent		10,665.00 Sq.ft	
			Total Extent of Document = 10,665.00 + 8,021.00 = 1	8.686.00 Sq.ft
		+	= 10,665.00 + 8,021.00 2 8,686.00 Sq.ft	
2.	Extent of Document (least of 1a & 1b)	- 1		8,021.00 Sq.ft
	Size of the Plot	-	10,665.00 Sq.ft	109'0" & 110'0"
	North & South	:	80'0" & 84'0"	
	East & West	:	130'0" & 130'0"	72'6" & 74'0"
			10,665.00 Sq.ft	8,021.00 Sq.ft
	Total Extent of the Plot			
3.	Characteristics of the site * What is the character of the locality?		Industrial & Residential	Area
	*What is the classification of the locality?	:	Middle Class	
	Development of surrounding areas	:	Industrial & Residenti	al Area
	Possibility of frequent flooding/sub merging Feasibility to The Civic amenities like school, hospital, bus stop, market etc.		Near by	
	Level of land with topographical conditions Shape of land		Rectangular	
	Type of use to which it can be put		Industrial & Resident	ial Area
	Any usage restriction Is plot in town planning approved layout?	:	Nil	
	Corner Plot or Intermittent Plot?		: Intermittent Plot	
	Type of road available at present		: Available in Tar Roa	d
	* Road facilities are available?		: Sankagiri Main Road	ATACHAI STEED VAL
	Is it a land – locked land? Water Potentiality		:	A 04105-06 X
	* What is the width of the Road?		: 30'0" Width Road	ARTER

1	Width of road – is it below 20ft or more than 20 ft. Underground sewerage system	1	Above than 30'0" Not Available
	Is power supply available at the site?	:	Available
	Advantage of the site 1. 2. Special remarks, if any, like threat of acquisition of land for public service	:	1. Opposite Sangamithra Gas Agency 2. Sankagiri Main Road
	purposes, road widening of applicability of CRZ provisions etc (Distance from sea-coast/tidal level must be incorporated)		
	*Any factors which affect the marketability of the land?	•	
	* Type of the land? Accessibility	:	
-	Value on adopting GLR (Guideline Rate) i) Guideline rate as obtained from the Registrar's office (a		Rs. 100.00/ Sq.ft
	evidence thereof to be enclosed) ii) Value of land by adopting GLR(18,686.00 Sq.ft X Rs. 100.00/Sq.ft)		Rs. 18,68,600/- : Say Rs. 18.69 Lakhs
	5. Value by adopting PMR (Prevailing Market Rate) Prevailing market))	: Rs. 1,750.00/Sq.ft
	rate(Along with details/reference of atleast two latest		: : Rs. 3,27,00,500/-
	deals/transactions with respect adjacent properties in the areas) Unit rate adopted in this valuation after considering the characteristics.	on	Say Rs. 327.01 Lakhs
	of the subject plot Value of land by adopting PMR (18,686.00 Sq.ft X Rs. 1,750.00/- Sq		04/05-06

PART C - BUILDINGS

			Residential/Commercial/Industrial
<u></u>	Type of Building		Load bearing /RCC/Steel Framed/ framed
1	Type of construction	:	Load bearing / RCC/Steel Flamour
1.	Type of construction	- 1	-lus churo
<u> </u>	Quality of construction	:	Superior / I Class / II Class / III Class
2.	Quality of Construction		Common / Attractive / Aesthetic
3.	Appearance of Building		Exterior: New one / Excellent/Good
4.	Maintenance/Condition of	:	/Normal Average/ Poor
1	the Building		Victorial Victorial
			Interior: Excellent, Cool.
1			Average/ Poor
-	Di di Aroo	1:	GF RCC Roof Security Room - 95.06 Sq.ft
5.	Plinth Area	 .	Ground Floor Only
6	Number of floors and	.	Building Height: 10'0"
	height of each floor		Dunding Freedows
	including basement, if any	<u>_</u>	

Floor	Teal of Communication	Roof		Plinth Area	
	(as reported/ as per actual observation/ as per deed)		Main Portion A	Cantilevered Portion B	Total A+50% of B 95.06
G.F	GF Security Room	RCC Roof	95.06		95.00
F.F.					
S.F.					05.06 Ca.ft
	TOTAL		95.06 Sq.ft		95.06 Sq.ft

- 1. Drawing approval Approval Plan Not Available
 - a. Date of issue and validity of layout of approved map/plan
 - b. Approved map/plan issuing authority
 - c. Whether genuineness or authentic of approved map/plan is verified?
 - d. Any other comments by our empanelled valuers on authentic of approved plan?
 - d. (Discuss on the building approval, reference, violations observed, consequences of violation etc.)
 - 8. Value of building is estimated by adopting suitable unit plinth area rate depending upon the specifications. Depreciation is calculated KTACH straight-line method assuming a salvage value of 16.50% (RCC Report).

1. VALUATION OF BUILDING:

DESCRIPTION	Ground Floor	First Floor	Second Floor	Other floor, if any
Specification				
loor finish	Cement			
Superstructure				
Roof	RCC Roof			
Doors	Steel			
Windows	Steel			
Weathering course	Cement			
Plinth area	95.06 Sq.ft			
Year of construction	RCC Roof - 2009,			
. 1/				
(as reported/ observed/ as per				
deed)				
Age of the building	RCC Roof - 60 Yrs,			
	RCC Roof - 11 Yrs			1
If the age is not	RCC ROOI 11 115			
exactly known, further				
Total life of the	RCC Roof - 49 Yrs		·	
building				
estimated				
Depreciation	11 Years x 1.50%			
	= 16.50% (RCC			·
percentage	Roof)			
(assuming salvage	1001)			
value				
Replacement rate o	f GF RCC Roof			
construction with	n Security Room - Rs.	.		
the sexisting	800/- Sq.ft			
conditions and	D 1			
specifications				
Replacement Value	GF RCC Roof			
•	Security Room - Rs	•		
	76,048.00			
				NACA
Depreciation Val	ue GF RCC Roof			STATE OF THE PARTY
the rate of 16.50 %	Security Room - R	S.		12/3 100 06 15 N
(RCC),	12,547.00			A 105-06
Present value o	f GF RCC Roof			REU
building	Security Room - R	s.		
vananie	pecurity moone at	1	ı	1 '

		63,500.00		
Total value floors if any)	of	Rs. 63,500/-	 	
floors if any)				

(Note: Add extra sheets for additional floors and buildings)

SI N o	of items	Plinth Area	Roo f Hei g ht	Age of the buil di ng	Estimate d replacem e nt rate of constructi on Rs . Rs. 800/-	Replacem ent Cost Rs.	Depreciati on Rs.	Net value after deprec iations Rs.
	First Floor							
	Second floor,						D 40 545/	Rs. 63,500/-
	Total					Rs.76,048/-	Rs.12,547/-	Rs. 63,500/-

PART D - AMENITIES & EXTRA ITEMS

(Value after Depreciation) Portico Rs. ---1. Rs. ---Ornamental Front / Pooja 2. door Sitout/Verandah with Steel Rs. ---3. grills Extra Steel/collapsible Rs. ---4. gates Rs. ---Open staircase 5. Wardrobes, showcases, Rs. ---6. wooden cupboards 7. Glazed tiles Rs. ---Extra sinks and bath tub 8. Rs. ---Rs. ---9. Marble/ceramic tiles flooring Rs. ---Interior decorations 10. Rs. ---**Architectural Elevation** 11. works Rs. ---False ceiling works 12. 04/05-06 Paneling works Rs. ---13. <u>14.</u> Aluminum works Rs. ---

Rs. ---

15.

Aluminum handrails

16. Separate Lumber Room	:	Rs
17. Separate Toiler Room	:	Rs
18. Separate water tank/sump		Rs
19. Trees, gardening		Rs
20. Any other	:	Rs
20. This outer		

1.		:	lue after Depreciation) Rs
1,	Open Well		
	: Bore Well		
	: Hand pump		
	: Motor		
	Panchayat Tap		
	Underground level sump		
	Overhead water tank		
2.	Drainage arrangements Septic Tank	:	Rs
	Underground sewerage		
3.	Compound WallRm. @ Rs / m2. Height: 8'0" Length: Building Alround Type of construction: Brick Work	•	Rs. 2,30,000.00
4.	Pavements Rm. @ Rs/m2	:	Rs
5	Steel gate Rm. @ Rs/m2	:	Rs
6.	E.B Deposits, water deposits, drainage deposits etc.	:	Rs
7.	Electrical fittings & others	:	Rs
	Type of wiring	<u> :</u>	Rs
	Class of fittings (superior/Ordinary/Poor)	:	Rs. —
	Number of light Points	<u> </u> :	Rs
	Fan Points	<u> :</u>	Rs
	Spare Plug Points	:	Rs
	Any other item	1:	Rs

	T:	Rs
	1:	Rs
	1	Rs
taps etc	 :	Rs
tures	+:-	Rs
	+:-	Rs
	·	Rs. 2,30,000.00
	closets and their easins bs taps etc tures	pasins : bs : taps etc : tures :

PART F - ABSTRACT VALUE

Part	Description	Value of adopting					
В	Land	(GLR Rs		PMR	Rs.	
C	<u> </u>	Rs.	18,69,000.	00 Rs.		10.	
D	Building Amenities	Rs.	64,000.		64,000.00		
E	Services	Rs.		Rs.			
		Rs.	2,30,000.0	00 Rs.	2,30,000.00		
	Total Say	Rs.	21,63,000.0	00 Rs.	3,29,95,000.00		
Fa		Rs.	21,63,000.0	00 Rs.	3,29,95,000.00		
1. 2. A	actors favouring for an additional		+)	Rs.			
1. 2.	ctors favouring for less value	•	,				
Le		(-))	Rs.			
TI	esent Market Value			Rs.	3,29,95,000.00	(F)	

ANY OTHER DETAILS:

(Valuation: Here the approved valuer should discuss in detail his approach to valuation of property and indicate how the value has been arrived at, supported by necessary calculations. Also, such aspects as i) Salability ii) Likely rental valuers in future in iii) Any likely income it may generate, may be discussed).

As a result of my appraisal and analysis, it is my considered opinion that the present fair market value of the above property in the prevailing condition with aforesaid specifications is Rs. 3,29,95,000.00 (Rupees Three Crore Twenty Nine Lakhs and Ninety Five Thousands Only). The book value of the above property as of is Rs. 21,63,000.00 (Rupees Twenty One Lakhs Sixty Three Thousands only) and the distress value Rs. 2,63,96,000/-(Rupees Two Crore Sixty Three Lakhs and Ninety Six Thousands only).

Place: Pallipalayam Date: 12.11.2020

Signature

(Name and Official seal of the Approved Valuer) Er. A.VENKATACHALAM, M.E.M.I.E. Eligento CHARTERED ENGINEER, REGISTERED VALUER.04/05-06,

HARIERED ENGINEER, REGISTERED VALUER.04/03 DISTRICT PANEL ENGINEER CLASS 1A APPROVED VALUER FOR BANKS,

ARRUL ASSOCIATES
81/1D. CHAIRMAN BUILDING SANKARI MAIN ROAD,
OTTAMETTHAI. PALLIPALAYAM - 638006.
CELL:98427 57507, 98427 22200

PART G - CERTIFICATE

- 1. It is hereby certified that in my opinion
 - The present market value of the property discussed in the report (above) by adopting prevailing market rate for land is Rs. 3,29,95,000.00 (Rupees Three Crore Twenty Nine Lakhs and Ninety Five Thousand Only) The forced sale value of the property is estimated as 20% less than the present market value.
- 2. Number of title deed(s) involved in this property is ---The relevant document for the subject property in the opinion of this valuer is the deed dated ...-.. with Registration Number -- registered in the ...- Registrar's Office ---
- 3. If this property is offered as collateral security, the concerned financial institution is requested to verify the extent of land shown in this valuation report with respect to the
- This report is not to be referred if the purpose is different other than 4. mentioned in I(1).
- 5. The property was inspected on10.11.2020.. by in the presence of Mr. Thangavel
- 6. The legal aspects were not considered in this valuation.
- 7. This valuation work was/ has been undertaken by the valuer based upon the request from Applicant.

Place

: Pallipalayam

Date

: 12.11.2020

(Panel Valuer) Er. A.VENKATACHALAM, M.E.M.I.E.,F.I.v.,,

CHARTERED ENGINEER REGISTERED VALUER.04/05-06, DISTRICT PANEL ENGINEER CLASS 1A

Note

Enclosures:

: This report contains 17 Pages

APPROVED VALUER FOR BANKS,
ARRUL ASSOCIATES
81/1D. CHAIRMAN BUILDING SANKARI MAIN ROAD, OTTAMETTHA! PALLIPALAYAM 638006. CELL:98427 57507, 98427:22200

- Key plan showing the location of the property
- Site plan with boundaries
- Photograph of owner/representative with property in background



Zone:

SALEM

Guideline Village:

PALLIPALAYAM AGARAHARAM

Revenue District:

NAMAKKAL

Sub Registrar Office:

PALLIPALAYAM

Revenue Village:


PALLIPALAYAM AGRAHARAM

Revenue Taluka:


KUMARAPALAYAM

Sr. No.	Survey/Subdivision No.	Guideline Value (₹) (British Value)	Guideline Value (₹) (Metric Value)	Land Classification	Effective Start Date
l	<u>279</u>	100/ Square Feet	1085/ Square Metre	Residential Class II Type - I	09-Jun- 2017
2	280	100/ Square Feet	1085/ Square Metre	Residential Class II Type - I	09-Jun- 2017






Google Maps 11°23'01.6"N 77°45'24.4"E



https://www.google.com/maps/place/11°23'01,6"N+77°45'24.4"E/@11.3841056,77.7574616,16z/data=!4m5!3m4!1s0x0:0x0!8m2!3d11.383769!4d77.756775





Imagery ©2020 CNES / Airbus, Maxar Technologies, Map data ©2020 200 m

https://www.google.com/maps/place/11°23'01,6"N+77°45'24,4"E/@11.3841056,77.7574616,1537m/data=i3m1!1e3!4m5i3m4!1s0x0:0x0l8m2i3d11.383769!4d77.756775

