SYNTHETIC: quality and environmental scenarios

Invented for training. Not real events.

Non-conformance scenario

On Tuesday the site team found that the pipe bedding delivered on Monday was 40 mm single-size stone. The specification calls for 10 mm single-size stone. 30 metres of pipe had already been laid and covered. The supplier's delivery docket says "granular bedding material" with no size. The foreman stopped work, photographed the delivery and informed the project manager. The client's clerk of works was told the same afternoon. The next delivery is due Thursday.

Environmental near miss

After heavy rain on Wednesday the water leaving the site drain looked cloudy. A silt fence beside the stream had slumped over 4 metres. The environmental lead took photos and a water sample, repaired the fence the same day and informed the client. No fish kill or complaint was reported.

Audit preparation

Procedures to be audited next month: control of nonconforming product, environmental incident reporting, subcontractor evaluation. Two findings from last year's audit: a calibration certificate for a laser level was out of date, and two toolbox talk records had no signatures.