


Hazard: 01_0014 frame 154

label = ANOMALY | proximity = 21.75 | 1 vehicle(s), 5 pedestrian(s)



Normal: 01_0014 frame 0

label = normal | proximity = 0.00 | 0 vehicle(s), 2 pedestrian(s)



 pedestrian skeleton (COCO-17)

 vehicle oriented box + corners

 vehicle centre + heading