

**Arizona Market**

ROC079383, ROC089248, ROC114027,
ROC82785, ROC82784
16767 N Perimeter Drive
Scottsdale, AZ 85260
Telephone: (800) 664-3094
Fax: (480) 598-2610

CRM: Daniel Morel
Phone #: (623) 764-6314
Fax #:
Email: Daniel.Morel@PulteGroup.com

Service Request # DD185127

Request Date 08/21/2014

LOT INFORMATION

Community	FS @ Norterra 3700s - Skyline - 5225	Lot Address	1808 W. Straight Arrow Lane	Close Date	05/03/2013
Lot/Block	13216		Phoenix, AZ 85085	Plan / #	3724-1- Ridge / 37241
Building #				Phase #	1384020013

CONTACT INFORMATION

Name	Dominic Tusio	Primary Phone	(623) 271-5020 (Mobile)	Other Phone	
Email	pulte@electricdominic.com (Home)				

SERVICE REQUEST INFORMATION

Source	Phone / Call In	Type	Standard	Status	In Progress
Notes					

LINE ITEM INFORMATION

L/I #	Parent #	W/O #	Issue	Status	Inspection Appt	Service Appt
1	NA	001	Plumbing >> Misc. >> Evaluate : Bathroom - Master :	In Progress		08/28/2014 8:00 am - 10:00 am
Additional Description: -Please evaluate and repair leak coming from 2nd level m/bathroom evidenced by water stained lid in family room below: NOTE: WATER STAINED LID WAS DRY AT TIME OF INSPECTION PER MOISTURE METER. APPEARS NOT TO BE AN ACTIVE LEAK. POSSIBLE CAUSES TUB DRAIN OR TOILET WAX RING.						
Assigned To: BREWER ENTERPRISES INC						Initials:
2	NA	003	Paint >> Misc. >> Touchup :	In Progress		08/28/2014 10:00 am - 12:00 pm
Additional Description: -Please kilz & paint 20" water stained lid @ family room due to leak from 2nd level m/bath. (Production paint)						
Assigned To: EXCEL HOME SERVICES INC						Initials:
3	NA	002	Electrical - Primary >> Wiring >> Installed Improperly :	In Progress		08/28/2014 8:00 am - 12:00 pm
Additional Description: -Please inspect and repair as needed 2 Gang switch @ 2nd level m/bath lav. Exhaust fan powers up with both light and exhaust fan switches. Should be independent of each other.						
Assigned To: AUSTIN ELECTRIC, INC						Initials:

Yes No

☐ ☐ Was your warranty request resolved in a timely manner?☐ ☐ Was your home left clean after the warranty work was complete

The items have been completed to my satisfaction.

Homeowner

Date

Pulte Representative

Date