STATE OF CALIFORNIA • DEPARTMENT OF TRANSPORTATION

STORMWATER SITE INSPECTION REPORT

CEM-2030 (REV 12/2019)

PROJECT INFORMATION NAME AND SITE ADDRESS	CONTRACT NUMBER/CO/RTE/PM
The project site is located at 3612 Webster St, Oakland, CA 94611. Project location is adjacent to MacArthur 580 Freeway The proposed work consists, in general, of construction of a new two-story 12,193 square-foot recreation center building and park improvements, located in Mosswood Park.	N/A
	PROJECT IDENTIFIER NUMBER N/A
	WDID NUMBER N/A
CONTRACTOR NAME AND ADDRESS JUV INC. Contact: Dzhemali Uchaneyshvili 7901 Oakport street, suite 2700, Oakland, CA 94621	PROJECT SITE RISK LEVEL ☐ Risk Level 1 ☐ N/A. WPCP ☒ Risk Level 2 ☐ N/A. Project resides in The Lake Tahoe Hydrologic Unit and is regulated under Order No. R6T-2016-0010, NPDES No. CAG616002 ☐ Risk Level 3
SUBMITTED BY CONTRACTOR (PRINT AND SIGN NAME) Dzhemali Uchaneyshvili	DATE 02/25/2025
WATER POLLUTION CONTROL MANAGER NAME AND COMPANY NAME Saeedreza Hafezneza - Socal Stormwater Runoff Solution Services, Inc.	PHONE NUMBER (310) 343-8313
	EMERGENCY (24/7) PHONE NUMBER (310) 343-8313

GENERAL INFORMATION

INSPECTOR'S NAME	Accompanied by Caltrans staff?	DATE OF INSPECTION
A. Mark Waldman, P.E., QSD/QSP	☐ Yes ☒ No If Yes, Name/Initials _____	02/25/2025

Weather Condition	Precipitation Condition		Wind Condition
☒ Clear	☒ None	☐ Heavy rain	☐ None
☐ Partly cloudy	☐ Misty	☐ Hail	☐ Less than 5 mph
☐ Cloudy	☐ Light rain	☐ Snow	☒ Greater than 5 mph
	☐ Rain		

Construction Phase	Site Information
☐ Highway construction	Total project area 2 acres
☐ Plant establishment	Total project disturbed soil area 2 acres
☐ Suspension of work (inactive site)	Current phase disturbed soil area 2 acres
	Current phase inactive disturbed soil N/A acres

Inspection Type *Check appropriate box(es)*	**Storm Information**	
☒ Weekly ☐ Annual Certification of Compliance ☐ Quarterly non-stormwater	Time elapsed since last storm _____ days	Precipitation amount from last storm _____ inches
☐ Pre-storm	Time storm is expected _____ (time) _____ (date)	Expected precipitation amount _____ inches
☐ During storm event	Time elapsed since storm began _____ hours-minutes	Precipitation amount from storm recorded from site rain gauge _____ inches
☐ Post storm	Time elapsed since storm _____ hours-minutes	Precipitation amount from storm recorded from site rain gauge _____ inches

Date	Daily Site Inspection of Best Management Practices (BMP) List Daily inspections for previous calendar week. Do not include weekly inspection.	Daily inspection performed by	Any corrective actions identified as completed or new?		If yes, were the actions added or verified on CEM-2035, as appropriate?		Date shown on corrective action form
			YES	NO	YES	NO	
02/25/2025	Check for BMP's in staging area, dirt pile coverings,	M Waldman	☐	☒	☐	☐	
	fiber rolls, geotextiles and mats, gravel bags, tracking		☐	☐	☐	☐	
	controls, damage to existing vegetation, inlet protection,		☐	☐	☐	☐	
	waste management, erosion and wind controls, stockpile		☐	☐	☐	☐	
	management and other environmental risks		☐	☐	☐	☐	

ADA Notice For individuals with sensory disabilities, this document is available in alternate formats. For alternate format information, contact the Forms Management Unit at (916) 445-1233, TTY 711, or write to Records and Forms Management, 1120 N Street, MS-89, Sacramento, CA 95814.