20 May 2025, 11:00 (Europe/Berlin)

syniotec

Handover Report

Handover ID

RC15484BTT

Contract ID RC15484BTT

Type Hand Out

Rental Company

GmbH Große Mode

28195 Bremen, Germany

Customer

GmbH Große Mode

28195 Bremen, Germany

Construction Site

Bremen Roadworks

Overview

	Product	Name	Booking Dates	Quantity
#1	Crawler excavator	Volvo F504	01.01.2028 14:42 – 02.02.2029 16:48	1
	ID 564564	Category Crawler excavator	Subtitle Volvo excavator over 50 t	Serial Number 564564
#2	Small inventory	Fence	01.01.2028 14:42 – 02.02.2029 16:48	100
#3	Big inventory	Long fence	01.01.2028 14:42 – 02.02.2029 16:48	100

Fences

Total	Delivered
100	98

Long fences

Total	Delivered
100	98

#1 Equipment
Volvo F504

Operating Hours
45 h

#4 Equipment
Volvo F504

Operating Hours
45 h

Rental information

Warehouse
Halensee Warehouse

Rental ID
RC15484BTT

Company/customer
Reisebüro GmbH

Place of use
Bremen Roadworks

Tank level
65%



Attachments

Attachment 1
Scratches on front mirror





Attachment 2 Technical check in PDF

Document 14.02.2020

Document 14.02.2020

General information

UVV
26.01.2021

Working hour
8:00 AM

Cleaning in order?
Yes

Question group

Group

General	Complete	Condition/function OK?
1.1 General operating licence / registration certificate	Yes	No
Additional information * The damage always indicates the failure or impairment of a machine or technical system. Machine damage can take many forms and often has a significant impact on efficiency.		
1.2 Operating instructions	Not relevant	
1.3 Hazard assessment	No	
1.4 Last test certificate	Yes	Yes
1.5 Type plate / CE marking	Not relevant	
1.6 Declaration of conformity	No	
1.7 Warning signs / information plates	Not relevant	
1.8 Last test certificate	No	
1.9 Type plate / CE marking	Not relevant	
1.10 Last test certificate	No	
1.11 Type plate / CE marking	Not relevant	
1.12 Last test certificate	Yes	Yes
Additional information * The damage always indicates the failure or impairment of a machine or technical system. Machine damage can take many forms and often has a significant impact on efficiency. 		
1.13 Type plate / CE marking	Not relevant	

Lights

Headlights
Yes Condition Okay

Cabin lights
No




Photos

Front view



Left side 45 degrees



Back view



Right side 45 degrees



Cabin



Bucket



Other image



360 views

360° view exterior
Exterior video.mp4

360° view interior
Interior video.mp4

Rating

Rate the equipment
3/5 ★ The quick brown fox jumps over the lazy dog

Rental Company

Max Mustermann

GmbH Große Mode

Transport Provider

John Doe

GmbH Holidayquelle

Customer

Max Mustermann

GmbH Reisefokus

max.mustermann@reisefokus.de

20 May 2025, 11:00 (Europe/Berlin)

Handover Report RC15484BTT

syniotec
A brand of Sharemac GmbH

Address: Am Wall 146
City: Bremen
Postcode: 28195
Country: Germany

T +49 421 83679700
M info@syniotec.com
www.syniotec.com

VAT ID: DE316314130
Register no.: HRB 33169

Bank: Deutsche Bank
BIC/SWIFT: DEUTDEFFXXX
IBAN: DE34 5001 0517 3163 9812 79

Management: Manuel Kimanov

Terms and conditions
"Terms and Conditions" is the document governing the contractual relationship between the provider of a service and its user. On the web, this document is often also called "Terms of Service" (ToS), "Terms of Use", EULA ("End-User License Agreement"), "General Conditions" or "Legal Notes".