20 May 2025, 11:00 (Europe/Berlin)

syniotec

# Handover Report

## Handover ID

## RC15484BTT

## Contract ID RC15484BTT

## Type Hand In

| Rental Company | Customer |
| --- | --- |
| Max Mustermann | Max Mustermann |
| GmbH Große Mode | GmbH Reisefokus |

### Overview

| | Product | Name | Booking Dates | Quantity |
| --- | --- | --- | --- | --- |
| #1 | Crawler excavator | Volvo F504 | 01.01.2028 14:42 – 02.02.2029 16:48 | 1 |

Something was changed in details
**Not comparable**

# Rental information

**Warehouse**
Halensee Warehouse

**Rental ID**
RC15484BTT

**Company/customer**
Reisebüro GmbH

**Place of use**
Bremen Roadworks

**Tank level**
65%



# Attachments

**Attachment 1**
Scratches on front mirror





**Attachment 2** Technical check in PDF

Document 14.02.2020 >

Document 14.02.2020 >

# General information

**UVV**
26.01.2021

**Working hour**
8:00 AM

**Cleaning in order?**
Yes

# Question group

## Group

| General | Complete | Condition/function OK? |
|---|---|---|
| 1.1 General operating licence / registration certificate | ✓ | No |
| Additional information * The damage always indicates the failure or impairment of a machine or technical system. Machine damage can take many forms and often has a significant impact on efficiency. | | |
| 1.2 Operating instructions | Not relevant | |
| 1.3 Hazard assessment | ✗ | |
| 1.4 Last test certificate | ✓ | Yes |
| 1.5 Type plate / CE marking | Not relevant | |
| 1.6 Declaration of conformity | ✗ | |
| 1.7 Warning signs / information plates | Not relevant | |
| 1.8 Last test certificate | ✗ | |
| 1.9 Type plate / CE marking | Not relevant | |
| 1.10 Last test certificate | ✗ | |
| 1.11 Type plate / CE marking | Not relevant | |
| 1.12 Last test certificate | ✓ | Yes |
| Additional information * The damage always indicates the failure or impairment of a machine or technical system. Machine damage can take many forms and often has a significant impact on efficiency. | | |
|  | | |
| 1.13 Type plate / CE marking | Not relevant | |

# Lights

**Headlights**
Yes Condition Okay

Cabin lights

No





## Photos

Front view



Left side 45 degrees



Back view



Right side 45 degrees



Cabin



Bucket



Other image



# 360 views

360° view exterior
**Exterior video.mp4**

360° view interior
**Interior video.mp4**

# Rating

Rate the equipment
**3/5** ★ The quick brown fox jumps over the lazy dog

Rental Company

Max Mustermann

GmbH Große Mode

Customer

**Max Mustermann**

GmbH Reisefokus

max.mustermann@reisefokus.de

20 May 2025, 11:00 (Europe/Berlin)

Handover Report RC15484BTT


**syniotec**
A brand of Sharemac GmbH

Address: Am Wall 146
City: Bremen
Postcode: 28195
Country: Germany

T +49 421 83679700
M info@syniotec.com
www.syniotec.com

VAT ID: DE316314130
Register no.: HRB 33169

Bank: Deutsche Bank
BIC/SWIFT: DEUTDEFFXXX
IBAN: DE34 5001 0517 3163 9812 79

Management: Manuel Kimanov



Terms and conditions
“Terms and Conditions” is the document governing the contractual relationship between the provider of a service and its user. On the web, this document is often also called “Terms of Service” (ToS), “Terms of Use”, EULA (“End-User License Agreement”), “General Conditions” or “Legal Notes”.